Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 530921

QUESTIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	530921
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2527631418
Incident Name	NAPP2527631418 SL DEEP FEDERAL 003 @ FAPP2203951721
Incident Type	Oil Release
Incident Status	Initial C-141 Approved
Incident Facility	[fAPP2203951721] SL DEEP FEDERAL #3 BATTERY

Location of Release Source		
Site Name	SL Deep Federal 003	
Date Release Discovered	09/09/2025	
Surface Owner	Federal	

Liner Inspection Event Information		
Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	1,250	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	12/05/2025	
Time liner inspection will commence	09:30 AM	
Please provide any information necessary for observers to liner inspection	Monty Wilson (505) 340-1905	
Please provide any information necessary for navigation to liner inspection site	32.63574, -103.80924	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 530921

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	530921
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
jacquih	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	12/1/2025