

Golden Graham 1 Fed Com CTB nAPP2600633201

Release Volume Documentation

Material Released- Produced Water

Source- Production Tank

Volume Released- 70 bbls

Volume Recovered- 70 bbls

TRI STAR SERVICES, LLC
PO BOX 1019 • CARLSBAD, NM 88221
OFFICE: (505) 838-8000 CELL: (505) 988-0021 FAX: (505) 261-7545

Ticket: **129767**

Date: **1-9-26**

Company: **Golden Graham 1 FC CTB**

Location: **Golden Graham 1 FC CTB**

Deliver to: **Golden Graham 1 FC CTB**

Material Hauled: **Fluids**

Top Gauge: _____ Bottom Gauge: _____ Truck: **63**

START TIME: **10:30 AM** END TIME: **2:30 PM** TOTAL HOURS: **4:00**

START TIME: _____ END TIME: _____ TOTAL HOURS: _____

☐ Fresh Water/Brine Ticket # _____ Barrels _____

☐ Produced Water Ticket # _____ Barrels **70**

☐ Backhoe ☐ Excavator ☐ Forklift ☐ Manlift ☐ Operator

☐ Welders ☐ Helper ☐ Stainless Welding

☐ QC/QA ☐ Supervisor ☐ Foreman

☐ Hot Shot ☐ Roustabout ☐ Hydro Test

☐ Pressure Washer ☐ Sandblast/Painting ☐ Other

☐ Trash Trailer Combo ☐ Pick-up Truck ☐ Mobile Field Office

Description Of Work: **Leave to location worked on location - Clean Containment Fluids 70 bbls To - Fluid**

Work Performed By: **Carly Hennessey**

Helper: _____

Company: **Mari**

MT DRIVER TRUCK TICKET BOOKS

NICHOLS PRINTING, INC. • 575-885-2313

Total Area Calculations						Standing Liquid Calculations					
Total Surface Area	width	length	wet soil			Standing Liquid Area	width	length	liquid depth	oil (%)	
Rectangle Area #1	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #1	58 ft X	108 ft X	1 in	0%	
Rectangle Area #2	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #2	0 ft X	0 ft X	0 in	0%	
Rectangle Area #3	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #3	0 ft X	0 ft X	0 in	0%	
Rectangle Area #4	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #4	0 ft X	0 ft X	0 in	0%	
Rectangle Area #5	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #5	0 ft X	0 ft X	0 in	0%	
Rectangle Area #6	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #6	0 ft X	0 ft X	0 in	0%	
Rectangle Area #7	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #7	0 ft X	0 ft X	0 in	0%	
Rectangle Area #8	0 ft X	0 ft X	0.00 in	0%		Rectangle Area #8	0 ft X	0 ft X	0 in	0%	

ERROR - Standing Liquid Area larger than Total Area, Review Data Input

Production Data NOT Required

Average Daily Production: Oil _____ Water _____

0 BBL 0 BBL

Did leak occur before the separator?: ☐ YES ☐ N/A (place an "X")

Amount of Free Liquid Recovered: 0 BBL okay

Percentage of Oil in Free Liquid Recovered: 0% (percentage)

Liquid holding factor *: 0.00 gal per gal

Use the following when the spill wets the grains of the soil.

Use the following when the liquid completely fills the pore space of the soil.

* sand = .08 gallon liquid per gallon volume of soil.

Occurs when the spill soaked soil is contained by barriers, natural (or not).

* gravelly (caliche) loam = .14 gallon liquid per gallon volume of soil.

* gravelly (caliche) loam = .25 gallon liquid per gallon volume of soil.

* sandy clay loam soil = .14 gallon liquid per gallon volume of soil.

* sandy loam = .5 gallon liquid per gallon volume of soil.

* clay loam = .16 gallon liquid per gallon volume of soil.

Saturated Soil Volume Calculations:				Free Liquid Volume Calculations:			
Total Solid/Liquid Volume:	sq. ft.	H2O cu. ft.	OIL cu. ft.	Total Free Liquid Volume:	6,264 sq. ft.	H2O 391.500 cu. ft.	OIL .000 cu. ft.
Estimated Volumes Spilled				Estimated Production Volumes Lost			
Liquid in Soil:		H2O 0.0 BBL	OIL 0.0 BBL	Estimated Production Spilled:		H2O 0.000000 BBL	OIL 0.000000 BBL
Free Liquid:		69.7 BBL	0.0 BBL				
Totals:		69.724 BBL	0.000 BBL				
				Estimated Surface Damage			
				Surface Area:	6,264 sq. ft.		

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 542922

QUESTIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 542922
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2600633201
Incident Name	NAPP2600633201 GOLDEN GRAHAM 1 FED COM CTB @ FAPP2600632710
Incident Type	Produced Water Release
Incident Status	Initial C-141 Received
Incident Facility	[fAPP2600632710] GOLDEN GRAHAM 1 FED COM CTB

Location of Release Source	
<i>Please answer all the questions in this group.</i>	
Site Name	GOLDEN GRAHAM 1 FED COM CTB
Date Release Discovered	01/05/2026
Surface Owner	State

Incident Details	
<i>Please answer all the questions in this group.</i>	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release	
<i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i>	
Crude Oil Released (bbls) Details	Not answered.
Produced Water Released (bbls) Details	Cause: Corrosion Production Tank Produced Water Released: 70 BBL Recovered: 70 BBL Lost: 0 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	Yes
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	A hole formed in the bottom of the tank releasing produced water into the lined secondary containment.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 542922

QUESTIONS (continued)

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 542922
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.

The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Not answered.

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Chase Settle Title: Safety & Environmental Rep II Email: chase_settle@eogresources.com Date: 01/14/2026
--	--

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 3

Action 542922

QUESTIONS (continued)

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 542922
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Site Characterization	
<i>Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.
What method was used to determine the depth to ground water	Not answered.
Did this release impact groundwater or surface water	Not answered.
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:	
A continuously flowing watercourse or any other significant watercourse	Not answered.
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.
An occupied permanent residence, school, hospital, institution, or church	Not answered.
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.
Any other fresh water well or spring	Not answered.
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.
A wetland	Not answered.
A subsurface mine	Not answered.
An (non-karst) unstable area	Not answered.
Categorize the risk of this well / site being in a karst geology	Not answered.
A 100-year floodplain	Not answered.
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.

Remediation Plan	
<i>Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.</i>	
Requesting a remediation plan approval with this submission	No
<i>The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.</i>	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 542922

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 542922
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
nvez	None	1/14/2026