

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 601984

QUESTIONS

Operator: Paragon Environmental LLC 1601 N. Turner St. Hobbs, NM 88240	OGRID: 331082
	Action Number: 601984
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2617336782
Incident Name	NAPP2617336782 ALASKA 29 FEE TB @ N-29-18S-26E
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved

Location of Release Source	
Site Name	ALASKA 29 FEE TB
Date Release Discovered	06/19/2026
Surface Owner	Private

Liner Inspection Event Information	
Please answer all the questions in this group.	
What is the liner inspection surface area in square feet	1,700
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/09/2026
Time liner inspection will commence	01:00 PM
Please provide any information necessary for observers to liner inspection	Manuel Villareal 432-209-3850
Please provide any information necessary for navigation to liner inspection site	32.71448,-104.40509

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 601984

CONDITIONS

Operator: Paragon Environmental LLC 1601 N. Turner St. Hobbs, NM 88240	OGRID: 331082
	Action Number: 601984
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
cjones1	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/6/2026