

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report☒ Final Report

Name <i>Exxon Company, U.S.A.</i>	Contact <i>Roland M. Moreau</i>
Address <i>P.O. Box 4358, Houston, TX 77210</i>	Telephone No. <i>(713) 431-1219</i>
Facility Name <i>East Hrama Ridge</i>	Facility Type <i>Tank Battery</i>
Surface Owner <i>San Simon Ranch</i>	Mineral Owner <i>Exxon</i>
Lease No. <i>San Simon 32 B State (Com)</i>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>31</i>	<i>21 S</i>	<i>35 E</i>					<i>San</i>

NATURE OF RELEASE

Type of Release <i>Condensate and Saltwater</i>	Volume of Release <i>66 bbls Condensate 117 bbls Saltwater</i>	Volume Recovered <i>0 bbls Condensate 0 bbls Saltwater</i>
Source of Release <i>Drain Valve</i>	Date and Hour of Occurrence <i>12/28/98</i>	Date and Hour of Discovery <i>12/28/98 9 AM</i>
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? <i>Sylvia Dickey</i>	
By Whom? <i>Jimmy Mc Bee</i>	Date and Hour <i>12/28/98 4:30 PM</i>	
Was Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully (Attach Additional Sheets if Necessary)

None

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)

Drain valve on a 210 bbl. stock tank froze and cracked due to water on the bottom of the tank.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets if Necessary)

The spill affected an area approximately 484 square feet on the tank battery location. The broken valve was replaced. Spill site will be bioremediated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should these operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Roland M. Moreau*

OIL CONSERVATION DIVISION

Released to Imaging: 8/20/2026 4:14:32 PM

Printed Name: *ROLAND M. MOREAU*

Approved by

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 616460

CONDITIONS

Operator: EXXON COMPANY USA Attn: Vicki Hustede Houston, TX 772522305	OGRID: 65333
	Action Number: 616460
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
scwells	Copying NOR into associated incident file.	8/20/2026