

Monthly Meter Analysis
July 2026



Meter #: 83609-01
Name: ROSA UNIT 88 B

Sample
Date: 01/27/2026
Type: Spot
Pressure: 43.0 H2O:
Temperature: 52.0 H2S:

Component	Mole %	Liquid Content	Mass %
Carbon Dioxide (CO2)	1.6805		4.3379
Nitrogen (N2)	0.4716		0.7749
Methane (C1)	95.4781		89.8411
Ethane (C2)	1.4939	0.4003	2.6347
Propane (C3)	0.7816	0.2157	2.0215
Isobutane (IC4)	0.0311	0.0102	0.1060
n-Butane (NC4)	0.0221	0.0070	0.0753
Isopentane (IC5)	0.0080	0.0029	0.0339
n-Pentane (NC5)	0.0050	0.0018	0.0212
Neopentane (neo)			
Hexanes Plus (C6+)	0.0281	0.0123	0.1535
Argon (Ar)			
Carbon Monoxide (CO)			
Hydrogen (H2)			
Oxygen (O2)			
Helium (He)			
Water (H2O)			
Hydrogen Sulfide (H2S)			
Totals	100.0000	0.6502	100.0000

Property	Total Sample
Pressure Base	14.730
Temperature Base	60.00
Relative Density	0.5897
HV, Dry @ Base P,T	1018.64
HV, Sat @ Base P, T	1000.87
HV, Sat @ Sample P, T	
Cricondentherm	-47.833
HCDP @ Sample Pressure	
Full Wellstream	
Free Water	
Condensate	
26 # RVP Gasoline	0.027
Testcar Permian	0.137
Testcar Panhandle	0.361
Testcar Midcon	0.281

ROSA UNIT 88B — C-129 Emission Volume Calculation

LOGOS Operating, LLC | Flyover-Rate Duration Method | Malfunctioned Dump Valve

Event Details

Well: Rosa Unit 88B
API / OGRID: 3004531061
Emission ID / Obs ID: 26658 / 147185
Lat/Lon (detection): 36.91374, -107.48681
Area: 4
Detection source note: Zeitview plume tagged to plugged Rosa Unit 273A; source is Rosa Unit
Event Type: Malfunctioned dump valve (non-routine)
Elective flyover detection: 8/16/2026 9:59-10:15 AM MT
Prior OGI / AVO: OGI 4/2026 (no leaks) / AVO 8/10/2026
Start of Event: 8/15/2026 4:46 AM MT (malfunction start)
End of Event: 8/17/2026 12:42 PM MT (repaired)
Methodology: Flyover-detected rate applied to event duration
Reporting: NMOCD Form C-129

Flyover rate (MCF/d): 218 *Zeitview best estimate, ID 26658 (range 131-305, +/-40.*

Volume Calculation (Rate x Hours / 24)

Date	Hours on Leak	Rate (MCF/d)	Vented Volume (MCF)
8/15/2026	19.23	218	174.7
8/16/2026	24.00	218	218.0
8/17/2026	12.70	218	115.4
Total	55.93		508.1

Notes

Vented volume = flyover-detected rate (218 MCF/d) x hours leaking / 24, by calendar day.

Event runs from the malfunction (8/15/2026 4:46 AM) to repair (8/17/2026 12:42 PM) = 55.93 hours.

Rate per Zeitview LeakSurveyor, Emission ID 26658 (range 131-305 MCF/d, +/-40%, Sherwin et al. 2021). malfunctioned dump valve on Rosa Unit 88B (same pad).

Prior elective flyover and 4/2026 OGI found no leaks; most recent AVO 8/10/2026.

Reportable on NMOCD Form C-129 (non-routine event).

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 618874

DEFINITIONS

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 618874
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 618874

QUESTIONS

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 618874
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	[30-045-31061] ROSA UNIT #088B
Incident Facility	Unavailable.

Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Dump Valve
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	95
Nitrogen (N2) percentage, if greater than one percent	0
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	2
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 618874

QUESTIONS (continued)

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 618874
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	08/15/2026
Time vent or flare was discovered or commenced	04:46 AM
Time vent or flare was terminated	12:00 PM
Cumulative hours during this event	19

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Cause: Normal Operations Dump Valve Natural Gas Vented Released: 218 Mcf Recovered: 0 Mcf Lost: 218 Mcf.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	Equipment malfunction LOGOS continually conducting AVOS
Steps taken to limit the duration and magnitude of vent or flare	Fixed Malfunction
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Continually conduct AVO's and elective flyovers

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 618874

ACKNOWLEDGMENTS

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 618874
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 618874

CONDITIONS

Operator: LOGOS OPERATING, LLC 2010 Afton Place Farmington, NM 87401	OGRID: 289408
	Action Number: 618874
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
vanessaf	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/28/2026