Received by OCL	D: 4/20/2021 6:52	2:29 AM										Page 1 of 4
used for reporting packer leakage tests				Dil Conservation Division New Mexico Packer-Leakage Test						Revised Ju	Page 1 ine 10, 2003	
Operator Hilco	orp Energy Com	pany		Lea	ase Nam	e SAN JU	IAN 2	8-5 U	INIT		Well No.	38A
Location of We	ell: Unit Letter	0	Sec	32	Тwp	028N	R	ge	005W	API	# 30-039-222	233
	Name of F	Reservoir o	or Pool			/pe Prod			Method of Prod		Prod Mediun	ı
Upper Completion	PC			G	as			Flov	v		Tubing	
Lower Completion	MV			G	as			Artif	icial Lift		Tubing	

Pre-Flow Shut-In Pressure Data Stabilized?(Yes or No) Hour, Date, Shut-In SI Press. PSIG Upper Length of Time Shut-In Completion 4/12/2021 327.1 Yes 181 Hour, Date, Shut-In Stabilized?(Yes or No) Lower SI Press. PSIG Completion 4/12/2021 137.3 Yes

Flow Test No. 1								
Commenced at: 4/1	9/2021	Zone Producing (Upper or Lower): UPPER						
Time	Lapsed Time	PRESSURE		Prod Zone				
(date/time)	Since*	Upper zone	Lower zone	Temperature	Remarks			
4/19/2021 12:30 PM	0	327.1	137.3					
4/19/2021 12:40 PM	0	100.7	137.3		PC down to 100.7 within 4 mins, MV did not communicate.			
4/19/2021 1:16 PM	1	86	137.3		After 30 minute pressure.			

Production rate during test

Oil:	BPOD Based on:	Bbls. In	Hrs.	Grav.	GOR	
Gas	MCFPD; Tes	t thru (Orifice or Mete	er)			

MCFPD; Test thru (Orifice or Meter)

Mid-Test Shut-In Pressure Data

Upper Completion	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. PSIG	Stabilized?(Yes or No)
Lower Completion	Hour, Date, Shut-In		SI Press. PSIG	Stabilized?(Yes or No)

(Continue on reverse side)

Northwest New Mexico Packer-Leakage Test

•

		Flo	w Test No. 2		
Commenced at:			Zone Pro	oducing (Upper	r or Lower)
Time	Lapsed Time	PRES	SURE	Prod Zone	
(date/time)	Since*	Upper zone	Lower zone	Temperature	Remarks
					<u> </u>
Production rate during	test				
Oil:BPOD	Based on:	Bbls. In	Hrs.	(GravGOR
Gas	MCFPD; Test th	nru (Orifice or Me	eter)		
I hereby certify that the Approved:		ontained is true	Operat	or: Hilcorp E	Energy Company
New Mexico Oil Co	nservation Division			-	•
Ву:			Title:	Multi-Skilled	Operator
Title:			Date:	Tuesday, Ap	ril 20, 2021
	NORT	HWEST NEWMEXICO	PACKER LEAKAGE	TEST INSTRUCTIO	NS
 A packer leakage test shall be comm completion of the well, and annually there Such tests shall also be commenced on all chemical or fracture treatment, and whene the tubing have been disturbed. Tests sha requested by the Division. 	eafter as prescribed by the order author I multiple completions within seven day ever remedial work has been done on a	izing the multiple completion. s following recompletion and well during which the packer	for Flow Te: /or remain shut- or 7. Pressur	st No. 2 is to be the same a in while the zone which wa es for gas-zone tests must	ed even though no leak was indicated during Flow Test No. 1. Procedure as for Flow Test No. 1 except that the previously produced zone shall as previously shut-in is produced. be measured on each zone with a deadweight pressure gauge at time ediately prior to the beginning of each flow period, at fifteen-minute
2. At least 72 hours prior to the commu Division in writing of the exact time the to			immediately flow period, to the conch which have p	prior to the conclusion of at least one time during ea ision of each flow period. previously shown question	and at hourly intervals thereafter, including one pressure measurement each flow period. 7-day tests: immediately prior to the beginning of each hch flow period (at approximately the midway point) and immediately prio Other pressures may be taken as desired, or may be requested on wells able test data. es, throughout the entire test, shall be continuously measured and recorde
 The packer leakage test shall comme stabilization. Both zones shall remain shu however, that they need not remain shut-in 			once at the e completion,	end of each test, with a dea	suracy of which must be checked at least twice, once at the beginning and dweight pressure gauge. If a well is a gas-oil or an oil-gas dual be required on the oil zone only, with deadweight pressures as required
 For Flow Test No. 1, one zone of th while the other zone remains shut-in. Suc 24 hours in the case of an oil well. Note: atmosphere due to lack of a pipeline conn 	ch test shall be continued for seven day if, on an initial packer leakage test, a g	s in the case of a gas well and gas well is being flowed to the	 The res Tests shall b New Mexico 	e filed with the Aztec Distr Packer Leakage Test For	d tests shall be filed in triplicate within 15 days after completion of the test rict Office of the New Mexico Oil Conservation Division on Northwest m Revised 10-01-78 with all deadweight pressures indicated thereon as cones only) and gravity and GOR (oil zones only).
5. Following completion of Flow Test above.	No. 1, the well shall again be shut-in, i	n accordance with Paragraph 3			
Released to Imaging: 4/2	21/2021 1:12:59 PM				

District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 COMMENTS

Action 24720

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS							
Operator:			OGRID:	Action Number:	Action Type:		
HILCORP ENERGY COMPAN	Y 1111 Travis Street	Houston, TX77002	372171	24720	PACKER LEAKAGE TEST (NW)		
Created By	Comment			Commen	t Date		
kpickford	KP GEO Review 4/21/2021			04/21/20	21		

District I 1625 N. French Dr., Hobbs, NM 88240

District II

District IV

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410

С	ONDI	TIONS

Action 24720

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	24720	PACKER LEAKAGE TEST (NW)
OCD Reviewer			Condition		
kpickford			None		