# U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: RDX FEDERAL 17 Well Location: T26S / R30E / SEC 17 / County or Parish/State: EDDY /

SWSW /

NIM

NM

Well Number: 19 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM20965 Unit or CA Name: Unit or CA Number:

US Well Number: 3001541249 Well Status: Temporarily Abandoned Operator: WPX ENERGY

PERMIAN LLC

Accepted for record – NMOCD gc 5/19/2021

### **Notice of Intent**

Type of Submission: Notice of Intent

Type of Action Temporary Abandonment

Date Sundry Submitted: 05/07/2021 Time Sundry Submitted: 06:53

Date proposed operation will begin: 05/08/2021

Procedure Description: WPX ENERGY PERMIAN, LLC (WPX) requests to extend the TA status for the above mentioned well. The well is in approved TA status from 05/10/2020 to 05/09/2021, and we would like to extend it for another year until 05/09/2022. This well was first put into TA status of 05/10/2018. The attached MIT was performed on 05/10/2018. Justification: WPX requests the approval for another year of temporary abandonment (TA) status on the RDX Federal 17-19 to come up with a plan to either return to production or plug and abandon the wellbore. The well still has a good casing integrity, so no immediate wellbore intervention or casing remediation is necessary. Under current market conditions, about \$50/BO and \$2.50/MCF, and cost to bring back to production, the economics do not meet WPX Energy's cutoffs. Costs to return to production will require drilling out the cast iron bridge plug, installing artificial lift since the well will not flow on its own, and running flowlines to an offset battery since the current pad has no facilities. These costs are estimated to be in the amount of about \$300,000 with a payout of a little over four years, not including other potential workovers to make repairs. Other costs include an approximate \$100,000 plug and abandonment liability. By extending the TA it will give WPX Energy more time to review alternatives to produce the well with different forms of artificial lift and/or more cost-effective methods to produce and meter the production into a facility. Other uses for the well such as an SWD or gas storage well are also not feasible or necessary at this time.

# **Surface Disturbance**

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

### **Procedure Description**

 $RDX\_Federal\_17\_19\_BLM\_3160\_5\_TA\_Renewal\_Intent\_Approved\_2020\_4\_7\_20210507065309.pdf$ 

RDX\_Federal\_17\_19\_MIT\_20210507065218.pdf

well Name: RDX FEDERAL 17 Well Location: T26S / R30E / SEC 17 / County or Parish/State: EDDY /

SWSW /

Well Number: 19 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM20965 Unit or CA Name: Unit or CA Number:

US Well Number: 3001541249 Well Status: Temporarily Abandoned Operator: WPX ENERGY

PERMIAN LLC

# **Conditions of Approval**

### **Specialist Review**

TA\_COA\_20210518131508.pdf

# **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: CAITLIN O'HAIR Signed on: MAY 07, 2021 06:51 AM

Name: WPX ENERGY PERMIAN LLC

Title: Regulatory

Street Address: 333 W. SHERIDAN AVE.

City: OKLAHOMA CITY State: OK

Phone: (405) 552-3330

Email address: CAITLIN.O'HAIR@DVN.COM

## **Field Representative**

**Representative Name:** 

**Street Address:** 

City: State: Zip:

Phone:

**Email address:** 

## **BLM Point of Contact**

Signature: Jonathon Shepard

**BLM POC Name:** Jonathon W Shepard **BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5752345972 **BLM POC Email Address:** jshepard@blm.gov

**Disposition:** Approved **Disposition Date:** 05/18/2021

The state of the s

5/10/18 Hemander

WPX CONSULTANT

124 Credit Dr. Scott, LA 70583 Phone (337) 237-7675 Fax (337) 237-7676

# Atchafalaya MEASUREMENT, INC.

Houma, LA 70360 Phone (985) 851-6077

Calil	brat	on	Cor	HE	cato
			-		

Company Name:_	American Safety Services	
Recorder Type:	Barton	
Recorder Serial:#	265-062017	

Recorder Pressure Range: 0-1000# Accuracy +/-: 0.2% PSIG
Temperature Range: 0-150 Deg F. Accuracy +/-: 2% Deg F

Increasing Pressure			Decreasing Pressure			
Pressure	Pressure		THE RESERVE OF THE PARTY OF THE	Indicated Pressure	Error%	
0.0#			800#	800#		
100#	100#			600#		
300#	300#			400#		
500#	500#	0	THE RESERVE OF THE PERSON NAMED IN COLUMN 1	200#	0	
700#	700#	0	0.0#	0.0#		
1000#	1000#			0.0#		

Temperature Tes	t	1
Applied Temperature	Indicated Temperature	Error%
35	35	0
89	89	0
150	150	0
87	87	0
38	38	0

Certified Calibration Instrument Used
Gauge: Crystal
Deadweight:
Remarks:

Technician: Lang Sutherland. Craig Sutherland

By BB

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY   Do not use thi abandoned wel	NMNM20965     If Indian, Allottee or	Tribe Name				
SUBMIT IN T	7. If Unit or CA/Agree	ment, Name and/or No.				
Type of Well	er				8. Well Name and No. RDX FEDERAL 17	7 19
Name of Operator     WPX ENERGY PERMIAN LLC	Contact: E-Mail: caitlin.ohai	CAITLIN O'H r@wpxenergy.			9. API Well No. 30-015-41249-0	D-S1
3a. Address 35.00 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172  3b. Phone No. (include area code) Ph: 539-573-3527					10. Field and Pool or E BRUSHY DRAW	
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description	)			11. County or Parish, S	State
Sec 17 T26S R30E SWSW 66	60FSL 880FWL				EDDY COUNTY	, NM
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION			TYPE OF	FACTION		
Notice of Intent     ■	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	□ Nev	Construction	□ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon		arily Abandon	
	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal	
If the proposal is to deepen directional Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fix WPX ENERGY PERMIAN, LL.  The well is in approved TA state another year until 5/9/2021.  This well was first put into TA applease see the attached for the please see the attached for the state of the stat	k will be performed or provide operations. If the operation resonationment Notices must be file nal inspection.  C requests to extend the stus from 5/10/2019 to 5/0 status on 05/10/2018.  e previously approved pa	the Bond No. or sults in a multipled only after all TA status for 19/2020, and	n file with BLM/BIA e completion or reco requirements, includ the above menti we would like to	a. Required sub impletion in a raining reclamation	osequent reports must be new interval, a Form 3160 n, have been completed a	filed within 30 days 0-4 must be filed once
	#Electronic Submission For WPX ENEI nmitted to AFMSS for proc	RGY PERMIAI	l LĹC, sent to the SCILLA PEREZ o	e Carlsbad	(20PP1904SE)	
Name (Frimew Typea) CATTLIN	JIAIK		Title REGUL	AIORTIE	<u>ЭП II</u>	
Signature (Electronic S	Submission)		Date 04/03/2	020		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE	
_Approved By_JONATHON SHEPA Conditions of approval, if any, are attached	d. Approval of this notice does		TitlePETROLE	UM ENGINI	EER	Date 04/07/2020
certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second tributes as a second tribute of the second tributes as a second tribute as a second	ct operations thereon.		Office Carlsbac	-	ake to any denartment or	agency of the United
States any false, fictitious or fraudulent s				winiuny to ma	are to any department of	agency of the Officed

### Revisions to Operator-Submitted EC Data for Sundry Notice #509582

**Operator Submitted BLM Revised (AFMSS)** 

TA NOI TA NOI Sundry Type:

NMNM20965 NMNM20965 Lease:

Agreement:

Operator: WPX ENERGY PERMIAN LLC

WPX ENERGY PERMIAN, LLC 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74103 3500 ONE WILLIAMS CENTER MD 35

TULSA, OK 74172 Ph: 539-573-3527 Ph: 855 979 2012

CAITLIN O'HAIR REGULATORY TECH III CAITLIN O'HAIR REGULATORY TECH II Admin Contact:

E-Mail: caitlin.ohair@wpxenergy.com E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527 Ph: 539-573-3527

CAITLIN O'HAIR REGULATORY TECH III Tech Contact:

CAITLIN O'HAIR REGULATORY TECH II

E-Mail: caitlin.ohair@wpxenergy.com E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527 Ph: 539-573-3527

Location:

State: County: NM EDDY NM EDDY

BRUSHY DRAW; DELAWARE **BRUSHY DRAW-DELAWARE** Field/Pool:

Well/Facility:

RDX FEDERAL 17 019 Sec 17 T26S R30E 660FSL 880FWL 32.037029 N Lat, 103.909217 W Lon RDX FEDERAL 17 19 Sec 17 T26S R30E SWSW 660FSL 880FWL

Released to Imaging: 5/19/2021 3:19:44 PM

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.

11. County or Parish, State

EDDY COUNTY, NM

Form 3160-5 (June 2015)

TULSA, OK 74172

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 17 T26S R30E SWSW 660FSL 880FWL

32.037029 N Lat, 103.909217 W Lon

# **UNITED STATES**

FORM APPROVED 0137 1,2018

DEPARTMEN BUREAU OF I SUNDRY NOTICES A Do not use this form for p abandoned well. Use form	OMB NO. 1004-0137 Expires: January 31, 2018  5. Lease Serial No. NMNM20965  6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE	- Other instructions on page 2	7. If Unit or CA/Agreement, Name and/or No.
Type of Well	si sa	8. Well Name and No. RDX FEDERAL 17 019
Name of Operator.     RKI EXPLORATION & PRODUCTION E-M	Contact: CAITLIN O'HAIR ail: caitlin.ohair@wpxenergy.com	9. API Well No. 30-015-41249
3a. Address 3500 ONE WILLIAMS CENTER MD 35	3b. Phone No. (include area code) Ph: 539-573-3527	10. Field and Pool or Exploratory Area BRUSHY DRAW; DELAWARE, E

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
<ul> <li>☑ Notice of Intent</li> <li>☐ Subsequent Report</li> <li>☐ Final Abandonment Notice</li> </ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	<ul> <li>□ Production (Start/Resume)</li> <li>□ Reclamation</li> <li>□ Recomplete</li> <li>☑ Temporarily Abandon</li> <li>□ Water Disposal</li> </ul>	☐ Water Shut-Off ☐ Well Integrity ☐ Other	2.6

RKI EXPLORATION & PRODUCTION, LLC requests to put the above mentioned well in Temporarily Abandonment Status for 5 years. Lyear approved

The well is currently down due to a grounded ESP. The production (7bopd) does not justify a rod pump conversion workover in the current price environment; however, the well should be capable of producing in paying quantities.

Attached is a current and proposed WBD, as well as a procedure to MIT.


CONDITIONS OF APPROVAL					
	been Shutin w/out	a Dr	วทิบ	als	ince 10/2016
e Property of States on the	e foregoing is true and correct.  Electronic Submission #412420 verifie For RKI EXPLORATION & PROI Committed to AFMSS for processing b	/ JENN	IIFER S	SANCHEZ	mation System arlsbad on 04/23/2018 ()
Name (Frimew Typeu)	CAITLIN O'HAIR	Title	SUE	BMITTER	
Signature	(Electronic Submission)	Date	04/	9/2018	APPROVED X / /
	THIS SPACE FOR FEDERA	L OF	STA	TE OFFI	CE USE
Approved By		Title			APR 2 2018 Date
certify that the applicant hold	y, are attached. Approval of this notice does not warrant or s legal or equitable title to those rights in the subject lease cant to conduct operations thereon.	Offic	e	BURE	OF LAND MANAGEMENT
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

(Instructions on page 2)


\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

<sup>13.</sup> Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the cite is ready for final inspection. determined that the site is ready for final inspection.











### MIT Workover Procedure

Well: RDX 17-19 Location: Eddy, NM Date: April 19, 2018

Objective: Mechanical Integrity Test

#### **EH&S Notes:**

- ✓ Personnel Safety is the number one job, no exceptions.
- ✓ Please follow appropriate WPX Energy contractor protocols for this job plan. (Please see your) WPX Energy Business Representative if you have any questions; Contractor protocols can be found in the WPX Energy Contractor Guide.)
- Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10ppm will require work to stop and the situation to be evaluated
- A Safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent. Please ensure these are documented per the WPX Contractor Guide.

### Prior to Job:

- Schedule Workover Rig
- Test anchors if not done so recently
- Verify location is ok for rig operations
- Ensure all flowlines on surface are clear and lease operator has installed proper tags

Current Wellbore Status: Vertical Completion in Delaware.

#### Procedure:

- Spot equipment; MIRU
- Blow down casing. If necessary pump water down casing to kill well.
- TOOH with tbg and ESP.

### TUBING DETAIL

212-27/8 L-80 Jts

- 1- 2 7/8 Seat Nipple
- 1- 27/8 L-80 Jt
- 1- 2 7/8 Drain Valve
- 1- 27/8 L-80 Jt
- 1- DY330 ESP, Accelerated w/ Shroud
- 1- 2 7/8 Cavins DeSander Int- 6,945

4- 2.7/8 Mud Jts EOP- 7,005 1- 2.7/8 Bull Plug BP- 7,113'

The shroud depth is from the pump intake to 7,021'

MIT Workover Procedure

April 19, 2018

1



- RU Wireline and run gauge ring down to 50' above top perf.
- RIH with RBP and set no more than 100' above top perf.
- Set 6 sacks of sand on top of plug.
- Load hole with clean water.
- Open Casing valves and note any flow before pressure testing.
- Close casing and apply 500 psi at surface and hold for 30 minutes.
  - Make sure to chart the pressure test with a recorder that has a maximum two hour clock and maximum 1000 pound spring.
  - o Insure the unit has been calibrated within the last six months.
  - Please Ensure to have both the Consultant on location and Rig Tool Pusher sign the chart.
  - o Note any flow during test
- If the well drops below 450 psi (10%) within the 30 minutes then it is considered to have failed the test.
  - In the event of a failed test please notify WPX Engineer so the NMOCD can be notified and proper actions taken.
- If the well does not drop below 450 psi (10%) within the 30 minutes then it is considered a successful test. The signed chart can be turned into the WPX field office.
- Open Casing valves back up and note for flow.
- Top hole off with water and leave set.
- RDMO

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Approved for a period of 12 months ending 04/23/2019 subject to conditions of approval.

### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with wellbore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

### RDX Federal 17 19

- 1. Well is approved to be TA/SI for a period of 12 months or until 04/23/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 04/23/2019
- 3. COA's met at this time.

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY Do not use the abandoned we	<ul><li>5. Lease Serial No. NMNM20965</li><li>6. If Indian, Allottee or</li></ul>	r Tribe Name				
SUBMIT IN	7. If Unit or CA/Agree	ment, Name and/or No.				
Type of Well	ner				8. Well Name and No. RDX FEDERAL 17	7 19
2. Name of Operator RKI EXPLORATION & PROD	Contact: LLC E-Mail: caitlin.ohai	CAITLIN O'H ir@wpxenergy.o			9. API Well No. 30-015-41249-0	0-S1
3a. Address 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172  3b. Phone No. (include area code) Ph: 539-573-3527					10. Field and Pool or E BRUSHY DRAW	Exploratory Area V-DELAWARE
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	1)			11. County or Parish, S	State
Sec 17 T26S R30E SWSW 66	60FSL 880FWL				EDDY COUNTY	, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE OI	F ACTION		
Notice of Intent     ■	☐ Acidize	□ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	□ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New	Construction	☐ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon		arily Abandon	
	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal	
following completion of the involved testing has been completed. Final At determined that the site is ready for final RKI EXPLORATION & PROD Abandonment Status for 5 year. The well is currently down due pump conversion workover in producing in paying quantities. Attached is a current and prop	pandonment Notices must be fil inal inspection.  UCTION, LLC requests to ars.  e to a grounded ESP. The the current price environi	ed only after all above production (7 ment; however	requirements, includ re mentioned we 7bopd) does not r, the well should	ing reclamatio  II in Tempor  justify a rod	n, have been completed a	0-4 must be filed once and the operator has
14. I hereby certify that the foregoing is	Electronic Submission # For RKI EXPLO	RATION & PR	DD LLC, sent to t	he Carlsbad	•	
Name (Printed/Typed) CAITLIN (	nitted to AFMSS for proces D'HAIR	ssing by JENN	Title SUBMI		(18JAS1109SE)	
			D : 04/40/0	040		
Signature (Electronic S	THIS SPACE FO	OR FEDERA	Date 04/19/2			
	11110 01 7102 11		1			<u> </u>
_Approved By_(BLM Approver Not	Specified)		Title			Date 04/23/2018
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conductive transfer of the conductive trans	uitable title to those rights in the		Office Carlsbac	<u> </u>		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ake to any department or	agency of the United
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISE	D ** BLM RE	EVISED ** BLN	1 REVISED	) ** BLM REVISE	) **

### Revisions to Operator-Submitted EC Data for Sundry Notice #412420

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

TA NOI

TA NOI

Lease:

NMNM20965 NMNM20965

Agreement:

Operator:

**RKI EXPLORATION & PRODUCTION** 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172 3500 ONE WILLIAMS CENTER MD 35

TULSA, OK 74172 Ph: 539-537-1196 Fx: 539 573 2922

Admin Contact:

CAITLIN O'HAIR SUBMITTER

Ph: 539-573-3527

E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

Tech Contact:

CAITLIN O'HAIR SUBMITTER

E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

Location:

State: County: EDDY

BRUSHY DRAW; DELAWARE, E Field/Pool:

Well/Facility:

RDX FEDERAL 17 019 Sec 17 T26S R30E SWSW 660FSL 880FWL 32.037029 N Lat, 103.909217 W Lon

**RKI EXPLORATION & PROD LLC** 

CAITLIN O'HAIR SUBMITTER E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

CAITLIN O'HAIR

SUBMITTER

NM EDDY


E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

**BRUSHY DRAW-DELAWARE** 

RDX FEDERAL 17 19 Sec 17 T26S R30E SWSW 660FSL 880FWL





<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 28623

### **CONDITIONS OF APPROVAL**

Operator:	OGRID:	Action Number:	Action Type:
WPX ENERGY PERMIAN, LLC Devon Energy - Regulatory	246289	28623	C-103I
333West Sheridan Ave. Oklahoma City, OK73102			

OCD Reviewer	Condition
gcordero	None