

Well Name: LAGUNA GRANDE UNIT FEDERAL	Well Location: T23S / R29E / SEC 29 / NWSE /	County or Parish/State: EDDY / NM
Well Number: 3	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM19848	Unit or CA Name: LAGUNA GRANDE- ATOKA	Unit or CA Number: NMNM70967A
US Well Number: 300152341400S1	Well Status: Temporarily Abandoned	Operator: CIMAREX ENERGY COMPANY OF COLORADO

Accepted for record – NMOCD gc 5/19/2021

Subsequent Report

Type of Submission: Subsequent Report	Type of Action: Temporary Abandonment
Date Sundry Submitted: 04/09/2021	Time Sundry Submitted: 09:16
Date Operation Actually Began: 01/05/2021	

Actual Procedure: Notify BLM – Omar Alomar – on location. 1/5/21 MIRU. Pressure up csg to 540# for 30 mins – OK. Chart attached. Bleed off press. SI & secure well. RDMO. Cimarex respectfully requests TA status approval with passing MIT.

SR Attachments

Actual Procedure

MIT_Laguna_Grande_Unit_Fed_3_20210409091555.pdf

SR Conditions of Approval

Specialist Review

TA_COA_20210426150218.pdf

Received by OCD: 5/5/2021 8:04:24 AM

Page 2 of 7

Well Name: LAGUNA GRANDE UNIT FEDERAL	Well Location: T23S / R29E / SEC 29 / NWSE /	County or Parish/State: EDDY / NM
Well Number: 3	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM19848	Unit or CA Name: LAGUNA GRANDE-ATOKA	Unit or CA Number: NMNM70967A
US Well Number: 300152341400S1	Well Status: Temporarily Abandoned	Operator: CIMAREX ENERGY COMPANY OF COLORADO

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: FATIMA VASQUEZ

Signed on: APR 09, 2021 09:15 AM

Name: CIMAREX ENERGY COMPANY OF COLORADO

Title: Regulatory Analyst

Street Address: 600 N Marienfeld Ste 600

City: Midland**State:** TX

Phone: (432) 620-1933

Email address: fvasquez@cimarex.com

Field Representative

Representative Name: Fatima Vasquez

Street Address: 600 N Marienfeld St., Suite 600

City: Midland**State:** TX**Zip:** 79701

Phone: (432)620-1933

Email address: fvasquez@cimarex.com

BLM Point of Contact

BLM POC Name: Jonathon W Shepard

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345972

BLM POC Email Address: jshepard@blm.gov

Disposition: Approved

Disposition Date: 04/26/2021

Signature: Jonathon Shepard

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.

Laguna Grande Unit 3


Actual Procedure:


Notify BLM – Omar Alomar – on location.

1/5/21 MIRU. Pressure up csg to 540# for 30 mins – OK.

Chart attached. Bleed off press. SI & secure well. RDMO.

Cimarex respectfully requests TA status approval with passing MIT.





District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 26880

CONDITIONS OF APPROVAL

Operator:	CIMAREX ENERGY CO. OF COLORADO	600 N. Marienfeld Street	OGRID:	162683	Action Number:	26880	Action Type:	C-103U
	Suite 600	Midland, TX79701						
OCD Reviewer	Condition							
gcordero	None							