| Office | <i>PM</i> State of New Me Energy, Minerals and Nature | | Form C-103 Revised July 18, 2013 | | | | |
|--|---|---|---|--|--|--|--|
| <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 | | | WELL API NO. 30-025-47663 | | | | |
| 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 | OIL CONSERVATION 1220 South St. Fran | | 5. Indicate Type of Lease STATE STATE | | | | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 | Santa Fe, NM 87 | 7505 | 6. State Oil & Gas Lease No. VB-2121 | | | | |
| (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC | CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO | JG BACK TO A | 7. Lease Name or Unit Agreement Name BLUE RIBBON FEDERAL COM | | | | |
| PROPOSALS.) 1. Type of Well: Oil Well | Gas Well 🗍 Other | | 8. Well Number 703H | | | | |
| 2. Name of Operator FRANKLIN | | | 9. OGRID Number 373910 | | | | |
| 3. Address of Operator 44 COOK S | STREET, SUITE 1000, DENVER, | CO 80206 | 10. Pool name or Wildcat WC-025 G-09 S253502D; UPR WOLFCAMP | | | | |
| 4. Well Location Unit LetterC: Section 2 | 675feet from thenorth Township 25S 11. Elevation (Show whether DR, 3245 | Range 35E | NMPM County Lea | | | | |
| 12. Check A | Appropriate Box to Indicate Na | ature of Notice, | Report or Other Data | | | | |
| | TENTION TO: | SUB | SEQUENT REPORT OF: | | | | |
| NUTICE OF IN | | | | | | | |
| | PLUG AND ABANDON | REMEDIAL WOR | | | | | |
| NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE | PLUG AND ABANDON | REMEDIAL WOR COMMENCE DR CASING/CEMEN | ILLING OPNS. P AND A | | | | |
| PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING | CHANGE PLANS | COMMENCE DR | ILLING OPNS. P AND A | | | | |

H&P 556 rigged up on the Blue Ribbon Fed Com 703H was re-spud 1/21/2021. Drilled and cased the 1st intermediate section. Wellbore construction details below:

Drilled 1st intermediate 12.25" hole to 5,445' TD KB. RIH w/ 118 jts. (5,425.53) 9.625" 40 lb/ft, L-80 BTC intermediate casing as follows: Float shoe 1.89', 1 csg joint 43.17', float-collar 1.48', 30 jts 1,375', dv tool set at 3,985 to 4,011' MD, 87 jts, LJ 39.76, landed at 5,433.63'.

Cemented 9.625" casing as follows: test lines to 4500 psi. Cement 1st stage with 160 bbls of 14.8 ppg, set packer, open dv tool, attempt to circ, cannot establish circulation. Pump 80 bbl water into annulus at 5.2 bpm at 1700 psi, begin cement lead, casing capacity 302 bbl to dv, mixed and pumped 405 bbl 12.8 ppg, squeezed out at 4343 psi. Unable to complete job. Rig down cementers, 1/d landing joint, wash out stack, make up bit and clean out cement in 9 5/8" to 3,985' (top of dv), shift dv closed with drill bit. Bad cement. Contact BLM for procedure and for permission to proceed. Run CBL. BLM approval to proceed with drilling operations received.

| Spud Date: | 1/21/2021 | Rig Release Date: | | | |
|-------------------------------|---|-----------------------------|--------------------------|---------------|-----------|
| I hereby certi | fy that the information above is true a | and complete to the best of | my knowledge and belief. | | |
| SIGNATURI | 3 | TITLE_Dir. Ops Pla | anning & Regulatory | DATE7/29/2021 | l |
| Type or print For State Us | name <u>Rachael Overbey</u> e Only | E-mail address: | _roverbey@fmellc.com | _ PHONE:720- | 414-6878_ |
| APPROVED | BY: | TITLE | | DATE | |

Conditions of Approval (if any): Released to Imaging: 8/2/2021 1:57:35 PM


| Recei | ved | by One | Ron Number Bit | 1000 | Winessed By | Resorded By | Location | Ecopoment Number | Tite Logger on Bottom | Tive Well Ready | Estimated Cement Top | Max. Recorded Temp. | Density / Viscosity | Type Fluid | Open Hole Size | Top Log Interval | Bottom Logged Interval | Depth Logger | Depth Driller | Run Number | Date | We Fie Co Sta | ell eld ounty ate | Blu Jal Lea | e Rik | n Mount bbon Fe exico | ed Con | n 703ł | | 0 | Page 2 of 5 |
|------------------|----------------|-----------|----------------|-----------------|-------------|-------------|-------------|------------------|-----------------------|-----------------|----------------------|---------------------|---------------------|---------------|----------------|------------------|------------------------|---------------|---------------|------------------------|-----------------------|------------------------|--------------------------------------|-------------------|-----------------|-----------------------------|---------------------|-----------------|--------------------------|----------------------------------|--|
| | | | From | Borehole Record | | | | | | | | | | | | | | | | | | Drilling Measured From | Permanent Datum Log Measured From | SEC | | _ocation: | County Lea | Field Jal | Well BI | Company Franklin Mountain Energy | |
| | | | To | | | Pete Landis | Midland TX. | WL-2 | 15:30 | 14:30 | | 102* | 8.3# | Freshwater | N/A | Surface | 5,360' | 5,360' | 5,433' | One | 1-25-2021 | | KB | TWP | | | à | _ | Blue Ribbon Fed Com 703H | anklin Mou | য |
| | | 9 5/8" | Size | | | | | | | | | | | | | | | | | | | - | | RGE | | API # : 30-025-47633 | (0) | | Fed Com | ıntain Ene | adial Ce |
| | | | Weight | Casing Record | | | | | | | | | | | | | | | | | | | Elevation | | |)25-47633 | State N | | 703H | rgy | Radial Cement Bond Log |
| | | Surface | From | cord | | | | | | | | | | | | | | | | | | G.L. | K.B. | <u></u> | | Othe | New Mexico | | | | ond Log |
| <<< | < Fo | 5,433' | To | | >> | | | | | | | | | | | | | | | | | | | Elevation | | Other Services | ö | | | | |
| All int of ar | terpr ny in | reta | tior pre | ns a tatic | re o | and | we | sh | all r | not, nyo | exc ne | ept resi | in ti ultin | he o Ig fr | case om | e of any | gro int | oss o terp | or w reta | villfu ation con | ul ne n m ditio | eglig ade | ence o by any set out | n our of ou | part, r offi | , be liab | ole or r gents c | espon or emp | sible f | or any lo | accuracy or correctness iss, costs, damages, or interpretations are also |
| | | | | | | | | | | | Τł | าลเ | nk | Ye | ou | Fo | or | Ch | 100 | | | | | n E | ner | gy Se | ervic | es | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |


| Sensor | Offset (ft) | Schematic | Description | Length (ft) | O.D. (in) | Weight (Ib |
|---------------|-------------|------------------|-------------|-------------|-----------|------------|
| ErrCt | 23.30 | | | | | |
| Released to I | naging: 8/2 | /2021 1:57:35 PM | | | | |


| Received by O | CD: 7/30/2 | 2021 4:06:08 PM | | CENT-CH_3.5IN FG010-BH01 | 4.47 | 3.50 | Page 3 of 5 |
|----------------------|----------------|------------------------|----------------------|-----------------------------------|-------------------|----------|--------------------|
| | | | | | | | |
| | | I | | | | | |
| | 10.10 | | | | | | |
| IntTemp Headvolt | 18.18 18.18 | J | | | | | |
| | | | | | | | |
| RBT_ACCZ RBT_ACCY | 16.85 16.85 | | | | | | |
| RBT_ACCX | 16.85 | | | | | | |
| | | | | | | | |
| WVFS16 | 14.60 | | | RBT16-PTS_351A (RBT351A_base) | 0.00 | 2.50 | |
| WVFS15 | 14.60 | | | Probe RADII 351-A | 8.98 | 3.50 | |
| WVFS14 | 14.60 | | | | | | |
| WVFS13 | 14.60 | | | | | | |
| WVFS12 | 14.60 | | | | | | |
| WVFS11 | 14.60 | | | | | | |
| WVFS10 | 14.60 | | | | | | |
| WVFS9 | 14.60 | - | | | | | |
| WVFS8 WVFS7 | 14.60 | | | | | | |
| WVFS7 WVFS6 | 14.60 14.60 | | | | | | |
| WVFS0 WVFS5 | 14.60 | | | | | | |
| WVFS4 | 14.60 | | | | | | |
| WVFS3 | 14.60 | | | | | | |
| WVFS2 | 14.60 | | | | | | |
| WVFS1 | 14.60 | | | CENT-CH_3.5IN FG010-BH01 | <mark>4.47</mark> | 3.50 | <mark>46.00</mark> |
| WVFCAL | 14.60 | | | FG010-BH01 | | | |
| WVF3FT | 14.60 | | | | | | |
| WVF5FT | 13.60 | | | | | | |
| HEADVOLT | 9.85 | | | | | | |
| | | - | | | | | |
| CCL\$2 | 4.14 | | | | | | |
| CCL\$1 | 4.14 | | | | | | |
| GCT_Temp | 3.26 | | | | | | |
| | | Í | | GC-GCT275-0BP0 (GCT275-0BP0_base) | 5.38 | 2.75 | 59.00 |
| GR | 2.39 | | | Probe GCT275-0BP0 w/Temp 6 Magnet | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | Ų | | | | | |
| | | Dataset: | 1-25-2021 | | iss8 | <u>.</u> | _ <u></u> |
| | | Total length: | 23.30 ft | - | | | |
| | | Total weight: O.D.: | 151.00 lb 3.50 in | | | | |
| | | U.D | 5.50 III | | | | |





Free Pipe Pass















Page 7 of 50




Page 8 of 50












Page 12 of 50







Page 14 of 50




Page 15 of 50




Page 16 of 50




Page 17 of 50





Page 18 of 50





Page 19 of 50





























| Received by OCD: 7/30/2021 4:00 | | 98.7 98.7 98.7 98.7 98.7 98.6 98.6 98.6 98.6 | |
|---------------------------------|------------------|--|------------------------------------|
| 325 TT (usec) 225 | 0 AMP (mV) 100 | 0 AMPMIN 150 | 200 VDL (usec) 1200 1 Cement Map 8 |
| -9 CCL 1 | 0 AMPx10 (mV) 10 | | |
| 0 GR (GAPI) 200 | | 0 AMPMAX 150 | |
| U UK (UAFI) 200 | | · | - |
| | | GCT_TEMP | |
| | | (degF) | |

| Database File Dataset Pathname Dataset Creation | 1-25-2021_frankl pass8 Mon Jan 25 15:3 | _ | | tion Repo | prt | | |
|---|--|----------------|-----------------------------------|------------|-------------------|--------|--------|
| | | G | amma Ray | Calibratio | n Report | | |
| Serial Nu Tool Mod Performe | el: | | GCT275-0 GCT275-0 Wed Sep 1 | 3P0 | | | |
| Calibrator | Value: | | 1.0 | | GAPI | | |
| Backgrou Calibrator | 0.0 1.0 | 1 | | | | | |
| Sensitivit | y: | | 1.0000 | | GAPI/cps | | |
| | | Segmente | ed Cement B | ond Log (| Calibration Repor | t | |
| Serial Nu Tool Mod | | | RBT351A_ PTS_351A | | | | |
| Calibratio Calibratio | n Casing Diamete n Depth: | r: | 9.625 115.792 | | n ft | | |
| Master C | alibration, perform | ed Mon Ja | n 25 14:44:2 | 1 2021: | | | |
| | Raw | (v) | | Calibrate | ed (mv) | Res | ults |
| | Zero | Cal | Z | Zero | Cal | Gain | Offset |
| eleased to Induging: 8/ CAL | /2/2021 1:507.906PM -0.006 | 0.907 1.074 | | 0.000 | 51.280 | 56.191 | 0.315 |

| 5' | -0.006 | 1.168 | 0 | .000 | 51.280 | 43.699 | 0.253 | Dama 22 |
|---------------------|-------------------|------------|-----------------|-----------|----------|-----------|-------------|---------|
| ved by OSDM7/30/202 | | 0.059 | 0 | 000 | 100 000 | 102 742 | 0 592 | Page 32 |
| S1 | -0.006 | 0.958 | | .000 | 100.000 | 103.743 | 0.583 | |
| S2 | -0.006 | 1.000 | | .000 | 100.000 | 99.376 | 0.626 | |
| S3 | -0.006 | 1.008 | | .000 | 100.000 | 98.582 | 0.605 | |
| S4 | -0.006 | 1.010 | | .000 | 100.000 | 98.467 | 0.563 | |
| S5 | -0.006 | 0.997 | | .000 | 100.000 | 99.709 | 0.621 | |
| S6 | -0.006 | 0.961 | | .000 | 100.000 | 103.402 | 0.607 | |
| S7 | -0.006 | 0.914 | 0 | .000 | 100.000 | 108.715 | 0.606 | |
| S8 | -0.006 | 0.874 | 0 | .000 | 100.000 | 113.615 | 0.724 | |
| Internal Refe | rence Calibratior | n, perform | ed (Not Perform | med): | | | | |
| | Raw (v |) | C | Calibrate | ed (v) | Re | sults | |
| | Zero | Cal | Zero | D | Cal | Gain | Offset | |
| CAL | 0.000 | 0.000 | -0 | .006 | 1.074 | 1.000 | 0.000 | |
| Air Zero Calit | oration, performe | ed Mon Ja | in 25 14:30:05 | 2021: | | | | |
| | Raw (v |) | C | Calibrate | ed (v) | Re | sults | |
| | Zero | | Zero | D | | | Offset | |
| 3' | 0.000 | | 0 | .000 | | | 0.000 | |
| 5' | 0.000 | | | .000 | | | 0.000 | |
| SUM | 0.000 | | 0 | .000 | | | 0.000 | |
| S1 | 0.000 | | 0 | .000 | | | 0.000 | |
| S1 S2 | 0.000 | | | .000 | | | 0.000 | |
| | | | | | | | | |
| S3 | 0.000 | | | .000 | | | 0.000 | |
| S4 | 0.000 | | | .000 | | | 0.000 | |
| S5 | 0.000 | | | .000 | | | 0.000 | |
| S6 | 0.000 | | | .000 | | | 0.000 | |
| S7 | 0.000 | | 0 | .000 | | | 0.000 | |
| S8 | 0.000 | | 0 | .000 | | | 0.000 | |
| | | In | clinometer Cal | ibration | Report | | | |
| Performed: | (No | ot Perform | ned) | | | | | |
| | Lov | v Read. | High Read. | | Low Ref. | High Ref. | | |
| X Accelerome | | 0 | 1.00 | | 0.00 | 1.00 | 7 00 | |
| | 0.0 | U | 1.00 | | 0.00 | 1.00 | gee | |
| Y Accelerome | eter 0.0 | 0 | 1.00 | | 0.00 | 1.00 | doo | |
| | | U | 1.00 | | 0.00 | 1.00 | gee | |
| Z Accelerome | eter 0.0 | 0 | 1.00 | | 0.00 | 1.00 | gee | |
| | | | | | | | | |

| | Company | Franklin Mountain Energy | | |
|-----------------------------|---------|--------------------------|---------|-----|
| | Well | Blue Ribbon Fed Com 703H | | |
| | Field | Jal | | |
| VAUGHN ENERGY SERVICES INC. | County | Lea | | |
| | State | New Mexico | Country | USA |

Released to Imaging: 8/2/2021 1:57:35 PM

Received by OCD: 7/30/2021 4:06:08 PM



FIELD SERVICE REPORT COVER SHEET

Form #FF-05, Rev B

FSJ # M-20-1171

Page 33 of 50

| VERTICAL 🛛 | HORIZONTAL | | DE | EVIATED (⁰) |) | | |
|------------------------|----------------------|----------|-----------|--------------------------|------------|------|-----|
| START DATE: | 1/24/2021 | CUSTOMER | R: Frank | lin Mountain | Energy | | |
| TAM BASE: | Midland | AGENT: | | | | | |
| SERVICE SPECIALIST: | P. Moore / R. Sexton | ADDRESS: | 44 Co | ook Street | | | |
| | F. MODIE / R. SEXION | | Suite | 1000 | | | |
| S.O. No.: | | | | Denver | со | 8020 |)6 |
| P.O. No.: | | | | | | | |
| C.T.No.: | CT-RS-1171 | CONTACT: | Frank | Lacey / Ha | rvey Moore | | |
| RIG TYPE: | Drilling | WELL NAM | E & No.: | Blue Ribbo | on 703H | | |
| CONTRACTOR: | H&P 556 | GEOGRAP | HIC AREA: | Lea | County | NM | USA |

JOB OBJECTIVES:

To achieve annular isolation using two stage cementing solution via TAM LONGCAP packer and stage tool.

TOOLS ON LOCATION:

9.63 LONGCAP ASSEMBLY, 10.88" OD, 120" SEAL, 40# DRIFT, 8.79" ID HCL-80, BTC BOX X PIN 9.63 L-80 HC BTC BOX X PIN 40# DRIFT 8.79 ID 8' PUP JOINT 9.63" STAGE TOOL, 40# DRIFT, 8.75" ID L-80, BTC BOX X BTC PIN PLUG SET FOR CEMENT COLLAR USE WITH 963-DV-900291600

JOB RESULTS:



FIELD SERVICE REPORT

FSJ No.: M-20-1171

WELLBORE SKETCH

| PREPARED FOR Frank Lacey / Ha | | COM Frank | | | n Ener | nv | | | | DATE: 1/24/21 | | | |
|----------------------------------|---------|--------------|----------------------|-------------------|--------|-------|----|--------|--------|------------------|----------|----------|---------|
| | | | | | | | | | | | | | |
| WELL: Blue Ribbon 703 | - | LOC | Lea | : Cou | intv | NM | | NEW | WELL: | | WOR | (OVER: | |
| | ί – Τ | | Lea | 000 | Tity | INIVI | | L | | | | | |
| | ITEM | | | DESCR | | ON | | | OD" | ID" | LENGTH | FROM | то |
| | | Landing J | loint / Cas | ing Hang | jer | | | | 9.625 | 8.835 | 38.76 | -3.63 | |
| | | 9.625 | 40# E | втс но | CL-80 | | 87 | Joints | 9.625 | 8.835 | 3,947.10 | 35.13 | |
| | | | gCap Ass PN: 9 | | | | | | 10.880 | 8.750 | 25.45 | 3,982.23 | |
| | | PN: 963- | DV-90029 PJ-12908 | 9 1600 9.6 | | | | | | | | | |
| | | 9.625 | 40# E | втс но | CL-80 | | 30 | Joints | 9.625 | 8.835 | 1,375.78 | 4,007.68 | |
| | | Float Coll | lar (Sumn | nit) | | | | | | | 1.48 | 5,383.46 | 1 |
| | | 9.625 | 40# I | втс но | CL-80 | | 1 | Joint | 9.625 | 8.835 | 43.17 | 5,384.94 | |
| | | Float Sho | e (Summ | nit) | | | | | | | 1.89 | 5,428.11 | |
| | | | | | | | | | | | | | |
| CASING: SURFA | CE | 13 3/8 | | SET@ | | 1352 | 1 | NTERN | | E | 9 5/8 | SET@ | 5435.5 |
| LONG STRING RESTRICTIONS | | | | SET@ | | | | LINER | | | | SET@ | |
| WORK STRING | | | | FLUID: | | Brir | le | WT.#/ | | 1(| 0.1 LE | VEL | SURFACE |
| | VIEINTO | | | | | | | | | | | | |

.



| Customer | - | Franklin Mountain Energy |
|--------------------------|----|--|
| Customer Rep | - | Frank Lacey / Harvey Moore |
| Well Number | - | Blue Ribbon 703H |
| Drilling Contractor | - | H&P 556 |
| Rig Name | xx | H&P 556 |
| Well Type | - | VERTICAL |
| Casing Size | - | 13 5/8 |
| Casing Weight | - | 54.5 |
| Casing Grade | - | J-55 |
| Casing Thread | - | BTC |
| Casing Depth MD/TVD | - | 1352 |
| Liner Size | - | 9.625 |
| Liner Weight | - | 40 |
| Liner Grade | - | HCL-80 |
| Liner Thread | - | BTC |
| Liner Depth MD/TVD | - | 1352 |
| Open Hole ID | - | 12.25 |
| Open Hole Depth MD/TVD | - | 5446 |
| Maximum Well Deviation | - | - |
| Maximum Dog Leg Severity | - | - |
| Well Fluid Type/Density | - | Brine / 10.1 |
| Well Fluid Level | - | SURFACE |
| Bottom Hole Pressure | | 2860 |
| Bottom Hole Temperature | - | 110 |
| Page 3 of 4 | | M-20-1171 FME, Blue Ribbon 703H Job File |

Released to Imaging: 8/2/2021 1:57:35 PM

TAM INTERNATIONAL OPERATION REPORT

| Shut in Well Head Pressure | - | - |
|---|---|---|
| Formation Type | - | - |
| Production Tubing Size | - | - |
| Production Weight | - | - |
| Production Grade | - | - |
| Production Thread | - | - |
| Production Tubing Depth MD/TVD | - | - |
| Restriction | - | - |
| Setting Depth of Tools MD/TVD | - | - |
| Setting Depth Intervals MD/TVD | - | - |
| ID Tools must be set in | - | - |
| Smallest ID Tools must pass through | - | - |
| Deviation at Tool Setting | - | - |
| Inflation Fluid Type | - | ÷ |
| Type of Fluid(s) to be pumped | - | - |
| Density of Fluid(s) to be pumped | - | - |
| Temperature of Fluid(s) to be pumped | - | - |
| Maximum Pump Rate | - | - |
| CE Jobs Only: Number of Inflation Cycles | - | - |
| Total Volume of Mud Pumped | - | - |

.


.

| | | | ATIONAL | |
|----------------|---|--|---------------------------|---|
| Operator: | Franklin M | Nountain Energy | Base Point: | Midland |
| Company Rep: | | ey / Harvey Moore | Tam Rep: | P. Moore / R. Sexton |
| Well Name: | | Ribbon 703H | Date Started: | 1/24/2021 |
| Ticket Number: | the second s | -RS-1171 | Date Completed: | 1/25/2021 |
| | Lea | -KS-11/1 NM | Type of Job: | 2 Stage Cement |
| County/State: | and the second se | INIVI | | the second se |
| DATE | Time | | Acti | |
| | 6:00 | | DLAND, TX FOR LOCA | ATION |
| | 8:00 | ARRIVE ON LOCATI | | NG TALLY, WELL INFO, MUD WEIGHTS, |
| | 8:10 | CEM INFORMATION | | NG TALLT, WELL INFO, MUD WEIGHTS, |
| | 8:15 | | | N HOLE, INSPECT FOR POSSIBLE |
| | 0.15 | DAMAGE TO ELEME | | THOLE, NOT EOT FORT OCODEL |
| | | | | ACT, INSPECT FOR CORRECT |
| | | THREADS | | |
| | 8:30 | | PACKER PLACEMEN | IT ONTOP OF JOINT |
| | 5.65 | 31, AND MARK OUT | | |
| | 8:40 | | | /ITH RIG CREW, CASING CREW (H&P) |
| | | AND CO MAN | | |
| | 8:48 | | | ISING SUMMIT FLOAT EQUIPMENT AND |
| | | THREAD LOK AND | | |
| | 9:00 | PUMP THROUGH W | ITH CRT AND CHECK | (FLOATS |
| | 10:18 | | KED TOOL ASSEMBL' | |
| | 14:30 | ON BOTTOM WITH | CASING, NO ISSUES | WHILE RUNNING IN HOLE, START |
| | | | | PM, 200 PSI STAND PIPE PRESSURE |
| | 15:15 | | tion, relieving Paul Mod | ore |
| | 15:30 | Rig up Schlumberger | | |
| | 16:30 | | | n location over cement job. |
| | 17:08 | Pressure test cemen | | |
| | 17:22 | Start 30 bbls of 12.5 | | |
| | 47.00 | 20 bbls 2.7 bbl | | And a second |
| | 17:38 | Start 160 bbls of 14.8 25 bbls 5.2 bbl | | |
| | | 150 bbls 4.5 bbl | | |
| | 18:15 | Load Wiper Plug | S/IIIII 150 PS1 | |
| | 18:17 | | t displacing calculated | 408 bbls to float collar |
| | 10.17 | | Is/min 100 PSI | |
| | | | Is/min 100 PSI | |
| | | and a second | Is/min 100 PSI | |
| | 19:01 | | rate to 4 bbls/min 300 F | PSI |
| | | | Is/min 740 PSI | |
| | 19:50 | | | 100 PSI. Kicked off pumps at 2,100 PSI. |
| | 19:54 | Walk up in 200 PSI in | ncrements at 1 bbls/mil | n to set packer. |
| | | 2,400 PSI75 bb | ols | |
| | | 2,700 PSI75 bb | ols | |
| | | 3,000 PSI75 bb | | |
| | 00.00 | | ols - (3 bbls pumped) | |
| | 20:00 | | | arted to drop. Stabilized at 3,040 PSI. |
| | 20.02 | 110 PSI pressure dro | | aluma (1 hbla sature al) Other to |
| | 20:03 | | | olume (1 bbls returned). 2 bbls to b truck had leak so assuming less |
| | | volume in LongCap) | | o unok nau leak so assuming less |
| | 20:05 | | | ves have functioned and closed. (3 bbls) |
| | 20:09 | | | nd check floats. Calculated returns - 5.25 |
| | 20.00 | | 6.5 bbls. (2.75 bbls fr | |
| | 20:15 | | ne. Wait 25 minutes be | |
| | 20:42 | | | and kicked off pumps at 1,200 PSI. |
| | LV.72 | | | DV tool) Pressure slowly started |
| | | | | re to 0, .75 bbls returned. |
| | 20:50 | | | sure stablized at 1,500 PSI. Pumped |
| | | | n. Bled off pressure to (| |
| | 21:02 | | | SI. Pressure stablized at 1,700 PSI. |
| | | | | turns. Fluid started dropping in the annulus. |

| | | | RNATIONAL | |
|--|------------|-------------------------------------|---|--|
| Operator: | Franklin M | Mountain Energy | Base Point: | Midland |
| Company Rep: | | ey / Harvey Moore | Tam Rep: | P. Moore / R. Sexton |
| Well Name: | | Ribbon 703H | Date Started: | 1/24/2021 |
| Ticket Number: | | -RS-1171 | Date Completed: | 1/25/2021 |
| County/State: | Lea | NM | Type of Job: | |
| DATE | Time | T T T | the second s | 2 Stage Cement |
| DATE | 21:10 | Chut down to make a | Acti | |
| | 21:39 | Shut down to make p | hone call with Schlum | berger engineers. |
| | 21.39 | Started pumping 8.4# | fresh water at 5 bbis/i | min and pressure stabilized at 2,300 PSI. |
| | | decision is made on r | pressure aropped to 1 | ,700 PSI. Continue circulating until |
| | 21:55 | | | |
| | 21.00 | linto stogo 2 | a or o.4# fresh water a | nd shut down. Decision made to go |
| | 00.47 | into stage 2. | | |
| | 22:17 | Start 30 DDIS OF 12.5# | stage 2 spacer at 4 bl | bis/min 1,380 PSI. |
| | 22.20 | | # stage 2 lead cement | |
| | | 50 bbls 5.1 bbl 100 bbls 5.1 bbl | | |
| | | | | |
| | | 300 bbls 4.9 bbl | | |
| | 22.47 | 400 bbls 5.2 bbl | | od olimbing. Dumpe kined and of a |
| | 23:47 | AL 4 TO DOIS INTO READ O | cement, pressure start | ed climbing. Pumps kicked out at 2,500 |
| | | Kieked aut | nping at 2 bbls/min an | d pressure to increased to 4,500 PSI. |
| 1/25/2021 | 0:15 | | d pressure held steady | |
| 1/25/2021 | 0.15 | | | Irill pipe and try and wash as much |
| | 0.45 | | | to shift DV closed if needed. |
| | 2:45 | | ub and start in hole will | th drill pipe. Washing and rotating to DV |
| | 5.10 | tool. | | |
| | 5:43 | Made up stand 43. S/ | O Weight - 113,000lbs | s. Tagged DV tool at 3,990' and sat |
| | | | | on pipe and slowly started adding |
| | | weight. Sat down 50,0 | JUU lbs and felt no indi | cation. Pulled back up to mark and |
| | 5.54 | weight indicator still s | nowing 103,000lbs. | |
| | 5:51 | Started slacking off a | gain and went 60,000 | bs down to 53,000lbs. Left weight |
| | | at 103,000lbs. | inute and no indication | n of shift. Picked back up to mark and still |
| | 5.50 | | ator and falt alaava ah | ift at 54,000lbs (59,000lbs down). |
| | 5:53 | | | ed up to 103,000lbs and made a mark. |
| | | Difforence in marke w | as 6.5", DV tool is close | ed up to 103,000lbs and made a mark. |
| | | Job Complete. | as 0.5, DV tool is clos | sea. |
| | | Job Complete. | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Contraction of the local division of the loc | | 1 | and the state of the second | |



Cementing Job Report



Received by OCD: 7/30/2021 4:06:08 PM



Cementing Service Report

| | | | | 1 | Cust | | Fran | nklin Mountain | | | Job | Number | 3193 | 093 |
|--|--|--|--|--|---|--|----------|--|---|--|--------------------------------------|---------|---------|---------------|
| Well Ribbon Federal C | Com 703H Blue | Ribbon Feder | al Com 703H | Location (legal) | 1&P 556 | | | Schlumberger | Location | | | Job St | | 24/2021 |
| Field | | | Formation Name | e/Type | Devi | ation | | Bit Size | | Well MD | | 1 | Well T | VD |
| | | | Dirt | y-Sandstone | | deg | | in | | 54 | 400.0 ft | | | 5391.0 ft |
| County | Lea | | State/Province | New Mexico | внр | | E | BHST | вно | т. | | Pore Pr | ess. Gr | adient |
| Well Master (| 065980858 | | API/UWI | | | psi | | 123 degF | | 107 deg | ιF | | | /gal |
| Rig Name | | Drilled For | | Service Via | | | | | Casing/I | iner | | | 1400 | |
| H& | Р | Oil | & Gas | Land | De | epth, ft | | Size, in | Weight, I | | 6 | Grade | T | Thread |
| Offshore Zone | | Well Class | | Well Type | | 5433.0 | - | 9.6 | 40 | | | N/A | - | N/A |
| | | | New | Development | | 0.0 | - | 0.0 | 0. | | | 11/6 | -+ | N/A |
| Drilling Fluid Typ | e | | Max. Density | Plastic Viscosity | - | | _ | | ubing/Drill | | | | - | |
| | Bentonite | | 10.00 lb/gal | A TELEVISE POOLS IN A MADE | T/D | Depth, ft | | Size, in | | t, Ib/ft | - | Grade | 1 | Thread |
| Service Line | | Job Type | | | | | | one cy m | Weight | 10/10 | | Grade | | Inread |
| Cemen | ting | | 9 5/8" Interr | nediate | | | | | | | | | | |
| Max. Allowed Tu | h Press | Max. Allowe | d Ann Droce | WH Connection | - | L | | | | | | | | |
| psi | | Flax. Allowe | psi | Single Cement head | | | | | prations/Op | | | | | |
| Service Instructi | | | | | ' | Top, ft | B | lottom, ft | shot/ | ft | No. of | Shots | Т | otal Interval |
| our rice instructi | 013 | | | | | ft | _ | ft | | | | | | ft |
| | | | | | | ft | | ft | | | | | 0 | Diameter |
| | | | | | | ft | | ft | | | | | | in |
| | | | | | Treat | Down | | Displacement | | Packer T | уре | | Packer | Depth |
| | | | | | | Casing | | bbl | | | | | | ft |
| | | | | | Tubir | ng Vol. | | Casing Vol. | | Annular | Vol. | | Openh | ole Vol. |
| | | | | | | bbl | | bbl | | | bbl | | | bbl |
| Casing/Tubing S | ecured | X 1 Hole | e Vol. Circulated p | rior to Cement | x | c | Casing T | ools | | | | Squeeze | Job | |
| Lift Pressure | | ps | ă. | | Shoe | Туре | | | Guide | Squeeze | Туре | | | |
| Pipe Rotated | | | | | | | | | | 1.2.1 | | | | |
| | | | Pipe Reciprocate | ed [| Shoe | Depth | | 54 | 33.0 ft | Tool Type | e | | | |
| No. Centralizers | | Top P | | Bottom Plugs | - | Depth Tool Type | | 54 | | Tool Type | - | | | |
| Cement Head Typ | | Top Pl | | | Stage | | | 54 | | | th | | | |
| Cement Head Typ Job Scheduled Fo | r | Arrived on Lo | lugs | | Stage | e Tool Type | | 54 | 33.0 ft | Tool Dep | th Size | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 | 14:00 | Arrived on Lo Jan/24/2 | ocation 2021 14:00 | Bottom Plugs | Stage Stage Collar | Tool Type | | | 33.0 ft ft | Tool Dep Tail Pipe | th Size Depth | | | |
| Cement Head Typ Job Scheduled Fo | r | Arrived on Lo | lugs pocation 2021 14:00 | Bottom Plugs | Stage Stage Collar | e Tool Type e Tool Depth r Type r Depth | v | | ft Float | Tool Dep Tail Pipe Tail Pipe | th Size Depth I Vol. | ssage | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 | r 14:00 Time 24-hr | Arrived on Lo Jan/24/2 Treati Press | lugs pocation 2021 14:00 | Bottom Plugs | Stage Stage Collar Collar Density | a Tool Type Tool Depth Type Depth | v | 53 /olume BBL | 133.0 ft ft Float 87.0 ft | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth I Vol. | ssage | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date | r 14:00 Time 24-hr clock | Arrived on Lo Jan/24/2 Treati Press | lugs cation 2021 14:00 ng ure II | Bottom Plugs Leave Location Jan/24/2021 Flow Rate B/M 0.0 | Stage Stage Collar Collar Density | e Tool Type e Tool Depth r Type r Depth 8.30 | v | 53 /olume BBL 0.0 | 33.0 ft ft Float 87.0 ft Started A | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth I Vol. | ssage | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 | Arrived on Lo Jan/24/2 Treati Press | 2021 14:00 | Bottom Plugs | Stage Stage Collar Collar Density | e Tool Type e Tool Depth r Type r Depth 8.30 8.30 | v | 53 /olume BBL 0.0 0.0 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 | Arrived on Lo Jan/24/2 Treati Press | Jugs cocation 2021 14:00 ng ure or -2 -2 -2 -2 12 | Воttom Plugs | Stage Stage Collar Collar Density | e Tool Type e Tool Depth r Type r Depth 8.30 8.30 8.30 | v | 53 /olume BBL 0.0 0.0 0.1 | 33.0 ft ft Float 87.0 ft Started A | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 | Arrived on Lo Jan/24/2 Treati Press | Jugs cocation 2021 14:00 ng ure -2 -2 -2 12 20 | Bottom Plugs Leave Location Jan/24/2021 Flow Rate B/M 0.0 0.0 2.2 2.5 | Stage Stage Collar Collar Density | e Tool Type Tool Depth Type T Depth 8.30 8.30 8.30 8.30 | v | 53 /olume BBL 0.0 0.0 0.1 0.5 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 | Arrived on Lo Jan/24/2 Treati Press | ugs cocation 2021 14:00 ng ure st -2 -2 -2 12 20 122 | Воttom Plugs | Stage Stage Collar Collar Density | e Tool Type Tool Depth Type Depth 8.30 8.30 8.30 8.30 8.30 8.30 | | 53 /olume BBL 0.0 0.0 0.1 0.5 2.8 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:03:18 17:04:08 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 12 20 122 58 | Воttom Plugs | Stage Stage Collar Collar Density | e Tool Type Tool Depth Type Depth 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 | | 53 /olume BBL 0.0 0.0 0.0 0.1 0.5 2.8 7.0 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:03:18 17:04:08 17:04:58 | Arrived on Lo Jan/24/2 Treati Press | -2 -2 -2 -2 20 12 58 55 | Воttom Plugs | Stage Stage Collar Collar Density | Tool Type Tool Depth r Type r Depth 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 | v | 53 /olume BBL 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:58 17:04:58 17:05:48 | Arrived on Lo Jan/24/2 Treati Press | -2 -2 -2 -2 12 20 122 58 55 730 | Воttom Plugs | Stage Stage Collar Collar Density | Tool Type Tool Depth r Type r Depth 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 | v | 53 /olume BBL 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:08 17:04:58 17:05:48 17:06:38 | Arrived on Lo Jan/24/2 Treati Press | Jugs cocation 2021 14:00 ng -2 -2 -2 12 20 122 58 55 730 1495 | Воttom Plugs | Stage Stage Collar Collar Density | Tool Type Tool Depth Type Toeth S.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 | v | 53 /olume BBL 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started An Start Job | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:03:18 17:04:08 17:04:58 17:05:48 17:05:48 17:06:38 17:07:28 | Arrived on Lo Jan/24/2 Treati Press | Jugs cocation 2021 14:00 ng -2 -2 -2 12 20 122 58 55 730 1495 4119 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 8.32 8.32 | v | 53 /olume BBL 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 | Tool Dep Tail Pipe Tail Pipe Sqz. Tota | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:19 17:02:28 17:03:18 17:04:08 17:04:58 17:05:48 17:05:48 17:06:38 17:07:28 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng ure -2 -2 -2 122 58 55 730 1495 4119 4526 | Bottom Plugs Leave Location Jan/24/2021 Flow Rate B/M 0.0 2.2 2.5 4.9 1.6 2.8 0.0 0.0 0.0 | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a S.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 | v | 53 /olume BBL 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Ad Start Job 5 bbls of 1 | Tool Dep Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:19 17:02:28 17:03:18 17:04:58 17:04:58 17:05:48 17:05:48 17:05:48 17:06:38 17:08:18 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 122 20 122 58 55 730 1495 4119 4526 4526 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a B.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 | • | 53 /olume 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 | Tool Dep Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:19 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:05:38 17:06:38 17:08:18 17:08:18 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 20 122 58 55 730 1495 4119 4526 4523 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a Saaa 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 | • | 53 /olume 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 10.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 | Tool Dep Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:06:36 17:07:28 17:09:28 17:09:08 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 122 55 730 1495 4119 4526 4526 4522 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth r B.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 | | 53 /olume 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota Sqz. Tota Coquisition Water to fi Water to fi Water to fi est Lines | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:05:48 17:06:36 17:09:28 17:09:23 17:09:58 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ing -2 -2 -2 12 20 122 55 730 1495 4119 4526 4523 4522 4522 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a Saaa 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 8.32 | | 53 /olume 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 10.3 10.3 10.3 10.3 10.3 10.3 | 33.0 ft ft Float 87.0 ft Started Ar Start Job 5 bbls of 1 5 bbls of 1 Pressure T Low Test= | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota Sqz. Tota Coquisition Water to fi Water to fi Water to fi est Lines | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:06:36 17:07:28 17:09:28 17:09:08 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 122 55 730 1495 4119 4526 4526 4522 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth r B.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 | | 53 /olume BBL 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 | 33.0 ft ft Float 87.0 ft Started Ar Start Job 5 bbls of 1 5 bbls of 1 Pressure T Low Test= | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota Sqz. Tota Coquisition Water to fi Water to fi Water to fi est Lines | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:05:48 17:06:36 17:09:28 17:09:23 17:09:58 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ing -2 -2 -2 12 20 122 55 730 1495 4119 4526 4523 4522 4522 | Воttom Plugs | Stage Stage Collar Collar Density | Tool Type Tool Depth Type Depth Saaa 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 | | 53 /olume BBL 0.0 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 | 33.0 ft ft Float 87.0 ft Started Ar Start Job 5 bbls of 1 5 bbls of 1 Pressure T Low Test= | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota Sqz. Tota Coquisition Water to fi Water to fi Water to fi est Lines | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:28 17:02:28 17:03:18 17:04:58 17:04:58 17:04:58 17:05:48 17:05:48 17:05:48 17:05:28 17:05:28 17:09:28 17:09:23 17:09:58 17:10:48 | Arrived on Lo Jan/24/2 Treati Press | Jugs cocation 2021 14:00 ng -2 -2 -2 12 20 122 58 55 730 1495 4119 4526 4523 4522 1 4522 1 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a S.30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 | | 53 /olume BBL 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10 | 33.0 ft ft Float 87.0 ft Started Ar Start Job 5 bbls of 1 5 bbls of 1 Pressure T Low Test= | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi est Lines 750 PSI CESS | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:19 17:02:28 17:03:18 17:04:58 17:04:58 17:04:58 17:05:48 17:05:48 17:06:30 17:09:28 17:09:08 17:09:58 17:10:48 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 122 20 122 55 730 1495 4119 4526 4523 4522 1 19 | Bottom Plugs Leave Location Jan/24/2021 Flow Rate B/M 0.0 2.2 2.5 4.9 1.6 2.8 0.0 | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type r Depth a Sa30 8.30 8.30 8.30 8.30 8.30 8.30 8.30 8.32 | | 53 /olume 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 1 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 Pressure 1 Low Test= Test= Suc | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi est Lines 750 PSI CESS | th Size Depth al Vol. Me | | | |
| Cement Head Typ Job Scheduled Fo Jan/24/2021 Date 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 01/24/2021 | r 14:00 Time 24-hr clock 17:01:38 17:01:39 17:02:19 17:02:19 17:02:28 17:03:18 17:04:08 17:04:08 17:04:58 17:05:48 17:05:48 17:06:38 17:08:22 17:09:08 17:09:23 17:09:58 17:10:48 17:11:38 17:11:38 | Arrived on Lo Jan/24/2 Treati Press | Jugs coation 2021 14:00 ng -2 -2 -2 122 55 730 1495 4119 4526 4523 4522 1 19 18 | Воttom Plugs | Stage Stage Collar Collar Density | a Tool Type a Tool Depth r Type a Depth a Depth a Depth a Depth a B.30 B.30 B.30 B.30 B.32 B.32 | | 53 /olume 0.0 0.0 0.1 0.5 2.8 7.0 9.3 10.3 1 | 33.0 ft ft Float 87.0 ft Started Au Start Job 5 bbls of 1 Pressure 1 Low Test= Test= Suc | Tool Dep/ Tail Pipe Tail Pipe Sqz. Tota cquisition Water to fi est Lines 750 PSI CESS | th Size Depth al Vol. Me | | | |

3lue

| ell ederal Com 70 | 3H Blue Ribbon Fe | ederal Com 703F | u | Job Start Jan/24/2021 | Customer Frankl | in Mountain | 300 Number 3193093 |
|----------------------|------------------------|-----------------------------|---------------------|--------------------------|--------------------|--------------------|-----------------------|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message |
| 01/24/2021 | 17:15:48 | 19 | 0.0 | 8.32 | 10.3 | | |
| 01/24/2021 | 17:16:38 | 18 | 0.0 | 8.32 | 10.3 | | |
| 01/24/2021 | 17:17:28 | 18 | 0.3 | 8.54 | 10.3 | | |
| 01/24/2021 | 17:18:13 | 18 | 0.0 | 11.72 | 10.4 | Start Pumping S | pacer |
| 01/24/2021 | 17:18:18 | 18 | 0.0 | 11.85 | 10.4 | | |
| 01/24/2021 | 17:18:22 | 29 | 0.7 | 11.94 | 10.4 | 30 bbls of MPE | 12.5 PPG |
| 01/24/2021 | 17:19:08 | 63 | 1.9 | 12.35 | 11.9 | | |
| 01/24/2021 | 17:19:58 | 65 | 1.8 | 12.43 | 13.5 | | |
| 01/24/2021 | 17:20:48 | 65 | 1.8 | 12.45 | 15.0 | | |
| 01/24/2021 | 17:21:38 | 64 | 1.9 | 12.44 | 16.5 | | |
| 01/24/2021 | 17:22:28 | 66 | 2.0 | 12.46 | 18.1 | | |
| 01/24/2021 | 17:23:18 | 77 | 2.3 | 12.44 | 20.0 | | |
| 01/24/2021 | 17:24:08 | 72 | 2.5 | 12.44 | 22.0 | | |
| 01/24/2021 | 17:24:58 | 70 | 2.5 | 12.39 | 24.1 | | |
| 01/24/2021 | 17:25:48 | 64 | 2.4 | 12.38 | 26.1 | | |
| 01/24/2021 | 17:26:38 | 63 | 2.5 | 12.37 | 28.1 | | |
| 01/24/2021 | 17:27:28 | 82 | 3.2 | 12.35 | 30.4 | | |
| 01/24/2021 | 17:28:18 | 84 | 3.3 | 12.35 | 33.1 | | |
| 01/24/2021 | 17:29:08 | 35 | 1.2 | 12.38 | 33.8 | | |
| 01/24/2021 | 17:29:58 | 60 | 2.0 | 12.34 | 34.4 | | |
| 01/24/2021 | 17:30:48 | 83 | 3.4 | 12.31 | 37.3 | | |
| 01/24/2021 | 17:31:38 | 29 | 1.0 | 12.34 | 38.7 | | |
| 01/24/2021 | 17:32:28 | 22 | 0.2 | 12.35 | 39.4 | | |
| 01/24/2021 | 17:33:18 | 22 | 0.4 | 12.35 | 39.6 | | |
| 01/24/2021 | 17:33:49 | 29 | 1.1 | 12.67 | 40.0 | End Spacer | |
| 01/24/2021 | 17:34:08 | 30 | 1.1 | 13.42 | 40.3 | | |
| 01/24/2021 | 17:34:58 | 60 | 1.9 | 14.16 | 41.7 | | |
| 01/24/2021 | 17:35:48 | 60 | 1.9 | 14.48 | 43.2 | | |
| 01/24/2021 | 17:35:54 | 84 | 2.2 | 14.57 | 43.4 | Start Cement Slu | ITTY |
| 01/24/2021 | 17:35:56 | 92 | 2.2 | 14.59 | 43.5 | Bring to Weight | |
| 01/24/2021 | 17:35:57 | 90 | 2.2 | 14.60 | 43.5 | Verified Mud Scale | es |
| 01/24/2021 | 17:36:38 | 219 | 4.6 | 14.64 | 45.8 | | |
| 01/24/2021 | 17:37:28 | 332 | 5.1 | 14.72 | 49.5 | | |
| 01/24/2021 | 17:38:18 | 207 | 5.1 | 14.78 | 53.9 | | |
| 01/24/2021 | 17:39:08 | 198 | 5.1 | 14.79 | 58.2 | | |
| 01/24/2021 | 17:39:58 | 137 | 5.1 | 14.88 | 62.5 | | |
| 01/24/2021 | 17:40:48 | 237 | 5.2 | 14.88 | 66.8 | | |
| 01/24/2021 | 17:41:38 | 231 | 5.2 | 14.81 | 71.1 | | |
| 01/24/2021 | 17:42:28 | 231 | 5.2 | 14.80 | 75.4 | | |
| 01/24/2021 | 17:43:18 | 246 | 5.2 | 14.77 | 79.6 | | |
| 01/24/2021 | 17:44:08 | 259 | 5.2 | 14.81 | 84.0 | | |
| 01/24/2021 | 17:44:58 | 266 | 5.2 | 14.86 | 88.4 | | |
| 01/24/2021 | 17:45:48 | 259 | 5.2 | 14.87 | 92.7 | | |
| 01/24/2021 | 17:46:38 | 254 | 5.2 | 14.89 | 97.0 | | |
| 01/24/2021 | 17:47:28 | 264 | 5.2 | 14.90 | 101.3 | | |
| 01/24/2021 | 17:48:18 | 271 | 5.2 | 14.88 | 105.7 | | |
| 01/24/2021 | 17:49:08 | 257 | 5.3 | 14.88 | 110.0 | | |
| 01/24/2021 | 17:49:58 | 232 | 5.2 | 14.84 | 114.4 | | |
| 01/24/2021 | 17:50:48 | 225 | 5.2 | 14.83 | 118.8 | | |
| 01/24/2021 | 17:51:38 | 243 | 5.2 | 14.80 | 123.1 | | |
| 01/24/2021 | 17:52:28 | 262 | 5.2 | 14.77 | 127.5 | | |
| 01/24/2021 | 17:53:18 | 248 | 5.2 | 14.78 | 131.9 | | |
| 01/24/2021 | 17:54:08 | 237 | 5.2 | 14.80 | 136.3 | | |
| 01/24/2021 | 17:54:58 | 244 | ++ | 14.80 | 140.6 | | |

| well on Federal Com 70 | 3H Blue Ribbon Fe | ederal Com 703F | | Job Start Jan/24/2021 | Customer Frankl | n Mountain | Job Number 3193093 |
|---------------------------|------------------------|-----------------------------|---------------------|--------------------------|--------------------|-------------------|-----------------------|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message |
| 01/24/2021 | 17:56:38 | 233 | 5.2 | 14.87 | 149.4 | | |
| 01/24/2021 | 17:57:28 | 221 | 5.2 | 14.88 | 153.7 | | |
| 01/24/2021 | 17:58:18 | 186 | 5.2 | 14.83 | 158.1 | | |
| 01/24/2021 | 17:59:08 | 234 | 5.2 | 14.75 | 162.5 | | |
| 01/24/2021 | 17:59:58 | 219 | 5.2 | 14.74 | 166.9 | | |
| 01/24/2021 | 18:00:48 | 240 | 5.2 | 14.77 | 171.2 | | |
| 01/24/2021 | 18:01:38 | 168 | 4.6 | 14.80 | 175.5 | | |
| 01/24/2021 | 18:02:28 | 159 | 4.6 | 14.80 | 179.2 | | |
| 01/24/2021 | 18:03:18 | 147 | 4.5 | 14.81 | 183.0 | - | |
| 01/24/2021 | 18:04:08 | 153 | 4.5 | 14.79 | 186.8 | | |
| 01/24/2021 | 18:04:58 | 181 | 4.6 | 14.80 | 190.6 | | |
| 01/24/2021 | 18:05:48 | 179 | 4.6 | 14.73 | 194.4 | | |
| 01/24/2021 | 18:06:38 | 201 | 4.5 | 14.90 | 198.2 | | |
| 01/24/2021 | 18:07:28 | 173 | 4.6 | 14.78 | 202.0 | | |
| 01/24/2021 | 18:07:33 | 178 | 4.4 | 14.78 | 202.3 | End Cement Slun | γ |
| 01/24/2021 | 18:08:18 | 11 | 0.0 | 14.95 | 202.6 | | |
| 01/24/2021 | 18:09:08 | 13 | 0.2 | 12.25 | 202.6 | | |
| 01/24/2021 | 18:09:58 | 12 | 0.6 | 11.52 | 203.0 | | |
| 01/24/2021 | 18:10:48 | 18 | 0.0 | 10.18 | 203.5 | | |
| 01/24/2021 | 18:11:38 | 18 | 0.0 | 9.68 | 203.5 | | |
| 01/24/2021 | 18:13:18 | 17 | 0.0 | 9.41 | 203.5 | | |
| 01/24/2021 | 18:14:05 | 63 | 2.6 | 8.92 | 204.2 | Drop Top Plug | |
| 01/24/2021 | 18:14:08 | 65 | 2.8 | 9.18 | 204.4 | | |
| 01/24/2021 | 18:14:28 | 92 | 3.9 | 10.13 | 205.3 | Start Displaceme | nt |
| 01/24/2021 | 18:14:30 | 85 | 3.9 | 10.11 | 205.5 | 408 bbls of Water | • |
| 01/24/2021 | 18:14:58 | 102 | 5.2 | 9.64 | 207.6 | | |
| 01/24/2021 | 18:15:48 | 178 | 5.2 | 8.58 | 212.0 | | |
| 01/24/2021 | 18:16:30 | 107 | 5.2 | 8.33 | 215.6 | Checked fuel and | oil levels |
| 01/24/2021 | 18:16:38 | 125 | 5.2 | 8.33 | 216.3 | | |
| 01/24/2021 | 18:17:28 | 139 | 5.4 | 9.87 | 220.7 | | |
| 01/24/2021 | 18:18:18 | 173 | 6.6 | 8.11 | 226.4 | | |
| 01/24/2021 | 18:19:08 | 86 | 7.1 | 10.31 | 232.0 | | |
| 01/24/2021 | 18:19:58 | 34 | 0.0 | 10.44 | 236.7 | | |
| 01/24/2021 | 18:20:48 | 69 | 6.5 | 9.41 | 240.6 | | |
| 01/24/2021 | 18:21:38 | 148 | 6.6 | 8.32 | 245.6 | | |
| 01/24/2021 | 18:22:28 | 103 | 5.4 | 8.32 | 250.2 | | |
| 01/24/2021 | 18:23:18 | 93 | 0.0 | 8.33 | 250.9 | | |
| 01/24/2021 | 18:24:08 | 111 | 5.3 | 8.32 | 254.1 | | |
| 01/24/2021 | 18:24:58 | 103 | 5.3 | 8.32 | 258.6 | | |
| 01/24/2021 | 18:25:48 | 115 | 5.3 | 11.55 | 263.0 | | |
| 01/24/2021 | 18:26:38 | 96 | 5.3 | 8.32 | 267.4 | | |
| 01/24/2021 | 18:27:28 | 116 | 5.7 | 8.32 | 272.0 | | |
| 01/24/2021 | 18:28:18 | 102 | 5.7 | 8.32 | 276.7 | | |
| 01/24/2021 | 18:29:08 | 114 | 5.6 | 8.32 | 281.4 | | |
| 01/24/2021 | 18:29:58 | 125 | 5.7 | 8.32 | 286.1 | | |
| 01/24/2021 | 18:30:48 | 115 | 5.6 | 8.32 | 290.9 | | |
| 01/24/2021 | 18:31:38 | 124 | 5.7 | 8.32 | 295.6 | | |
| 01/24/2021 | 18:32:28 | 106 | 5.7 | 8.32 | 300.3 | | |
| 01/24/2021 | 18:33:18 | 123 | 5.7 | 8.32 | 305.0 | | |
| 01/24/2021 | 18:34:08 | 108 | 5.1 | 8.32 | 309.3 | | |
| 01/24/2021 | 18:34:58 | 96 | 5.1 | 8.32 | 313.6 | | |
| 01/24/2021 | 18:35:48 | 109 | 5.1 | 8.32 | 317.9 | | |
| 01/24/2021 | 18:36:38 | 107 | 5.1 | 8.32 | 322.2 | | |

| well on Federal Com 70: | 3H Blue Ribbon Fe | ederal Com 703F | | Job Start Jan/24/2021 | Franklin Mountai | n 3193093 |
|----------------------------|----------------------|-------------------|--------------|--------------------------|------------------|-----------|
| Date | Time 24-hr | Treating Pressure | Flow Rate | Density LB/G | Volume BBL | Message |
| | clock | PSI | B/M | | | |
| 01/24/2021 | 18:39:08 | 93 | 5.1 | 8.32 | 335.0 | |
| 01/24/2021 | 18:39:58 | 91 | 5.1 | 8.32 | 339.3 | |
| 01/24/2021 | 18:40:48 | 89 | 5.2 | 8.32 | 343.6 | |
| 01/24/2021 | 18:41:38 | 90 | 5.1 | 8.32 | 347.9 | |
| 01/24/2021 | 18:42:28 | 86 | 5.1 | 8.32 | 352.2 | |
| 01/24/2021 | 18:43:18 | 90 | 5.1 | 8.32 | 356.5 | |
| 01/24/2021 | 18:44:08 | 102 | 5.1 | 8.32 | 360.8 | |
| 01/24/2021 | 18:44:58 | 100 | 5.1 | 8.32 | 365.0 | |
| 01/24/2021 | 18:45:48 | 91 | 5.1 | 8.32 | 369.3 | |
| 01/24/2021 | 18:46:38 | 103 | 5.1 | 8.32 | 373.6 | |
| 01/24/2021 | 18:47:28 | 101 | 5.1 | 8.32 | 377.9 | |
| 01/24/2021 | 18:48:18 | 86 | 5.1 | 8.32 | 382.1 | |
| 01/24/2021 | 18:49:08 | 103 | 5.1 | 8.33 | 386.4 | |
| 01/24/2021 | 18:49:58 | 93 | 5.1 | 8.32 | 390.7 | |
| 01/24/2021 | 18:50:48 | 84 | 5.1 | 8.32 | 395.0 | |
| 01/24/2021 | 18:51:38 | 96 | 5.1 | 8.33 | 399.2 | |
| 01/24/2021 | 18:52:28 | 98 | 5.1 | 8.32 | 403.4 | |
| 01/24/2021 | 18:53:18 | 87 | 5.1 | 8.32 | 407.8 | |
| 01/24/2021 | 18:54:08 | 98 | 5.1 | 8.32 | 412.1 | |
| 01/24/2021 | 18:54:58 | 109 | 5.2 | 8.32 | 416.3 | |
| 01/24/2021 | 18:55:48 | 105 | 5.1 | 8.32 | 420.6 | |
| 01/24/2021 | 18:56:38 | 101 | 5.1 | 8.32 | 424.9 | |
| 01/24/2021 | 18:57:28 | 101 | 5.2 | 8.32 | 429.2 | |
| 01/24/2021 | 18:58:18 | 103 | 5.1 | 8.32 | 433.5 | |
| 01/24/2021 | 18:59:08 | 87 | 5.1 | 8.32 | 437.7 | |
| 01/24/2021 | 18:59:58 | 106 | 5.2 | 8.32 | 442.0 | |
| 01/24/2021 | 19:00:48 | 89 | 5.1 | 8.32 | 446.3 | |
| 01/24/2021 | 19:01:38 | 113 | 5.2 | 8.32 | 450.6 | |
| 01/24/2021 | 19:02:28 | 98 | 5.2 | 8.32 | 454.9 | |
| 01/24/2021 | 19:03:18 | 137 | . 5.2 | 8.32 | 459.3 | |
| 01/24/2021 | 19:04:08 | 163 | 5.2 | 8.32 | 463.6 | |
| 01/24/2021 | 19:04:58 19:05:48 | 197 | 5.2 | 8.32 | 467.8 472.1 | |
| 01/24/2021 | 19:06:38 | 269 | | | | |
| 01/24/2021 | 19:07:28 | 259 | 5.1 | 8.32 | 476.4 | |
| 01/24/2021 | 19:08:18 | 298 | 5.1 | 8.32 | 485.0 | |
| 01/24/2021 | 19:09:08 | 266 | 4.1 | 8.32 | 488.8 | |
| 01/24/2021 | 19:09:58 | 302 | 4.1 | 8.32 | 492.2 | |
| 01/24/2021 | 19:10:48 | 327 | 4.1 | 8.32 | 495.6 | |
| 01/24/2021 | 19:11:38 | 339 | 4.1 | 8.32 | 499.1 | |
| 01/24/2021 | 19:12:28 | 394 | 4.1 | 8.32 | 502.5 | |
| 01/24/2021 | 19:13:18 | 399 | 4.1 | 8.32 | 505.9 | |
| 01/24/2021 | 19:14:08 | 429 | 4.1 | 8.32 | 509.4 | |
| 01/24/2021 | 19:14:58 | 460 | 4.1 | 8.32 | 512.8 | |
| 01/24/2021 | 19:15:48 | 470 | 4.1 | 8.32 | 516.2 | |
| 01/24/2021 | 19:16:38 | 506 | 4.1 | 8.32 | 519.6 | |
| 01/24/2021 | 19:17:28 | 516 | 4.1 | 8.32 | 523.1 | |
| 01/24/2021 | 19:18:18 | 536 | 4.1 | 8.32 | 526.5 | |
| 01/24/2021 | 19:19:08 | 575 | 4.1 | 8.32 | 529.9 | |
| 01/24/2021 | 19:19:58 | 583 | 4.1 | 8.32 | 533.4 | |
| 01/24/2021 | 19:20:48 | 617 | 4.1 | 8.32 | 536.8 | |
| | | | | | | |
| 01/24/2021 | 19:21:38 | 639 | 4.1 | 8.32 | 540.1 | |

Released to Imaging: 8/2/2021 1:57:35 PM

3lue

| ederal Com 70 | 3H Blue Ribbon Fe | ederal Com 703F | ••• | Job Start Jan/24/2021 | Customer Frankl | in Mountain | Job Number 3193093 |
|---------------|------------------------|-----------------------------|---------------------|--------------------------|--------------------|----------------------|-----------------------|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message |
| 01/24/2021 | 19:24:58 | 733 | 4.1 | 8.32 | 553.9 | | |
| 01/24/2021 | 19:25:48 | 745 | 4.1 | 8.32 | 557.3 | | |
| 01/24/2021 | 19:26:38 | 761 | 4.1 | 8.32 | 560.7 | | |
| 01/24/2021 | 19:27:28 | 768 | 4.1 | 8.32 | 564.1 | | |
| 01/24/2021 | 19:28:18 | 799 | 4.1 | 8.32 | 567.6 | 4 | |
| 01/24/2021 | 19:29:08 | 820 | 4.1 | 8.32 | 571.0 | | |
| 01/24/2021 | 19:29:58 | 825 | 4.1 | 8.32 | 574.4 | | |
| 01/24/2021 | 19:30:48 | 846 | 4.1 | 8.32 | 577.8 | | |
| 01/24/2021 | 19:31:38 | 843 | 4.1 | 8.32 | 581.2 | | |
| 01/24/2021 | 19:32:28 | 867 | 4.1 | 8.32 | 584.6 | | |
| 01/24/2021 | 19:33:18 | 874 | 4.1 | 8.32 | 588.1 | | |
| 01/24/2021 | 19:34:08 | 880 | 4.1 | 8.32 | 591.5 | | |
| 01/24/2021 | 19:34:58 | 917 | 4.1 | 8.32 | 594.9 | | |
| 01/24/2021 | 19:35:48 | 910 | 4.1 | 8.32 | 598.3 | | |
| 01/24/2021 | 19:36:38 | 936 | 4.1 | 8.32 | 601.7 | | |
| 01/24/2021 | 19:37:28 | 946 | 4.1 | 8.32 | 605.1 | | |
| 01/24/2021 | 19:38:18 | 956 | 4.1 | 8.32 | 608.5 | | |
| 01/24/2021 | 19:39:08 | 990 | 4.1 | 8.32 | 611.9 | | |
| 01/24/2021 | 19:39:58 | 993 | 4.1 | 8.32 | 615.4 | | |
| 01/24/2021 | 19:40:48 | 1024 | 4 4.1 | 8.32 | 618.8 | | |
| 01/24/2021 | 19:41:38 | 101 | 9 4.1 | 8.32 | 622.2 | | |
| 01/24/2021 | 19:42:28 | 103 | 7 4.1 | 8.32 | 625.6 | | |
| 01/24/2021 | 19:43:18 | 104- | 4 4.1 | 8.32 | 629.0 | | |
| 01/24/2021 | 19:44:08 | 107 | 5 4.1 | 8.32 | 632.4 | | |
| 01/24/2021 | 19:44:58 | 1076 | 5 4.1 | 8.32 | 635.8 | | |
| 01/24/2021 | 19:45:48 | 107: | 4.1 | 8.32 | 639.2 | | |
| 01/24/2021 | 19:46:38 | 1099 | 4.1 | 8.32 | 642.6 | | |
| 01/24/2021 | 19:47:03 | 173: | 0.3 | 8.32 | 644.1 | Bump Top Plug | |
| 01/24/2021 | 19:47:06 | 1765 | 5 0.0 | 8.32 | 644.1 | Bumped at 1750 PS | SI |
| 01/24/2021 | 19:47:07 | 1774 | 0.0 | 8.32 | 644.1 | Hold for a couple of | Minutes |
| 01/24/2021 | 19:47:28 | 1768 | 0.0 | 8.32 | 644.1 | | |
| 01/24/2021 | 19:48:18 | 1752 | 2 0.0 | 8.32 | 644.1 | | |
| 01/24/2021 | 19:49:08 | 1752 | 0.0 | 6.32 | 644.1 | | |
| 01/24/2021 | 19:49:58 | 1754 | 0.0 | 8.32 | 644.1 | | |
| 01/24/2021 | 19:51:22 | 2142 | 0.2 | 8.32 | 644.9 | Pressure up to 2147 | 7 PSI |
| 01/24/2021 | 19:51:38 | 2140 | 0.0 | 8.32 | 644.9 | | |
| 01/24/2021 | 19:52:28 | 2209 | 1.2 | 8.32 | 645.0 | | |
| 01/24/2021 | 19:52:55 | 2438 | 0.0 | 8.32 | 645.5 | Pressure up to 2439 | 9 PSI |
| 01/24/2021 | 19:53:18 | 2463 | 1.2 | 8.32 | 645.6 | | |
| 01/24/2021 | 19:53:46 | 2699 | 0.0 | 8.32 | 646.0 | Pressure up to 2705 | 5 PSI |
| 01/24/2021 | 19:54:08 | 2704 | 0.0 | 8.32 | 646.0 | | |
| 01/24/2021 | 19:54:47 | 2955 | 0.0 | 8.32 | 646.5 | Pressure up to 2959 | PSI |
| 01/24/2021 | 19:54:58 | 2954 | 0.0 | 8.32 | 646.5 | | |
| 01/24/2021 | 19:55:48 | 3086 | 1.3 | 8.32 | 646.8 | | |
| 01/24/2021 | 19:56:03 | 3164 | 0.3 | 8.32 | 647.1 | Pressure up to 3150 |) PSI |
| 01/24/2021 | 19:56:33 | 3051 | 0.0 | 8.32 | 647.1 | Pressured down to 3 | 3056 PSI |
| 01/24/2021 | 19:56:38 | 3051 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 19:57:28 | 3049 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 19:58:18 | 2624 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 19:59:08 | 2166 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 19:59:26 | 2148 | 0.0 | 8.32 | 647.1 | Bled down to 2146 | PSI |
| 01/24/2021 | 19:59:58 | 2144 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 20:00:48 | 2146 | 0.0 | 8.32 | 647.1 | | |
| 01/24/2021 | 20:01:38 | 2147 | 0.0 | 8.32 | 647.1 | | |

3lue

| ederal Com 703 | 3H Blue Ribbon Fe | ederal Com 703F | | Jan/24/2021 | Frank | in Mountain | 3193093 |
|----------------|------------------------|-----------------------------|---------------------|-----------------|---------------|------------------|--|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message |
| 01/24/2021 | 20:03:08 | 3855 | 0.7 | 8.32 | 650.0 | Pressure up to 3 | 855 PSI |
| 01/24/2021 | 20:03:18 | 3850 | 0.0 | 8.32 | 650.0 | | |
| 01/24/2021 | 20:03:28 | 3817 | 0.0 | 8.32 | 650.0 | Pressure came d | own to 3823 PSI |
| 01/24/2021 | 20:04:08 | 3820 | 0.0 | 8.32 | 650.0 | | |
| 01/24/2021 | 20:04:58 | 3819 | 0.0 | 8.32 | 650.0 | | |
| 01/24/2021 | 20:05:48 | 3813 | 0.0 | 8.32 | 650.0 | | |
| 01/24/2021 | 20:06:38 | 2810 | 0.0 | 8.32 | 650.0 | - | |
| 01/24/2021 | 20:07:07 | 1443 | 0.0 | 8.32 | 650.0 | Bled off | |
| 01/24/2021 | 20:07:28 | 199 | 0.0 | 8.32 | 650.0 | Dica on | |
| 01/24/2021 | 20:08:18 | -2 | 0.0 | 8.32 | 650.0 | 1 | |
| 01/24/2021 | 20:39:08 | -0 | 0.0 | 8.32 | 650.0 | | |
| 01/24/2021 | 20:39:58 | 88 | 0.0 | 8.32 | 650.0 | | and the second second second second second |
| 01/24/2021 | 20:40:48 | 159 | 1.3 | 8.31 | 650.6 | | |
| 01/24/2021 | 20:41:38 | 693 | 1.2 | 8.31 | 651.7 | | |
| 01/24/2021 | 20:42:28 | 1018 | 1.3 | 8.32 | 652.7 | | |
| 01/24/2021 | 20:43:18 | 1136 | 0.0 | 8.32 | 653.7 | | |
| 01/24/2021 | 20:44:08 | 949 | 0.0 | 8.32 | 653.7 | | |
| 01/24/2021 | 20:44:58 | 901 | 0.0 | 8.32 | 653.7 | | |
| 01/24/2021 | 20:45:48 | -2 | 0.0 | 8.32 | 653.7 | 1 | |
| 01/24/2021 | 20:46:38 | -1 | 0.0 | 8.32 | 653.7 | | |
| 01/24/2021 | 20:47:28 | 12 | 0.8 | 8.32 | 653.7 | | |
| 01/24/2021 | 20:48:18 | 754 | 2.1 | 8.32 | 655.3 | | |
| 01/24/2021 | 20:49:08 | 1413 | 2.1 | 8.31 | 657.0 | | |
| 01/24/2021 | 20:49:34 | 1362 | 0.0 | 8.32 | 657.7 | Opened at 1511 | DC1 |
| 01/24/2021 | 20:49:58 | 1126 | 0.0 | 8.32 | 657.7 | Opened at 1511 | 101 |
| 01/24/2021 | 20:50:48 | 296 | 0.0 | 8.32 | 657.7 | | |
| 01/24/2021 | 20:51:38 | 2 | 0.0 | 8.32 | 657.9 | | |
| 01/24/2021 | 20:52:28 | 91 | 2.2 | 8.32 | 658.2 | | |
| 01/24/2021 | 20:53:18 | 1045 | 2.1 | 8.32 | 660.0 | | |
| 01/24/2021 | 20:54:08 | 1468 | 2.2 | 9.32 | 661.8 | | |
| 01/24/2021 | 20:54:58 | 1508 | 2.1 | 8.32 | 663.6 | | |
| 01/24/2021 | 20:55:48 | 1074 | 0.0 | 8.32 | 664.3 | | |
| 01/24/2021 | 20:56:38 | 958 | 0.0 | 8.32 | 664.3 | | |
| 01/24/2021 | 20:57:28 | 924 | 0.0 | 8.32 | 664.3 | | |
| 01/24/2021 | 20:58:18 | 902 | 0.0 | 8.32 | 664.3 | | |
| 01/24/2021 | 20:59:08 | 488 | 0.0 | 8.32 | 664.3 | | |
| 01/24/2021 | 21:00:48 | 13 | 1.5 | 8.32 | 664.3 | | |
| 01/24/2021 | 21:01:38 | 1554 | 4.2 | 8.32 | 667.5 | | |
| 01/24/2021 | 21:02:28 | 1841 | 4.2 | 8.32 | 671.0 | | |
| 01/24/2021 | 21:03:18 | 1758 | 4.1 | 8.32 | 674.4 | | |
| 01/24/2021 | 21:04:08 | 1090 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:04:12 | 1037 | 0.0 | 8.32 | 676.6 | Remark | |
| 01/24/2021 | 21:04:58 | -4 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:05:48 | -1 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:06:38 | 0 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:07:28 | 2 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:08:18 | 2 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:09:08 | 2 | 0.0 | 8.32 | 676.6 | | |
| 01/24/2021 | 21:09:58 | 56 | 2.5 | 8.32 | 676.7 | | |
| 01/24/2021 | 21:10:48 | 1826 | 5.4 | 8.32 | 680.0 | | |
| 01/24/2021 | 21:11:38 | 1175 | 0.0 | 8.32 | 681.5 | | |
| 01/24/2021 | 21:12:28 | 912 | 0.7 | 8.32 | 681.5 | | |
| | | 2183 | 5.2 | 8.32 | | | the second s |

| well on Federal Com 70 | 3H Blue Ribbon Fe | ederal Com 703H | | Job Start Jan/24/2021 | Customer Franklin | Mountain | Job Number 3193093 |
|---------------------------|------------------------|-----------------------------|---------------------|--------------------------|----------------------|--------------------|-----------------------|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Mescage |
| 01/24/2021 | 21:15:48 | 1748 | 5.2 | 8.32 | 698.3 | | |
| 01/24/2021 | 21:16:38 | 1723 | 5.2 | 8.32 | 702.7 | | |
| 01/24/2021 | 21:17:28 | 904 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:18:18 | 287 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:19:08 | -3 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:19:58 | -3 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:20:48 | -2 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:21:38 | -2 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:22:28 | -3 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:23:18 | -3 | 0.0 | 8.32 | 705.1 | | |
| 01/24/2021 | 21:35:48 | 51 | 1.7 | 8.32 | 705.2 | | |
| 01/24/2021 | 21:36:38 | 1456 | 5.4 | 8.32 | 708.5 | | |
| 01/24/2021 | 21:37:28 | 1683 | 4.9 | 8.32 | 712.8 | | |
| 01/24/2021 | 21:38:18 | 1681 | 4.9 | 8.32 | 716.9 | | |
| 01/24/2021 | 21:39:08 | 1685 | 5.0 | 8.32 | 721.0 | | |
| 01/24/2021 | 21:39:58 | 1706 | 5.0 | 8.32 | 725.2 | | |
| 01/24/2021 | 21:40:48 | 1720 | 5.0 | 8.32 | 729.5 | | |
| 01/24/2021 | 21:41:38 | 1660 | 5.1 | 8.32 | 733.7 | | |
| 01/24/2021 | 21:42:28 | 1640 | 5.1 | 8.32 | 737.9 | | |
| 01/24/2021 | 21:43:18 | 1647 | 5.1 | 8.32 | 742.1 | | |
| 01/24/2021 | 21:44:08 | 1679 | 5.1 | 8.32 | 746.3 | | |
| 01/24/2021 | 21:44:58 | 1607 | 5.1 | 8.32 | 750.5 | | |
| 01/24/2021 | 21:45:48 | 1624 | 5.1 | 8.32 | 754.8 | | |
| 01/24/2021 | 21:46:38 | 1645 | 5.0 | 8.32 | 759.0 | | |
| 01/24/2021 | 21:47:28 | 1624 | 5.0 | 8.32 | 763.2 | | |
| 01/24/2021 | 21:48:18 | 1647 | 5.0 | 8.32 | 767.4 | | |
| 01/24/2021 | 21:49:58 | 1637 | 5.0 | 8.32 | 775.9 | | |
| 01/24/2021 | 21:50:48 | 980 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:51:05 | 813 | 0.0 | 8.32 | 779.0 | Start second Stage | 3 |
| 01/24/2021 | 21:51:38 | 799 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:52:28 | 786 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:53:18 | 775 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:54:08 | 768 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:54:58 | 760 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:55:48 | 754 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:56:38 | 747 | 0.0 | 8.32 | 779.0 | | |
| 01/24/2021 | 21:57:28 | 741 | 0.0 | 8.33 | 779.0 | | |
| 01/24/2021 | 21:58:18 | 735 | 0.0 | 8.33 | 779.0 | | |
| 01/24/2021 | 21:59:08 | 729 | 0.0 | 8.34 | 779.0 | | |
| 01/24/2021 | 21:59:58 | 724 | 0.0 | 8.33 | 779.0 | | |
| 01/24/2021 | 22:00:48 | 718 | 0.1 | 9.51 | 779.1 | | |
| 01/24/2021 | 22:01:38 | 714 | 0.0 | 10.45 | 779.2 | | |
| 01/24/2021 | 22:02:28 | 708 | 0.0 | 10.61 | 779.2 | | |
| 01/24/2021 | 22:03:18 | 703 | 0.0 | 10.61 | 779.2 | | |
| 01/24/2021 | 22:04:08 | 698 | 0.0 | 10.48 | 779.2 | | |
| 01/24/2021 | 22:04:58 | 692 | 0.0 | 10.58 | 779.2 | | |
| 01/24/2021 | 22:05:48 | 687 | 0.0 | 10.71 | 779.2 | | |
| 01/24/2021 | 22:06:38 | 683 | 0.0 | 10.81 | 779.2 | | |
| 01/24/2021 | 22:07:28 | 678 | 0.0 | 10.88 | 779.2 | Start Duranian Con | |
| 01/24/2021 | 22:08:08 | 686 | 0.4 | 11.95 | 779.3 | Start Pumping Spa | |
| 01/24/2021 | 22:08:12 | 676 | 0.3 | 12.07 | 779.3 | 30 bbls of Mudpus | n @ 12.5 PPG |
| 01/24/2021 | 22:08:18 | 684 | 0.0 | 12.15 | 779.4 | 1 | |

| Well on Federal Com 70 |)3H Blue Ribbon F | ederal Com 703H | ld | Job Start Jan/24/202 | Customer 1 Frankli | n Mountain | Job Number 3193093 | | |
|---------------------------|------------------------|-----------------------------|---------------------|-------------------------|-----------------------|-------------------|-----------------------|--|--|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message | | |
| | | | | | | | | | |
| 01/24/2021 | 22:10:48 | 57 | 5 0.5 | 12.24 | 779.8 | | | | |
| 01/24/2021 | 22:11:38 | 66 | 7 0.0 | 12.12 | 780.1 | | | | |
| 01/24/2021 | 22:12:28 | 78 | 6 0.9 | 12.13 | 780.1 | | | | |
| 01/24/2021 | 22:13:18 | 91 | 9 0.7 | 12.13 | 781.8 | | | | |
| 01/24/2021 | 22:14:08 | 79 | 3 2.7 | 12.22 | 781.9 | | | | |
| 01/24/2021 | 22:14:58 | 134 | 40 4.1 | 12.17 | 785.2 | | | | |
| 01/24/2021 | 22:15:48 | 141 | 4.0 | 12.24 | 788.6 | | | | |
| 01/24/2021 | 22:16:38 | 140 | .1 | 12.25 | 791.9 | | | | |
| 01/24/2021 | 22:17:28 | 14: | 4.1 | 12.30 | 795.3 | | | | |
| 01/24/2021 | 22:18:18 | 139 | 99 4.1 | 12.33 | 798.7 | | | | |
| 01/24/2021 | 22:19:08 | 74 | 6 0.3 | 12.29 | 800.7 | | | | |
| 01/24/2021 | 22:19:33 | 61 | 6 0.3 | 12.29 | 800.8 | End Spacer | | | |
| 01/24/2021 | 22:19:58 | 62 | .6 0.3 | 12.28 | 800.9 | | | | |
| 01/24/2021 | 22:20:48 | 69 | 6 0.0 | 12.26 | 801.2 | | | | |
| 01/24/2021 | 22:21:38 | 102 | 29 4.1 | 12.33 | 802.9 | | | | |
| 01/24/2021 | 22:22:28 | 139 | 96 4.6 | 12.33 | 806.8 | | | | |
| 01/24/2021 | 22:22:50 | 171 | 4.7 | 12.63 | 808.5 | Start Mixing Lead | Slurry | | |
| 01/24/2021 | 22:22:52 | 173 | | 12.70 | 808.7 | Bring to Weight | | | |
| 01/24/2021 | 22:23:18 | 157 | 78 4.8 | 12.73 | 810.7 | | | | |
| 01/24/2021 | 22:24:08 | 157 | | 12.82 | 814.6 | | | | |
| 01/24/2021 | 22:24:58 | 161 | | 12.92 | 818.5 | | | | |
| 01/24/2021 | 22:25:48 | 150 | | 12.86 | 822.5 | | | | |
| 01/24/2021 | 22:26:38 | 150 | | 12.80 | 826.3 | | | | |
| 01/24/2021 | 22:27:28 | 163 | | 12.75 | 830.6 | | | | |
| 01/24/2021 | 22:28:18 | 168 | | 12.75 | 834.8 | | | | |
| 01/24/2021 | 22:29:08 | 166 | | 12.75 | 839.0 | | | | |
| 01/24/2021 | 22:29:58 | 166 | | 12.75 | 843.3 | | | | |
| 01/24/2021 | 22:30:48 | 160 | | 12.73 | 843.3 | | | | |
| 01/24/2021 | 22:31:38 | 160 | | 12.70 | 851.9 | | | | |
| 01/24/2021 | 22:32:28 | 160 | | 12.84 | 856.1 | | | | |
| 01/24/2021 | 22:33:18 | 155 | | | | | | | |
| 01/24/2021 | 22:34:08 | 155 | | 12.80 | 860.4 | | | | |
| 01/24/2021 | 22:34:58 | | | 12.82 | 864.7 | | | | |
| 01/24/2021 | 22:35:48 | 152 | | 12.86 | 868.9 | | | | |
| 01/24/2021 | 22:35:48 | 152 | | 12.83 | 873.2 | | | | |
| 01/24/2021 | 22:37:28 | 151 | | 12.78 | 877.5 | | | | |
| 01/24/2021 | 22:39:08 | 148 | | 12.74 | 881.8 | | | | |
| 01/24/2021 | 22:39:58 | 148 | | 12.75 | 890.3 | | | | |
| 01/24/2021 | 22:40:48 | 143 | | 12.76 | 894.6 | | | | |
| 01/24/2021 | 22:40:40 | 145 | | 12.74 | 898.8 | | | | |
| 01/24/2021 | 22:41:30 | 129 | | 12.74 | 902.6 | | | | |
| 01/24/2021 | 22:42:28 | 145 | | 12.75 | 906.9 | | | | |
| 01/24/2021 | 22:44:08 | 144 | | 12.76 | 911.2 | | | | |
| 01/24/2021 | 22:44:58 | 147 | | 12.77 | 915.5 | | | | |
| 01/24/2021 | 22:44:58 | 140 | | 12.78 | 919.8 | | | | |
| 01/24/2021 | | | | 12.79 | 924.1 | | | | |
| | 22:46:38 | 143 | | 12.80 | 928.4 | | | | |
| 01/24/2021 | 22:47:28 | 140 | | 12.82 | 932.7 | | | | |
| 01/24/2021 | 22:48:18 | 136 | | 12.85 | 937.0 | | | | |
| 01/24/2021 | 22:49:08 | 138 | | 12.86 | 941.3 | | | | |
| 01/24/2021 | 22:49:58 | 138 | | 12.86 | 945.6 | | | | |
| 01/24/2021 | 22:50:48 | 132 | | 12.84 | 949.9 | | | | |
| 01/24/2021 | 22:51:38 | 129 | | 12.84 | 954.3 | | | | |
| 01/24/2021 | 22:52:28 | 128 | | 12.85 | 958.6 | | | | |
| 01/24/2021 | 22:53:18 | 134 | 5 5.2 | 12.83 | 962.9 | | | | |

| | 3H Blue Ribbon Fe | | | Job Start Jan/24/2021 | Customer Franklin Moun | tain | Job Number 3193093 |
|------------|------------------------|-----------------------------|---------------------|--------------------------|---------------------------|------|-----------------------|
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume BBL | | Message |
| 01/24/2021 | 22:54:58 | 1281 | 5.2 | 12.80 | 971.5 | | |
| 01/24/2021 | 22:55:48 | 1247 | 5.2 | 12.78 | 975.8 | | |
| 01/24/2021 | 22:56:38 | 1259 | 5.1 | 12.81 | 980.1 | | |
| 01/24/2021 | 22:57:28 | 1259 | 5.2 | 12.84 | 984.4 | | |
| 01/24/2021 | 22:58:18 | 1246 | 5.2 | 12.84 | 988.7 | | |
| 01/24/2021 | 22:59:08 | 1255 | 5.1 | 12.86 | 993.0 | | |
| 01/24/2021 | 22:59:58 | 1183 | 5.2 | 12.90 | 997.3 | | |
| 01/24/2021 | 23:00:48 | 1172 | 5.1 | 12.92 | 1001.6 | | |
| 01/24/2021 | 23:01:38 | 1173 | 5.2 | 12.87 | 1005.9 | | |
| 01/24/2021 | 23:02:28 | 1180 | 5.2 | 12.80 | 1010.3 | | |
| 01/24/2021 | 23:03:18 | 1128 | 5.2 | 12.84 | 1014.6 | | |
| 01/24/2021 | 23:04:08 | 1133 | 5.2 | 12.83 | 1018.9 | | |
| 01/24/2021 | 23:04:58 | 1085 | 5.2 | 12.77 | 1023.2 | | |
| 01/24/2021 | 23:05:48 | 1138 | 5.2 | 12.83 | 1027.5 | | |
| 01/24/2021 | 23:06:38 | 1131 | 5.2 | 12.89 | 1031.8 | | |
| 01/24/2021 | 23:08:18 | 1056 | 4.8 | 12.88 | 1040.2 | | |
| 01/24/2021 | 23:09:08 | 902 | 4.9 | 12.86 | 1044.2 | | |
| 01/24/2021 | 23:09:58 | 926 | 4.8 | 12.85 | 1048.3 | | |
| 01/24/2021 | 23:10:48 | 809 | 4.9 | 12.87 | 1052.3 | | |
| 01/24/2021 | 23:11:38 | 789 | 4.8 | 12.88 | 1056.3 | | |
| 01/24/2021 | 23:12:28 | 840 | 4.8 | 12.92 | 1060.3 | | |
| 01/24/2021 | 23:13:18 | 829 | 4.8 | 12.88 | 1064.3 | | |
| 01/24/2021 | 23:14:08 | 837 | 4.9 | 12.89 | 1068.4 | | |
| 01/24/2021 | 23:14:58 | 837 | 4.8 | 12.88 | 1072.4 | | |
| 01/24/2021 | 23:15:48 | 748 | 4.9 | 12.88 | 1076.5 | | |
| 01/24/2021 | 23:16:38 | 792 | 4.8 | 12.86 | 1080.5 | | |
| 01/24/2021 | 23:17:28 | 806 | 4.8 | 12.85 | 1084.5 | | |
| 01/24/2021 | 23:18:18 | 829 | 4.9 | 12.87 | 1088.6 | | |
| 01/24/2021 | 23:19:08 | 697 | 4.9 | 12.82 | 1092.6 | | |
| 01/24/2021 | 23:19:58 | 663 | 4.9 | 12.76 | 1096.7 | | |
| 01/24/2021 | 23:20:48 | 639 | 4.9 | 12.80 | 1100.7 | | |
| 01/24/2021 | 23:21:38 | 700 | 4.9 | 12.82 | 1104.8 | | |
| 01/24/2021 | 23:22:28 | 687 | 4.9 | 12.86 | 1108.8 | | |
| 01/24/2021 | 23:23:18 | 717 | 4.8 | 12.88 | 1112.8 | | |
| 01/24/2021 | 23:24:08 | 690 | 4.9 | 12.89 | 1116.9 | | |
| 01/24/2021 | 23:24:58 | 762 | 4.8 | 12.92 | 1120.9 | | |
| 01/24/2021 | 23:25:48 | 728 | 4.8 | 12.95 | 1125.0 | | |
| 01/24/2021 | 23:26:38 | 616 | 4.8 | 12.93 | 1129.0 | | |
| 01/24/2021 | 23:27:28 | 631 | 4.8 | 12.95 | 1133.1 | | |
| 01/24/2021 | 23:28:18 | 594 | 4.8 | 12.89 | 1137.2 | | |
| 01/24/2021 | 23:29:08 | 669 | 4.8 | 12.87 | 1141.2 | | |
| 01/24/2021 | 23:29:58 | 669 | 4.8 | 12.86 | 1145.2 | | |
| 01/24/2021 | 23:30:48 | 467 | 4.9 | 12.87 | 1149.3 | | |
| 01/24/2021 | 23:31:38 | 460 | 4.9 | 12.86 | 1153.4 | | |
| 01/24/2021 | 23:32:28 | 466 | 4.9 | 12.83 | 1157.2 | | |
| 01/24/2021 | 23:33:18 | 576 | 5.2 | 12.83 | 1161.5 | | |
| 01/24/2021 | 23:34:08 | 509 | 5.1 | 12.83 | 1165.8 | | |
| 01/24/2021 | 23:34:58 | 486 | 4.9 | 12.84 | 1170.1 | | |
| 01/24/2021 | 23:35:48 | 408 | 5.1 | 12.85 | 1174.2 | | |
| 01/24/2021 | 23:37:28 | 462 | 5.2 | 12.79 | 1182.7 | | |
| 01/24/2021 | 23:38:18 | 498 | 5.1 | 12.85 | 1187.0 | | |
| 01/24/2021 | 23:39:08 | 524 | 5.2 | 12.82 | 1191.3 | | |
| 01/24/2021 | 23:39:58 | 570 | 5.1 | 12.93 | 1195.7 | | |

| Well | | Field | | Job Start | Customer | Job Number |
|-----------------|------------------------|-----------------------------|---------------------|-----------------|---------------|------------|
| Federal Com 703 | 3H Blue Ribbon Fe | deral Com 703F | | Jan/24/2021 | Franklin Mour | |
| Date | Time 24-hr clock | Treating Pressure PSI | Flow Rate B/M | Density LB/G | Volume DBL | Message |
| 01/24/2021 | 23:42:28 | 781 | 5.2 | 12.91 | 1208.6 | |
| 01/24/2021 | 23:43:18 | 2506 | 3.5 | 12.89 | 1212.9 | |
| 01/24/2021 | 23:44:08 | 2255 | 0.0 | 13.24 | 1213.1 | |
| 01/24/2021 | 23:44:58 | 2237 | 0.0 | 13.92 | 1213.1 | |
| 01/24/2021 | 23:45:48 | 2224 | 0.0 | 14.01 | 1213.1 | |
| 01/24/2021 | 23:46:38 | 2446 | 1.3 | 12.90 | 1213.3 | |
| 01/24/2021 | 23:47:28 | 3753 | 2.2 | 12.85 | 1214.8 | |
| 01/24/2021 | 23:48:18 | 3967 | 0.0 | 13.13 | 1215.2 | |
| 01/24/2021 | 23:49:08 | 3955 | 0.8 | 12.82 | 1215.3 | |
| 01/24/2021 | 23:49:58 | 4291 | 0.4 | 12.99 | 1215.6 | |
| 01/24/2021 | 23:50:48 | 4474 | 0.4 | 12.88 | 1215.7 | |
| 01/24/2021 | 23:51:38 | 4471 | 0.0 | 13.29 | 1215.8 | |
| 01/24/2021 | 23:52:28 | 4460 | 0.0 | 13.56 | 1215.8 | |
| 01/24/2021 | 23:53:18 | 4449 | 0.0 | 13.66 | 1215.8 | |
| 01/24/2021 | 23:54:08 | 4441 | 0.0 | 13.71 | 1215.8 | |
| 01/24/2021 | 23:54:58 | 4434 | 0.0 | 13.74 | 1215.8 | |
| 01/24/2021 | 23:55:48 | 4428 | 0.0 | 13.74 | 1215.8 | |
| 01/24/2021 | 23:56:38 | 4425 | 0.0 | 13.73 | 1215.8 | |
| 01/24/2021 | 23:57:28 | 2721 | 0.0 | 13.73 | 1215.8 | |
| 01/24/2021 | 23:58:18 | 9 | 0.0 | 13.73 | 1215.8 | |
| 01/24/2021 | 23:59:08 | 580 | 2.2 | 12.06 | 1216.3 | |
| 01/24/2021 | 23:59:58 | 1429 | 1.0 | 11.93 | 1217.4 | |
| 01/25/2021 | 00:00:48 | 2159 | 1.0 | 11.73 | 1218.2 | |
| 01/25/2021 | 00:01:38 | 2831 | 1.0 | 11.46 | 1219.1 | |
| 01/25/2021 | 00:02:28 | 3479 | 1.0 | 11.29 | 1219.9 | |
| 01/25/2021 | 00:03:18 | 4170 | 1.0 | 11.27 | 1220.7 | |
| 01/25/2021 | 00:04:08 | 4343 | 0.0 | 11.36 | 1221.0 | |
| 01/25/2021 | 00:04:58 | 4335 | 0.0 | 11.55 | 1221.0 | |
| 01/25/2021 | 00:06:38 | 502 | 0.0 | 11.87 | 1221.0 | |
| 01/25/2021 | 00:07:28 | 130 | 0.0 | 11.96 | 1221.0 | |
| 01/25/2021 | 00:08:18 | 40 | 0.0 | 12.01 | 1221.0 | |
| 01/25/2021 | 00:09:08 | 9 | 0.0 | 12.02 | 1221.0 | |
| 01/25/2021 | 00:09:58 | 5 | 0.0 | 11.99 | 1221.0 | |

Post Job Summary

| Average Pump Rates, bbl/min | | | | | Volume of Fluid Injected, bbl | | | | | | | | | | | | |
|-----------------------------|-----------------|------------|----------------------------------|-------------------|-------------------------------|----------|------------------------|------------|---------|--------|-------------------|---------------|-------------|---------|-------|-----------|---|
| Slurry N2 4.1 | | Mud | | Maximum Rate | | | Total Slurry 1220.9 | | Mud 0.0 | | Spacer 61.4 | | | N2 | | | |
| | | Treating P | ressure Sur | nmary, psi | | | | | | | | Breakd | own Fluid | | | | |
| Maximum | aximum Final Av | | Average | Average Bump Plug | | Breakdo | | vn Туре | | Volume | | | | Density | | | |
| 4533 0 8 | | 826 | 5 | | | | | Slickwater | | bbl | | | 8.34 lb/gal | | | | |
| Avg. N2 Percent | | Designed | Slurry Vol | ume | Displacem | ent | м | lix Wate | er Temp | Ceme | ent Circulat | ed to Surface |) [| | Volu | me bbl | |
| % | | 0.0 DDI | | | 428.8 bbl | | | 83 degF | | Wash | Washed Thru Perfs | | [| | To ft | | |
| Customer or Auth | orized | Representa | tive | | Schlumber | ger Sup | pervisor | | | | Circulatio | on Lost | [| | Job (| Completed | x |
| Fred Lacey | | | Lee Perry / Pumper Rafael Millas | | | Millasal | ky | | - | | | | - | | | | |

.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

| CONDITIONS | | | | | |
|------------------------------|--------------------------------|--|--|--|--|
| Operator: | OGRID: | | | | |
| Franklin Mountain Energy LLC | 373910 | | | | |
| 44 Cook Street | Action Number: | | | | |
| Denver, CO 80206 | 39024 | | | | |
| | Action Type: | | | | |
| | [C-103] Sub. Drilling (C-103N) | | | | |
| | | | | | |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| ksimmons | None | 8/2/2021 |

CONDITIONS

Page 50 of 50

Action 39024