Received by OCD: 9/10/2021 9:29:13 AM This form is not to be used for reporting packer leakage tests in Southeast New Mexico Northwe				Oil Conservation Division at New Mexico Packer-Leakage Test				Page 1 of			
			orthwest					P. Revised June 10,		ge 1 2003	
Operator Hilco	orp Energy Comp	bany		Lea	ase Name	e SAN JU	AN 32-7 I	UNIT		Well No. 79	
Location of We	ell: Unit Letter	J	Sec	07	Twp	031N	Rge	007W	_ API	# 30-045-25207	
	Name of R	eservoir	or Pool			rpe Prod		Method of Prod		Prod Medium	
Upper Completion	FR-PC			G	as		Flo	W		Tubing	
Lower Completion	MV			G	as		Flo	W		Tubing	

Pre-Flow Shut-In Pressure Data

	-			
Upper	Hour, Date, Shut-In		SI Press. PSIG	Stabilized?(Yes or No)
Completion	9/3/2021	Length of Time Shut-In	206	Yes
Lower	Hour, Date, Shut-In	157	SI Press. PSIG	Stabilized?(Yes or No)
Completion	9/3/2021		119	Yes

Flow Test No. 1

Commenced at: 9/9	Zone Producing (Upper or Lower): UPPER				
Time	Lapsed Time	PRESSURE		Prod Zone	
(date/time)	Since*	Upper zone	Lower zone	Temperature	Remarks
9/9/2021 12:28 PM	12	206	119		Started Test. John Durham, NMOCD,
					witnessed test.
9/9/2021 12:30 PM	12	95	119		Reached crossover immediately after
	1	1		1	producing to the blow trailer
9/9/2021 1:00 PM	13	6	119		30 mins after crossover.

Production rate during test

Oil:	BOPD Based on:	Bbls. In	Hrs.	Grav.	GOR

Gas _____MCFPD; Test thru (Orifice or Meter) _____

Mid-Test Shut-In Pressure Data

Upper Completion	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. PSIG	Stabilized?(Yes or No)
Lower Completion	Hour, Date, Shut-In		SI Press. PSIG	Stabilized?(Yes or No)

(Continue on reverse side)

Northwest New Mexico Packer-Leakage Test

		Flov	w Test No. 2				
Commenced at:			Zone Pro	oducing (Uppe	r or Lower)		
Time	Lapsed Time	Time PRESSU		RE Prod Zone			
(date/time)	Since*	Upper zone	Lower zone	Temperature	F	Remarks	
Production rate during	a toot						
	-						
Dil:BOPI	D Based on:	Bbls. In	Hrs.		Grav.	GOR	
las	MCFPD; Test th	hru (Orifice or Me	eter)				
Remarks:							
hereby certify that th	e information herein o	contained is true a	and complete	to the best of	my knowledge.		
Approved:		20	Operat	or: Hilcorp E	Energy Company		
					lineigy company		
New Mexico Oil Conservation Division		Ъу	By: Ryan Gray				
Ву:			Title:	Multi-Skilled	Operator		
Title:			Date:	Friday, Septe	ember 10, 2021		
				,			
	NORT	THWEST NEWMEXICO I	PACKER LEAKAGE	TEST INSTRUCTIO	NS		
. A packer leakage test shall be com	menced on each multiply completed wel	ll within seven days after actual	6. Flow T	est No. 2 shall be conduct	ed even though no leak was ind	cated during Flow Test No. 1. Procedure	
such tests shall also be commenced on a	reafter as prescribed by the order author all multiple completions within seven day	ys following recompletion and/	or remain shut-		as for Flow Test No. 1 except th as previously shut-in is produce	at the previously produced zone shall d.	
he tubing have been disturbed. Tests sh	never remedial work has been done on a hall also be taken at any time that comm						
equested by the Division.			intervals as f	ollows: 3 hours tests: imm	ediately prior to the beginning	a deadweight pressure gauge at time of each flow period, at fifteen-minute	
	mencement of any packer leakage test, the		immediately	prior to the conclusion of	each flow period. 7-day tests:	, including one pressure measurement mmediately prior to the beginning of each	
Division in writing of the exact time the	test is to be commenced. Offset operat	ors shall also be so notified.	to the conclu	flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells			
			which have p	previously shown question	able test data.		

The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.

4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to lack of a pipeline connection the flow period shall be three hours.

5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.

Released to Imaging: 9/13/2021 1:42:21 PM

3.

Page 2 of 3 Page 2

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 47630

CONDITIONS				
Operator: HILCORP ENERGY COMPANY	OGRID: 372171			
1111 Travis Street Houston, TX 77002	Action Number: 47630			
	Action Type: [UF-PLT] Packer Leakage Test (NW) (PACKER LEAKAGE TEST (NW))			

CONDITIONS

Created By	Condition	Condition Date
kpickford	None	9/13/2021