

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: ROPCO 9 Well Location: T29N / R14W / SEC 9 / County or Parish/State: SAN

SENW / 36.744562 / 108.317268 JUAN / NM

Well Number: 4 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMSF079968 Unit or CA Name: Unit or CA Number:

US Well Number: 3004530345 Well Status: Gas Well Shut In Operator: HILCORP ENERGY

COMPANY

Subsequent Report

Type of Submission: Subsequent Report

Type of Action: Plug and Abandonment

Date Sundry Submitted: 01/29/2021 Time Sundry Submitted: 03:10

Date Operation Actually Began: 12/04/2020

Actual Procedure: Attached please find the sundry that was submitted through WIS on 12/14/2020 to report on the P&A

SR

SR Attachments

Actual Procedure

WIS_PRINT_SUBMITTED_540680_20210129151014.pdf

ROPCO_9_4_P_A_SR_20210129151014.pdf

Current_Schematic_12.14.20_20210129151014.pdf

BLM Point of Contact

BLM POC Name: WILLIAM F TAMBEKOU **BLM POC Title:** PETROLEUM ENGINEER

BLM POC Phone: 7192698500 BLM POC Email Address: wtambekou@blm.gov

Disposition: Accepted **Disposition Date:** 04/02/2021

Signature: William Max Tambekou

Page 1 of 1

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMSF0799686. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.			
Type of Well ☐ Oil Well ☐ Other Other				8. Well Name and No. ROPCO 9 4			
2. Name of Operator Contact: AMANDA WALKER HILCORP ENERGY E-Mail: mwalker@hilcorp.com					9. API Well No. 30-045-30345		
3a. Address 1111 TRAVIS ST. HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505-324-5122		10. Field and Pool or Exploratory Area TWIN MOUNDS PC				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	ı)			11. County or Parish,	State	
Sec 9 T29N R14W Mer NMP SENW 1438FNL 1910FWL				SAN JUAN COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION			TYPE OI	F ACTION			
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	□ Нус	lraulic Fracturing	□ Reclam	ation	■ Well Integrity	
	☐ Casing Repair	□ Nev	v Construction	☐ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	🛛 Pluş	g and Abandon	□ Tempor	arily Abandon		
	☐ Convert to Injection	☐ Plug	g Back	■ Water I	Disposal		
testing has been completed. Final At determined that the site is ready for final ATTACHED PLEASE FIND To	inal inspection. HE SR FOR THE P&A OI	-	_	ling reclamatio	n, have been completed a	and the operator has	
14. I hereby certify that the foregoing is	Electronic Submission #	540680 verifie DRP ENERGY,	d by the BLM We sent to the Farm	II Information ington	n System		
Name(Printed/Typed) AMANDA WALKER			Title OPERATIONS/REGULATORY TECH SR.		SR.		
Signature (Electronic S	Submission)		Date 12/14/2	020			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By			Title			Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the		Office				
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any po	erson knowingly and	willfully to ma	ake to any department or	agency of the United	

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

ROPCO 9 4 3004530345 P&A SR NMSF079968

12/4/2020: MIRU. CK WELL PRESSURE (TBG: 0 PSI, CSG: 0 PSI, BH: 0 PSI). ND WH. NU BOPE. FUNCTION TST BOPE. TST GOOD. SPOT IN KILL TRUCK. LOAD & PT CSG W/10 BBLS, CSG TST FAILED. RU WL. RUN CBL FROM CIBP @ 730' TO SURF. SIW. SL. SDFWE.

12/10/2020: MIRU CMT EQUIP. CK WELL PRESSURE (TBG: 0 PSI, CSG: 0 PSI, BH: 0 PSI). PU & TALLY 23 JTS OF 2 3/8" TBG. TAG PLG. LD 1 JT, LEAVING EOT ABV PLUG @ 772'. MIX AND PUMP PLUG #1 (SURF PLUG) W/ 60 SKS OF 15.8 PPG 1.15 YIELD 12.3 BBLS SLURRY CLASS G NEAT CEMENT F/ 730' TO SURF. RETURNED GOOD CEMENT TO SURFACE AND CUT PUMPS. SIW. WASH UP EQUIPMENT & WOC 4 HRS. PU 3 TBG JT & TAG TOC @ 96'. 25' CMT DOWN FROM CALC TAG DEPTH AFTER PIPE DISPLACEMENT. LOAD HOLE & PT CSG TO 600 PSI. TST GOOD. MIX & PMP TOP OFF CEMENT PLUG (SURF PLUG) W/ 12 SKS OF 15.8 PPG 1.15 YIELD 2.45 BBLS SLURRY CLASS G NEAT CEMENT F/ 96' TO SURFACE. RETURNED GOOD CEMENT TO SURFACE AND CUT PUMPS. SIW. WASH UP EQUIPMENT AND WOC OVER NIGHT. ND BOPE & NU WH. SIW. SDFN.


12/11/2020: CK WELL PRESSURE (TBG: 0 PSI, CSG: 0 PSI, BH: 0 PSI). RU WELDER. CO WH. CMT DWN 4' ON BACKSIDE. WEALD ON DHM. TOP OF CELLAR. RD RR

Hilcorp Energy Company

Current Schematic

Well Name: ROPCO 9 #4

	Surface Legal Location T29N-R14W-S09	Field Name Twin Mounds Pictured Cliffs	Route 0204			Well Configuration Type Vertical
Ground Elevation (ft) 5,380.00	Original KB/RT Elevation (ft) 5.385.00	KB-Ground Distance (ft) 5.00	KB-Casing Flange Di	stance (ft)	KB-Tubing Hanger	r Distance (ft)



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 22788

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	22788
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	10/4/2021