

## District II - Artesia

811 S. 1<sup>st</sup> Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Artesia District Office

## BRADENHEAD TEST REPORT

|                                                  |                                   |
|--------------------------------------------------|-----------------------------------|
| Operator Name<br><b>Devon Energy</b>             | API Number<br><b>30-015-40835</b> |
| Property Name<br><b>Parkway west unit SWD #1</b> | Well No<br><b>1</b>               |

| UL - Lot | Section   | Township   | Range      | Feet from   | N/S Line | Feet From  | E/W Line | County      |
|----------|-----------|------------|------------|-------------|----------|------------|----------|-------------|
|          | <b>27</b> | <b>19S</b> | <b>29E</b> | <b>1255</b> | <b>N</b> | <b>430</b> | <b>W</b> | <b>Eddy</b> |

## Well Status

| TA'D Well                                                     | SHUT-IN                                                       | INJECTOR                                                       | PRODUCER                                            | DATE           |
|---------------------------------------------------------------|---------------------------------------------------------------|----------------------------------------------------------------|-----------------------------------------------------|----------------|
| YES <input type="radio"/> NO <input checked="" type="radio"/> | YES <input type="radio"/> NO <input checked="" type="radio"/> | INJ <input type="radio"/> SWD <input checked="" type="radio"/> | OIL <input type="radio"/> GAS <input type="radio"/> | <b>7-15-21</b> |

## OBSERVED DATA

|                      | (A) Surf-Interm. | (B) Interm. (1) | (C) Interm. (2) | (D) Prod Casing | (E) Tubing         |
|----------------------|------------------|-----------------|-----------------|-----------------|--------------------|
| Pressure             | 0                | 0               |                 | 0               | 790                |
| Flow Characteristics |                  |                 |                 |                 |                    |
| Puff                 | Y/N              | Y/N             | Y/N             | Y/N             | CO2 _____          |
| Steady Flow          | Y/N              | Y/N             | Y/N             | Y/N             | WTR _____          |
| Surges               | Y/N              | Y/N             | Y/N             | Y/N             | GAS _____          |
| Down to nothing      | Y/N              | Y/N             | Y/N             | Y/N             | If applicable type |
| Gas or Oil           | Y/N              | Y/N             | Y/N             | Y/N             | Fluid injected for |
| Water                | Y/N              | Y/N             | Y/N             | Y/N             | Waterflood         |

If Braden head flowed water, check all the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

|                                                 |                                  |
|-------------------------------------------------|----------------------------------|
| Signature:                                      | <b>OIL CONSERVATION DIVISION</b> |
| Printed name: <b>Danny Smolik</b>               | Entered RBDMS                    |
| Title: <b>Compliance Office O</b>               | Re-test                          |
| E-mail Address: <b>danny.smolik@state.nm.us</b> |                                  |
| Date:                                           | Phone: <b>575-626-0836</b>       |
|                                                 | Witness:                         |

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 40817

CONDITIONS

|                                                                                                       |                |
|-------------------------------------------------------------------------------------------------------|----------------|
| Operator:<br>DEVON ENERGY PRODUCTION COMPANY, LP<br>333 West Sheridan Ave.<br>Oklahoma City, OK 73102 | OGRID:         |
|                                                                                                       | 6137           |
|                                                                                                       | Action Number: |
|                                                                                                       | 40817          |
| Action Type:                                                                                          |                |
| [UF-BHT] Bradenhead Test (BRADENHEAD TEST)                                                            |                |

CONDITIONS

|            |           |                |
|------------|-----------|----------------|
| Created By | Condition | Condition Date |
| gcordero   | None      | 12/20/2021     |