



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-11-21 Operator Coleman Oil & Gas API #30-0 45-24744
Property Name McCord Well No. 7E Location: Unit P Section 4 Township 30N Range 13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 352 Intermediate N/A Casing 352 Bradenhead 170

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min			<u>352</u>		
10 min			<u>352</u>		
15 min			<u>352</u>		
20 min			<u>352</u>		
25 min			<u>352</u>		
30 min			<u>352</u>		
				Steady Flow <u>X</u>	
				Surges	
				Down to Nothing	
				Nothing	
				Gas <u>X</u>	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE N/A

REMARKS: (Plunger well) Braden Head Steady Flow of gas thru 1/2 valve during 30 min Test

By Bruce Taylor
Lease operator
(Position)

Witness _____

E-mail address _____

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 66757

CONDITIONS

Operator: COLEMAN OIL & GAS INC P.O. Drawer 3337 Farmington, NM 87499	OGRID:
	4838
	Action Number:
	66757
Action Type:	
[UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

CONDITIONS

Created By	Condition	Condition Date
mkuehling	failed bht - wellhead repaired - will need 30 day bht after fix - 6 month bht after fix - 1 year bht after fix.	12/21/2021