2/9/2022

DATE

APPROVED BY:

Conditions of Approval (if any):

## State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary Adrienne Sandoval, Division Director Oil Conservation Division



Date: 1-11-21 API# 30-015-01899

A Mechanical Integrity Test (M.I.T.) was performed on, Well West Artesia Grey Bug Unit # 18

M.I.T. is successful, the original chart has been retained by the Operator on site. Send a legible scan of the chart with an attached Original C-103 Form indicating reason for the test, via post mail to District NMOCD field office. A scanned image will appear online via NMOCD website, <a href="https://www.emnrd.state.nm.us/ocd/OCDOnllne.htm">www.emnrd.state.nm.us/ocd/OCDOnllne.htm</a> 7 to 10 days after postdating.

M.I.T. is unsuccessful, the original chart is returned to the Operator. Repairs will be made; Operator is to schedule for a re-test within a 90-day period. If this is a test of a repaired well currently in non-compliance, all dates and requirements of the original are still in effect.

No expectation of extension should be construed because of this test.

M.I.T. **for Temporary Abandonment**, shall include a detailed description on **Form C-103**, including the location of the CIBP and any other tubular goods in the well including the Operator's request for TA status timeline.

M.I.T. is successful, after the secondary request of a scheduled M.I.T. is performed. Therefore, Operator has within a 30-day period from the M.I.T. to submit a current C-103 along with a legible scan of the Chart, including a detailed description of the repair(s). *Only after receipt of the C-103 will the non-compliance be closed.* 


\_\_\_\_M.I.T.**is successful**, Initial of an injection well, you must submit a **form C-103** to NMOCD within 30 days. A **C-103 form** must include a detailed description of the work performed on this well Including the position of the packer, tubing Information, the date of first Injection, the tubing pressure and Injection volume.

Please contact me for verification to ensure documentation requirements are in place prior to injection process.

If I can be of additional assistance, please feel free to contact me at (575) 626-0836

Thank You,

Dan Smolik, Compliance Officer EMNRD-O.C.D. District II – Artesia, NM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 78660

## **CONDITIONS**

Operator:	OGRID:
ROVER OPERATING, LLC	371484
17304 Preston Road	Action Number:
Dallas, TX 75252	78660
	Action Type:
	[C-103] Sub. General Sundry (C-103Z)

## CONDITIONS

Created By		Condition Date
gcordero	None	2/9/2022