District I
1625 N French Dr , Hobbs, NM 88240
Phone: (575) 393-6161 Fax. (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name		API Number
APACHE OIL CORP		30-025-09918
Property Name		**Well No.**
NORTH EAST DRINKARD UNIT (NEDU)		#703

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
K	15	21S	37E		1980	S	1980	W	LEA

Well Status

TA'D WELL		SHUT-IN			INJECTOR		PRODUCER			DATE
YES	NO	YES	NO	INJ		SWD	OIL	GAS		3/31/22

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	O	O		O	1000
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
	Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

CONDITIONS

Action 108793

**State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505**

CONDITIONS

Operator:		
APACHE CORPORATION 303 Veterans Airpark Ln Midland, TX 79705	OGRID: 873	
	Action Number: 108793	
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	5/27/2022