

District 1
7825 S French Dr., Hobbs, NM 88249
Phone: (575) 393-6161 Fax: (575) 393-9732

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SAT 4
INJ

BRADENHEAD TEST REPORT

Operator Name Chevron USA INC.		API Number 30-028-40466
Property Name CENTRAL VACUUM UNIT		Well No. 279

Surface Location									
PL - Lot E	Section 31	Township 17S	Range 35E	Feet from 2033	N/S Line N	Feet From 1187	E/W Line W	County LEA	

Well Status					DATE
TA'D Well YES: <input checked="" type="radio"/>	SHUT-IN YES: <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/>	PRODUCER OIL: <input type="radio"/> GAS: <input type="radio"/>	SWD	17 June 21

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	N/A	0	910
Flow Characteristics					
Puff	<input checked="" type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	CO2 <input checked="" type="checkbox"/>
Steady Flow	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	WTR <input type="checkbox"/>
Surges	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	If applicable type
Gas or Oil	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	fluid injected for
Water	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	Water flood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Van Riper</i>	OIL CONSERVATION DIVISION
Printed name: Van Riper Tyrone Haan	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: HGAN@Chevron.com	
Date: 17 June 21	Phone
	Witness:

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 39086

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 39086
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/15/2022