Received by OCD: 4/14/2022 1:40:52 PM

Released to Imaging: 7/12/2022 1:53:54 PM

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT									
		P	Operator I APACHE O					30-025-269	
WEST BLINEBRY DRINKARD UNIT (WBDU)						Well No. #26			
				^{7.} S	urface Locatio	n			
UL-Lot A	Section 08	Township 21S	Range 37E		Feet from 990	N/S Line N	Fret From 660	E/W Line E	County LEA

990 Well Status

YES TA'D WELL NO	YES	SHUT-IN	INJECTOR SWD	OIL PRODUCER GAS	3-31-2022

OBSERVED DATA

	(A)Surface	B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			0	87
Flow Characteristics					
Puff	Y / 📢	V/N	X/N	(D) N	CO2
Steady Flow	Y / 💍	N VY	YN	Y / (N)	WTR GAS
Surges	YIO	YN	Y / W	Y / 🗘	Type of Fluid
Down to nothing	res/ N	Y/N	Y / 1	N	Injected for Waterflood if
Gas or Oil	Y / (N)	Y/N	Y / N	Y/N	applies.
Water	Y / 🕥	Y/N	Y/N	Y	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Production casing had slight water.

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test A
E-mail Address:	Λ	
Date:	Phone:	
	Witness: Lary Kolman	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 98705

CONDITIONS

Operator:	OGRID:
APACHE CORPORATION	873
303 Veterans Airpark Ln	Action Number:
Midland, TX 79705	98705
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
gcordero	None	7/12/2022