

District I
1625 N French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name APACHE OIL CORP	API Number 30-025-06478
Property Name EAST BLINEBRY DRINKARD UNIT (EBDU)	Well No. #17

7. Surface Location

UL - Lot O	Section 11	Township 21S	Range 37E	Feet from 330	N/S Line S	Feet From 1980	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ	SWD	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE 4/21/2022
--	--	--	-----	---	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgng	(E)Tubing
Pressure	O	O		O	83
Flow Characteristics					
Puff	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	CO2
Steady Flow	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	WTR <input checked="" type="checkbox"/>
Surges	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	GAS <input type="checkbox"/>
Down to nothing	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	Type of Fluid
Gas or Oil	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	Injected for
Water	Y/N <input checked="" type="radio"/>	Y/N <input checked="" type="radio"/>	Y/N	Y/N <input checked="" type="radio"/>	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface - had a little bit of fluid

Signature: <i>Ruby Ortega</i>	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 108639

CONDITIONS

Operator: APACHE CORPORATION 303 Veterans Airpark Ln Midland, TX 79705	OGRID: 873
	Action Number: 108639
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	7/19/2022