Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103 Revised July 18, 2013			
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	energy, Minerals and Natural Resources		WELL API N	IO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5 I I' T	30-025-46336		
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Ty		E	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505			& Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				100db3y 1440db605449.45x004 1005543044 1005		
(DO NOT USE THIS FORM FOR PROP	TICES AND REPOR	O DEEPEN OR PLU	IG BACK TO A	7. Lease Nan SAUNDERS 2	ne or Unit Agreement 26 STATE	Name
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	9017 (MODELLE MODELLE		RSUCH	8. Well Num	her .	
1. Type of Well: Oil Well	Gas Well Oth			9. OGRID N	1	
2. Name of Operator GREAT WE	ESTERN DRILLING	G COMPANY		9. OGRID N	009338	
3. Address of Operator P.O. BOX	(1659 JD, , TX 79702			10. Pool nam WC-025 G-10	ne or Wildcat S143326C; DEVON	IAN
4. Well Location						
		m the NORTH			t from the WEST	line
Section 26			nge 33E	NMPM	County LEA	1000年1000年11年
	4,189 GR	how whether DR,	RKB, RT, GR, etc.,			
	1,100					
12. Check	Appropriate Box	to Indicate N	ature of Notice,	Report or Ot	her Data	
NOTICE OF I	NTENTION TO				REPORT OF:	
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CAS	
TEMPORARILY ABANDON		1000 (E-1000)	COMMENCE DRI	the state of the s		X PNR
PULL OR ALTER CASING DOWNHOLE COMMINGLE		IPL 🗆	CASING/CEMEN	I JOB [FINIX
CLOSED-LOOP SYSTEM						
OTHER:			OTHER:			
13. Describe proposed or com	ipleted operations. (Clearly state all	pertinent details, an	d give pertinent	t dates, including estin	nated date
of starting any proposed v		9.15./.14 NMAC	. For Multiple Co	mpletions: Atta	ach wellbore diagram	01
Well was drilled, evaluated and		lowing plugs we	re set as specified b	y Paul F. Kautz	z on 3/16/2021:	
Plug #1 Devonian - 88 sacks "H Plug #2 Atoka – 70 sacks "H" c						
Plug #3 Wolfcamp – 60 sacks "						
Plug #4 Tubb – 70 sacks "C" ce	ement from 6900' – 7	7059'.	(O) WOC d		. (2) 5 (5 ())	
Plug #5 Intermediate Casing – 6 Plug #6 Yates – 32 sacks "C" ce			60°. WOC, then ta	g top of cemen	t @ 3630 .	
Plug #7 Rustler – 32 sacks "C"						
Plug #8 Surface Casing - 32 sad	cks "C" cement from	n 325' – 432'.				
Plug #9 Ground – 20 sacks "C"	cement from 0' – 60)'.				
Cut off wellhead and weld on d	ry hole marker as pe	r NMOCD guide	lines 3/19/21.			
Spud Date: 02/11/2021		Rig Release Da	ite: 03/18/2021			
Spud Date: 02/11/2021		Rig Release De	03/16/2021			
I hereby certify that the information	on above is true and o	complete to the b	est of my knowledg	ge and belief.		
0 71	· ()					
SIGNATURE PM PILM	ngsker	TITLE AREA	ENGINEER		DATE <u>04/02/2021</u>	
Town and interest CARVINITY	NGSLEY	E mail a 11	a shillings!	uda aem	PHONE: (432)682	-5241
Type or print name <u>CARY BILLI</u> For State Use Only	NGSLEY	_ E-mail addres	s: <u>cbillingsley@gv</u>	vac.com	_ 1 HONE. (432)082	-541
0/	1 4	0	lionos Officer A		0/00/00	
APPROVED BY: 1000 APPROVED BY:	:24 AM	TITLE_Comp	oliance Officer A		_DATE9/20/22	

Received by OCD: 8/18/2022 2:55:17 PM GREAT WESTERN DRILLING COMPANY **OPERATED WELLS**

08/18/22

Page 1

TIGHT HOLE

GWDC

Saunders "26" State #1 – Lea Co., NM

PROS: North Saunders PTD: 13,700' Siluro-Devonian

LOC: 1900' FWL - 150' FNL, T14S-R33E, Sec 26

AFE: **CONTR: Norton Rig #2**

GWDC WI = 32.33% GWDC NRI = 24.89% API: 30-025-46336

SPUD: 2/11/21

APSR: #1912

02/09/21

Moved and set up trailer houses and septic. Set Substructure and pits. Started putting derrick together. Solids equipment coming later today.

02/10/21

RU Norton Rig #2. Set up CLS Solids equipment. Will finish rigging them up this A.M. Getting fast line laid to rig today. Have welder set for 10:00 A.M. to weld conductor. Will start filling water tanks and pits today. Notified NM OCD of spud and surface casing 4:40, 2/9/21. Had conversation with both tool pushers and we believe it will be tomorrow before we spud.

DC: \$27,745

CC: \$27,745

02/11/21

Drilling @ 382'. Made 0'/24 hrs. Rig repair & RU Norton Rig #2. Weld on conductor. Pre-spud safety inspection & corrections. Mix premix, 100 bbls of Hi Vis pill w/Bentonite. PU BHA, wash to btm. Tag @ 100'. Drlg 100' to 382', 17 1/2" hole, all wt., 80-90 RPM, 110-140 SPM, 700# press. Survey 0.2°, 88 Azi @ 151', 0.7° Inc 50 Azi @ 274', 0.9° Inc 68 Azi @ 373'. Pump 25 bbls hi Vis sweep, circ out. Pump 50 bbls Hi Vis sweep, circ out. Repair clamp on saver sub. Replace dies in grabber. Replace broken hose on iron roughneck. Circ thru string at intervals. TOH. LD 1 jt DP. Safety meeting w/laydown machine. RU Byrd laydown machine. LD Invictus 8" shot survey DC, bit sub & bit. RU Byrd csg crew. Get float equipment, swedge. Schlumberger iron on floor. Run 9 jts 13 3/8", 54.5#, J-55, STC csg w/Weatherford float shoe, float collar, 4 centralizers, 386' total. Set @ 382', FC @ 335', Circ 2 jts, 5 jt5s, 8 jts to wash scale & rust out.

DC: \$104,778

CC: \$148,936

02/12/21

Drilling @382'. Made 0'/24 hrs. Run 9 jts 13 3/8", 54.5#, J-55 STC csg w/Weatherford float shoe, float collar, 4 centralizers, 386' total. Set @ 382', FC @ 335', circ 2 jts, 5 jts, 8 jts to wash scale & rust out. Circ. RD csg crew & LD machine. WO Schlumberger. Had problems starting pump motor. Safety meeting w/Schlumberger. Norton rig #2 personnel and Joe Gordy. Cmt w/423 sks class C, 100 bbls @ 14.8#, 1.33 yield, 6.37 FW. Displace 53 bbls FW. Bump plug @ 10:56 A.M. 2/12/21. Floats held. WOC. Cut off conductor, weld on 13 3/8" x 5000# multi-bowl head. Test w/nitrogen 500# w/cactus tech. NU BOP, annular, manifold, valves, cutter rotating head w/Monahans NU. Having problems w/manifold.

DC: \$108,654

CC: \$257,590

08/18/22

Page 2

TIGHT HOLE

Drilling @382'. Made 0'/24 hrs. NU all BOP equipment w/Monahans NU. Test BOP, manifold, all valves to 250# & 5000#. Test annular 250# & 1500#. Pipe rams no test. Everything else test OK. Open doors, 1 ram rubber off block. WO ram rubbers and install same. Door gasket leaking. Try to tighten, replace door gaskets. Test rams 250# and 5000#, OK. Install wear ring w/Cactus Tech. Replace long hydraulic hose on top drive.

DC: \$151,881 CC: \$409,471

Drilling @ 382'. Made 0'/24 hrs. Trouble shoot top drive. Had to heat oil tank with 2 torches to get turning. Pits froze up. Ad brine f/9.4 wt. Thawing out lines with 2 torches. Put back yard together. MU Kelly hose. Try to pump thru standpipe to circ pits. Thawing out lines with 2 torches. Ran out butane. Could not locate any in Lovington. Also could not find welder to come out and help. Fuel jelling up in engines and light plant. Drain pumps and mud lines. Attempt to keep engines and light plant running while waiting on place to get butane and see if can locate welder. DC: \$50,135 CC: \$479,575

DC: \$50,135 CC: \$479,575

- Drilling @ 382'. Made 0'/24 hrs. Thaw out mud lines, waterlines w/2 torches & welder w/rosebud. Hook up pumps, standpipe & 4" mud line frozen. Thaw same out. Install bell nipple. Circ thru fill up line. Transfer 225 bbls slush water to half round pit. Add 200 bbls brine & circ thru fill up line. PU directional tools, scribe tools. TIH w/pump. Circ thru fill up line. MW 9.4, Vis 29, pH 7.5, Chl 118k. DC: \$29,450 CC: \$509,025
- 02/16/21 Drilling @ 1455'. Made 1073'/24 hrs. TIH w/directional BHA. Thaw mud valve to top drive. TIH w/directional BHA, tag cmt 316'. Test csg 1500# f/30 min test OK. Test MWD & motor, test OK. Test ½ shoe track @ 360' to 1500# f/30 min, test OK. Drlg cmt & shoe, 360'-382'. Drlg 382'-1421', ROP 134 FPH, 5-25 wt., 75 rot, 115 SPM, 520 GPM, 1400# press, 100-400# diff. Survey every 190' & conn 3 ¾ hrs. Cont. Slide/drilling from 1421'-1455'. MW 9.6, Vis 29, pH 10, Chl 130k. DC: \$34,187 CC: \$543,212
- 02/18/21 Drilling @ 3805'. Made 990'/24 hrs. Drilling f/2815'-3250'. Pason down, trouble shoot same. Drlg 2850'-3805'. MW 10.6, Vis 34, pH 9, Chl 191k. DC: \$37,635 CC: \$631,605

08/18/22

Page 3

TIGHT HOLE

- Drilling @ 3990'. Made 185'/24 hrs. Drilling f/3805'-3990'. TOH. Tight 1782-1320'. Work pipe out hole. Stopped coming up. Screw in and circ. Wash & ream 90' & back ream. TOH. Remove rotating head. TOH. Break bit, bit 4" out gauge for 3" down from cutters. MU Ulterra SPL616 bit w/9/16's. Test MWD and motor. TIH. Deviations: 0.7° @ 3832'. MW 10.6, Vis 34, pH 9, Chl 189k. DC: \$50,718 CC: \$682,322
- Drilling @ 4506'. Made 516'/24 hrs. TIH. Install rotating head, new gasket on Pason flow meter. Wash, ream & back ream 1320'-1722'. TIH. Wash,ream 100' to btm. Drilling from 3990'-4506'. Attempt to make bit drill, no success. Pump sweep and circ out. TOH to find problem. Deviations: 0.7° @ 4022', 0.4° @ 4212', 0.5° @ 4403'. MW 10.5, Vis 35, pH 10, Chl 188k. DC: \$48,398 CC: \$730,720
- 02/21/21 Drilling @ 5131'. Made 625'/24 hrs. TOH. Bit #3 DBR on heel row, flat. Change out motor & bit. TIH. Test motor & bit. TIH. Test motor & MWD. TIH. Wash & ream 75' to btm. Last 10' hard. Drilling and rotating from 4506'-5131'. Deviations: 0.4° @ 4593', 0.1° @ 4784', 0.2° @ 4975'. MW 10.5, Vis 35, pH 10, Chl 189k. DC: \$68,577 CC: \$799,297
- Drilling @ 5740'. Made 609'/24 hrs. Drill rotate from 5131'-5740'. Lost ROP, diff & torque. TOH f/bit. Tight 1600'-1400'. (Bit cored out, 3 gone cutters, several chipped, bit is DBR). Change bits. Repair chain in draw works. TIH w/bit #5. Tag 5250'. Wash & ream 5250'-5722'. Deviations: 0.1° @ 5165', 0.3° @ 5356', 0.1° @ 5546'. MW 10.6, Vis 34, pH 9, Chl 189k.

 DC: \$54,482

 CC: \$853,779
- Drilling @ 5814'. Made 74'/24 hrs. TIH. Hit bridge 5250'. Wash & ream to btm. Ream last 5' slw w/2k wt. Drlg rot 5740-5814'. TOH to run csg. Tight 5400'-4800'. Stabilizers balled up. Circ & rotate. TOH. Tight 1725'-1400'. Pump out hole. RU Byrd Laydown Machine. Replace half link in input chain. LD 9-8" DC's and directional tools, bit, get subs & bits off floor. Pull wear ring. RU Byrd csg crew & safety meetings w/all personnel on rig. Run 145 jts 9 5/8", 40#, L-80, LTC csg, shoe @ 5810'. FC @ 5767'. Total pipe ran w/Cactus Landing Mandrel 5819'. Brett w/New Mexico OCD notified 11:05 A.M. 2/22/21 of run csg & cmt. MW 10.6, Vis 34, pH 9, Chl 177k. DC: \$245,138

08/18/22

Page 4

TIGHT HOLE

Drilling @ 5814'. Made 0'/24 hrs. Run 145 jts 9 5/8", 40#, L-80, LTC csg, shoe @ 5810'. FC @ 5767'. Total pipe ran w/Cactus landing Mandrell @ 5819'. Wash & circ from 5280'-5810'. First 45' hard had to wash to btm. Make up landing jt, Mandrell, setting tool & slips. Hang csg. Rig down Byrd csg crew & LD machine. Safety meeting with Schlumberger & all personnel on location. Test lines, 40 bbl FW flush. Cmt w/1204 sks 596 bbls @ 11# wt., 2.78 yield point, tail w/203 sks, 48.1 bbls Class C @ 14.8#, yield 1.33. Displace w/438.5 bbls FW. Plug down @ 23:15 P.M. 2/24/21. Circ 125 bbls to WOC. Wash out BOP & wellhead w/Cactus washout tool. Install pack off. Test upper & lower seals. 40K over pull test. Test upper & lower seals to 5000# w/Cactus field tech and wear ring. WOC. Cleaning steel pits w/Duke trucks. WO truck. Clean off floor. MW 8.4, Vis 28, pH 7, Chl 500k.

DC: \$131,024 CC: \$1,230,305

Drilling @ 5984'. Made 170'/24 hrs. WOC. Cleaning steel pits w/Duke trucks. WO truck, clean off floor, measure, caliper 12 - 6 1/4" DC's. Get bit & bit breaker on floor. Load directional tools on racks. Fill pits w/fresh water. PU directional BHA. Test motor & MWD. TIH. Circ, test csg to 1500# f/30". Test OK. Drlg cmt, plug & float collar 5708'-5790'. Test csg shoe track 1500# f/30". Drlg cmt 5790'-5814'. Drlg rot f/5814'-5984'. Deviation: 0.2° @ 5821'. MW 8.4, Vis 28, pH 10.5, Chl 600k. DC: \$33,507 CC: \$1,260,523

Drilling @ 6264'. Made 280'/24 hrs. Drlg Rot 5984'-6169'. 6253' torquing up. Trying to get drill to 6255'. No luck. At 6210' 80% dolomite, 20% anhydrite. At 6250' 70% anhy and 30% dolo. TOH f/bit. Remove MWD, change out bit. Check motor, no slack. Drained good. PU MWD. TIH w/bit #7. Wash and ream w/2K to btm. Pump sweep. Drill rot 6255'-6264'. Deviation: 0.2° @ 6012', 1.4° @ 6202'. MW 8.4, Vis 28, pH 11, Chl 8000.

DC: \$35,924 CC: \$1,303,487

02/27/21 Drilling @ 7330'. Made 1,066'. Drill rot from 6264'-7330'. RS. Deviations: 1.9° @ 6393', 1.8° @ 6583', 0.9° @ 6774, 1° @ 6965', 0.9° @ 7156'. MW 8.4, Vis 28, pH 11, Chl 8400.

DC: \$45,775 CC: \$1,349,262

02/28/21 Drilling @ 8700'. Made 1370'. Drilling and rotating from 7330'-8700'. RS. Deviations: 0.7° @ 7346', 0.6° @ 7535', 0.4° @ 7727', 0.4° @ 7917', 0.6° @ 8107', 0.92° @ 8290'. MW 8.4, Vis 28, pH 10, Chl 9600.

DC: \$39,721 CC: \$1,388,983

03/01/21 Drilling @ 9882'. Made 1182'. Drilling and slide from 8700'-9405'. RS, grabber dies. Drilling from 9405-9882'. Deviations: 0.92° @ 8679', 0.79° @ 8870', 0.57° @ 9060', 0.75° @ 9251', 0.57° @ 9441', 0.53° @ 9630', .62° @ 9820'. MW 8.4, Vis 28, pH 9.5, Chl 9400.

08/18/22

Page 5

TIGHT HOLE

Drilling @ 10175'. Made 293'. Formation: Dolo & shale. Drilling 9882'-10083'. Lost full returns @ 10083'. TOH 5 stds. Work pipe every 20 min, mix LCM. Circ shale to pit f/25# per bbl. Pump 300 bbls mud w/25# bbl LCM. Regained returns. SD. Build volume in pits. Mix mud f/vis & waterloss. Add LCM f/25# bbl. Fill premix and mix mud. Pump 50 bbls. Regain circ. Wash & ream 9613-10083. No losses. Drlg f/10083'-10175'. Deviations: 0.62° @ 9820', 0.53° @ 10,010'. MW 8.7, Vis 35, pH 9.

Chl 4800.

DC: \$56,988 CC: \$1,524,669

03/03/21 Drilling @ 10753'. Made 578'. Formation: Limestone. Drilling and sliding 10175'-10285'. Hung up in slide. Work pipe 75k over string wt. to string wt. w/10k torque, came loose. Drlg and sliding f/10285'-10753'. Deviations: 1.45° @ 10,201', 1.1° @ 10,391', 0.97° @ 10,585. MW 8.6, pH 9, Chl 4800.

DC: \$33,484 CC: \$1,558,241

Drilling @ 10753'. Made 0'. Formation: Limestone. TOH f/bit & motor. Break & LD bit & motor. Bit #7. Change motor to 1.75 bend. TIH to 700'. Yest MWD and motor. Trouble shoot MWD. No pulse. Replace 2" hose on top drive. TOH f/MWD failure. Trouble shoot MWD. MWD would not latch into muleshoe all the way. Change out muleshoe & MWD. Test same. Test OK. TIH slow so as not breakdown loss area. Fill pipe every 2000'. Hung up at 6566'. Work pipe with and without pipe. 60k to 280k. Break double and LD same. RU rotary wireline, Free point. Stuck below MWD. Load shot & backoff top 1st monel. Leave 104' tools in hole. LD single. TOH. MW 8.5, Vis 39, pH 9, ChI 6400.

DC: \$90,159 CC: \$1,648,401

Drilling @ 10753'. Made 0'. Formation: Dolomite & Limestone. TOH. LD shot XO. Measure & caliper fishing tools. PU same. Screw in sub, bumper sub, jars, 6-6 ¼" DCs, Excelerator sub. TIH. Wash 60' to fish. Screw in and jar twice, came loose. TOH w/fish. Tight 1st 4 stands. LD fishing tools, shot monel, MWD. PU inspect bit & motor. Stabilizer skirt backed off on motor. LD motor. PU clean motor. Scribe tools and make up 7 blade Halco bit. PU MWD & 1 NMDC. Test motor & MWD. Test OK. TIH filling pipe every 2000' to 6100'. Wash & ream 6070'-6644' w/2 4kwt. Attempt TIH. 10K going down and hung up 6653'. 70k over to pull loose. Wash & ream and back ream w/2K wt., 6644'-7175'. We PU and go back down and nothing there. Acts like what is trying to stick. We are pushing down hole. Mud loggers say it is all 90% dolomite & 10% limestone. If we put more 2K on it, it tries to stick, torques up & takes 50-70k to pull out of it. MW 8.5, Vis 39, pH 9, ChI 6400.

DC: \$47,862 CC: \$1,696,263

08/18/22

Page 6

TIGHT HOLE

03/06/21

Drilling @ 10,753'. Made 0'. Formation: Dolomite & Limestone. Wash & ream 7175'-8080' w/1-2 KWT. RS. Wash & ream 8180'-8339'. Reaming went from 90 FPH to 30 FPH w/excessive torque. Keeps stalling motor & top drive out. TOH to check bit & motor. Remove MWD. Break bit & motor, bit full gauge w/a few chipped cutters on heel row. Motor drained good. No slack no visible problems w/motor. Have Halco 8 1/2" MMD75 PDC w/5X16's 7 blade to run. MW 8.5, Vis 44, pH 9.5, Chl 7000.

DC: \$46.434

CC: \$1,742,697

03/07/21

Drilling @ 11,365'. Made 612'/24 hrs. Formation: Limestone, Shale, Sand Stone. Cut drlg line. MU 8 1/2" Halco Bit. Test MWD & motor, test OK. TIH filling pipe every 2000'. Wash & ream 120' to btm, 2' fill. Drilling and sliding f/10,753' - 11,365'. Deviations: 0.57° @ 10,770', 0.75° @ 10,961', 0.57° @ 11,152. MW 8.5, Vis 44, pH 9.5, Chl 7000.

DC: \$41,003

CC: \$1,783,700

03/08/21

Drilling @ 11,690'. Made 325'/24 hrs. Formation: Limestone, Shale, pyrite. Drlg 11,365'-11,442'. Circ btms up. Try to get to drill. No success. TOH. No drag or problems. Hole in great shape. LD MWD, bit & motor. PU clean motor, 6 blade PDC w/13mm cutter. MU NMDC's, scribe tools. Install MWD. Test MWD & motor, test OK. TIH filling pipe every 2000'. Continue drilling f/11,442' – 11,690'. Deviations: 0.35° @ 11,342', 0.57° @ 11,534'. MW 8.6, Vis 45, pH 9.5, Chl 5800.

DC: \$46,506

CC: \$1,830,205

03/09/21

Drilling @ 12,013'. Made 323'/24 hrs. Formation: Limestone, Shale. Drlg 11,690'-11,717'. Lost all diff press. 5000# torque, ROP quit. Circ btms up. Try to get to drill. No success. TOH. No drag or problems. Hole in great shape. LD MWD, bit & motor. PU clean motor, Halco 7 blade PDC w/13mm cutter. MU NMDC's, scribe tools. Install MWD. Test MWD & motor, test OK. TIH filling pipe every 2000'. Ream 120' to btm. Continue drilling f/11,717' - 12,013'. Deviations: 0.53° @ 11,724', 0.66° @ 11,912'. MW 8.6, Vis 46, pH 9.5, Chl 5800.

DC: \$50.540

CC: \$1,880,745

03/10/21

Drilling @ 12,510'. Made 497'/24 hrs. Formation: Chert, Limestone, Shale. Drlg 12,013'-12,510'. Circ 12,500' sample. Formation 80% chert, 10% lime & 10% shale w/pyrite. TOH for bit. Will PU Smith Z813, 8 blade w/13MM cutters, 8x16's, bit #11. chipped cutters heel & center. Remove MWD. Break bit, ck motor, install Z813 Smith. Install MWD and test motor and MWD. Test OK. TIH w/DC's & directional tools. Cut drlg line. Deviations: 0.53° @ 11,724', 0.66° @ 11,912'. MW 8.6, Vis 46, pH 9.5, ChI 5800.

DC: \$74,065

CC: \$1,954,810

08/18/22

Page 7

TIGHT HOLE

- 03/11/21 Drilling @ 12,926'. Made 416'/24 hrs. Formation: Chert, Limestone, Shale. Cut drlg line. TIH w/bit #12, filling pipe every 2000'. Wash 60' to btm. Drlg 12,510'-12,925'. Attempt to drill, 0# diff, 5200# torque. Drlg f/12,925'-12,926'. Circ btms up. TOH f/bit and motor. Tight f/12,670'-12,340'. Had to pump out. Deviations: 0.62° @ 12,477'. 0.53° @ 12,665', .79° @ 12,853'. MW 8.6, Vis 43, pH 10, Chl 4900.
 - DC: \$29,571 CC: \$1,984,381
- Drilling @ 12,926'. Made 0'/24 hrs. Formation: Chert, Limestone, Shale. TOH f/bit & 03/12/21 motor. LD MWD, motor, bit. PU Halco 7 blade GTD74DHEW/7x20's. Clean motor MWD. Test MWD & motor. RS. TIH filling pipe every 2500'. At 7210' pipe would not circ. TOH to find what is plugged to directional tools. LD MWD, monels in mousehole. Muleshoe plugged w/fine cuttings. Unplug same. LD stabilizer. Ck motor. Pump thru same, OK. MU stabilize, UBHO. Install muleshoe. PU monels & MWD. Test motor & MWD. Test OK. Jet & clean sand trap & half shale pit. Build volume. TIH filling pipe every 2500'. MW 8.6, Vis 43, pH 10, Chl 4900. DC: \$49,583 CC: \$2.033.964
- 03/13/21 Drilling @ 13,530'. Made 604'/24 hrs. Formation: Limestone. TIH filling DP every 2000'. Wash 110' to btm, 5' fill. Drilling f/12,926' - 13,530'. Deviations: .84° @ 13,042', 1.1° @ 13,231'. MW 9.0, Vis 46, pH 9, Chl 4600. DC: \$51,350 CC: \$2,085,314
- Drilling @ 13,800'. Made 270'/24 hrs. Formation: Limestone, dolomite. Drilling 03/14/21 f/13,530'-13,665'. Circ samples @ 13,665'. Drlg f/13,665' - 13,690'. Circ samples @ 13,690'. Drlg f/13,690'-13,764'. Circ samples @ 13,764'. Drlg f/13,764'-13,800'. Circ sample @ 13,800'. 25 stand short trip to 11,500'. Circ f/logs. Work pipe every 20 min. TOH f/logs. Schlumberger to be on location @ 10:00 A.M. Deviations: 1.93° @ 13,609', 2.11° @ 13,740'. MW 9.0, Vis 52, pH 9, Chl 4600. DC: \$43,581 CC: \$2,128,895
- TD @ 13,800'. Formation: Limestone, dolomite. TOH w/DP & DC's. LD directional 03/15/21 tools. Load out same. RU & log w/Schlumberger. Loggers depth 13,780'. RD loggers. WO orders. DC: \$59,522 CC: \$2,188,417
- 03/16/21 WO orders. TIH opened slow w/DP & DCs on top, 60 MPH wind. Circ btms up. RU Byrds LD Machine & safety meeting. LD 166 1/4" DC's. Total 443'. PU 15 jts 4 1/2", 16.6 DP, total 474'. DC: \$58,593 CC: \$2,247,010

08/18/22

Page 8

TIGHT HOLE

Circ & WO Schlumberger. Set 1st plug @ 13,782', 10 bbls CW7 front, 88 sks, 17 bbls Class H @ 16.4#, 3 bbls FW, 183.6 bbls drlg mud. SD. Knock swedge off. LD 69 jts DP. Circ 1 ¼ hr. 2nd plug @ 11,611', 10 bbls CW 7, 70 sks, 13.3 bbls 16.4#, Class H, 3 bbls FW, 153.3 bbls drlg mud. LD 74 jts DP, circ 1 hr. Set 3rd plug @ 9264', 10 bbls CW 7, 60 sks, 11.3 bbls Class H @ 16.4#, 3 bbls FW, 120.1 bbls drlg mud. LD 70 jts DP, circ 1 hr. 4th plug @ 7044', 10 bbls CW 7, 49 sks, 9.3 bbls Class C neat @ 16.4#, 3 bbls FW, 89.4 bbls drlg mud. LD 37 jts DP. Circ. 5th plug @ 5869', 63 sks, 10 bbls CW7, 15 bbls Class C @ 16.4#, 3 bbls FW, 71.8 bbls drlg mud. TOH 5 stands, circ & WOC. HGave to tag plug at btm intermediate csg. Cmt still wet.

DC: \$19,932 CC: \$2,266,942

O3/18/21 Circ & WOC. Cmt still wet, 8:45 A.M. TIH w/3 stands. Tag cmt 5650'. LD 99 jts DP. TIH w/2 stands. Circ, set plug #6 @ 2727', 10 bbls CW 7, 32 sks. 7.2 bbls CLACC C @ 14.8#, 3 bbl FW, 28.3 bbls drlg fluid. LD 34 jts DP, circ @ 1648'. Set plug #7 @ 1648', 10 bbls CW7, 32 sks, 702 bbls class C @ 14.8#, 3 bbl FW, 13 bbls drlg mud. LD 34 jts, circ @ 444'. Set plug #8, 10 bbls CW 7, 32 sks, 7.6 bbls Class C @ 14.8#, 3 bbls FW, 2.2 bbls drlg fluid. LD 12 jts DP. Set top plug #9. 9.6 bbls FW, 20 sks, 4.2 bbls Class C @ 14.8#, 2.4 bbls FW. Remove wear bushing. ND BOP equipment manifold, rotating head, rental Spool. Clean pits w/Duke trucking. DC: \$160,115 CC: \$2,427,057

03/19/21 Released rig 16:00 P.M. 3/20/21. All equipment will be released today. Will start moving Norton #2 off this weekend. Will have all equipment off by Tuesday. FINAL REPORT.


N. SAUNDERS 26 STATE #1

150' FNL & 1900' FWL (LOT C), SEC 26, T14S-R33E
LEA COUNTY, NEW MEXICO
LAT 33.082310 N & LONG 103.586969 W

API#: 30-025-46336

OPERATOR: GREAT WESTERN DRILLING Co.

Spud date:	2/11/2021	1
Elevations:	GL	4195'
	GL-KB	17'
	KB	4212'



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 135571

COMMENTS

Operator:	OGRID:
GREAT WESTERN DRILLING CO	9338
P.O. Box 1659	Action Number:
Midland, TX 79701	135571
	Action Type:
	[C-103] Sub. Plugging (C-103P)

COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM	9/21/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 135571

CONDITIONS

Operator:	OGRID:
GREAT WESTERN DRILLING CO	9338
P.O. Box 1659	Action Number:
Midland, TX 79701	135571
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Need C103Q and marker pics to release	9/20/2022