

Surface Reclamation Complete Report

Well Name: ALBERT AJH #001

API: 30-015-26720

Well Location: Unit A, Section 21, T20S-R24E; Eddy County, New Mexico

Surface Owner: HENRY TERPENING

Reclamation Complete Date: 7/11/22

Total Acres reclaimed: 1.5 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)		
NMSLO - Loamy (L)	Black Grama	2.0	4.0		
п	Blue Grama	2.0	4.0		
п	Sideoats Grama	2.0	4.0		
п	Sand Dropseed	1.0	2.0		
п	Alkali Sacaton	2.5	5.0		
п	Little Bluestem	2.5	5.0		
Weights should be as pounds of pure live seed.					

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

Position: 032.56471°N / 104.58716°W

Altitude: 3699ft

Datum: NORTH AMERICAN 1983, CONUS



Page 2 of 9



Coreinal kegura	ortorease	122th/12	Aispeeton				Date:	10 / 1	2 / 2022			Page 4 oj
Site Name:	Albert AJ	IH #1										
API Number:	₃₀₋₀ 15	_26720) Plu	g Date:	02_/	22, 2022		Program:	Initial Final	Monitoring Corrective	YES	NO
Was this the last remain	ning or only wel	l on the loc	cation?						rilidi	corrective	I ES	INO
Are there any abandone				location?								
Is there any production	equipment or s	structure (n	not including stee	l marker, poure	d onsite concr	ete bases, or pip						
If any production equip	ment or structu	ıre (includir	ng 3rd party) is to	remain on loca	tion, please sp	oecify.	3rd pa	arty riser	on west s	ide of pad	_	
<u>Site Evaluation</u>												
Recontoured back to	original State	/Topsoil I	Replaced								YES	NO
Have the rat hole and co											 	
Have the cathodic prote Rock or Caliche Surfacin				claimed?							├	
	g materials nav	oc been ren	novcu:									
Section Comments: All Facilities Removed	d for Final Red	clamation									_	
Have all of the pipelines	& production 6	equipment	been cleared? (o	ther than the lis	ted above)						\checkmark	
Has all of the required j											<u> </u>	
Have all of the required		•			at least two f	eet below grour	nd level?					
Have all of the required Have all the required po				removeur							\	
Section Comments:												
Dry Hole Marker											YES	NO
Has a steel marker been	installed ner C	·ΩΔ require	ements?				Check One	: 🔲 Buri	ed 🔽	Above Ground	1	
That a steel marker seen	I motumed per e	.o, equ e					oneon one	<u> </u>		Federal Lease #	Ť	
DHM Info	Operator	Name	Lease Name & I	lumber	UL-S-T-R	Qtr Section	(Footage)	, A	API#	(Federal Only)		
Me			✓		✓						_	
Not Me Free of Oil or Salt Cor		nil						1			YES	NO
Have all the required pit			npliance with OCI	rules and the t	erms of the O	perator's pit pe	rmit and clos	sure plan?			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1
Have all other environm	nental concerns	been addr	essed as per OCD	rules?								
If any environmental co	ncerns remain o	on the loca	tion, please spec	fy							_	
Abandoned Pipelines	=											
Only need to provide and Have all fluids have bee					in accordance	with 19. 15. 35.	10 NMAC).				YES	NO
Have all abandoned pipe		•			NORM , othe	r than that whic	h accumulat	ed under no	ormal operation	on?		
Have all accessible poin	ts of abandoned	d pipelines	been permanent	ly capped?								
Section Comments:												
Last Remaining or On	ly Well on the	e Location	<u>1</u>									
Please answer all questi					going to be a	ny well or facilit	y remaining	at this local	tion.		YES	NO
Have all electrical service Is there any electrical ut	•				ation?						-	/
Have all the battery and						the terms of the	e Operator's	pit permit a	and closure pla	an?	/	
Have all the retrievable	pipelines, prod	uction equi	ipment been rem	oved from the l	ocation?						V	
Has all the junk and tras	sh been remove	d from the	location?								✓	
Section Comments:											_	
<u>iEnvironmental Only-</u> This section corresponds				ion Form in iEn	iironmental hi	it not related to	NMOCD for	me			Met	Not Met
Free of Noxious or Invas					ni omnemur bi	it not related to	WWW.CD JOI	1113.			√ Viet	Not wet
Site Stability? Erosion co	ontrols in place	(if necessa	ry) & working.								V	
Signs of seeding comple							_					
Revegetation Success as			1? Met >75%.		Circle Or	ne: 0%	25%	50%	% 75%	100%		-
Adequate Reclamation I	rence installed:	?									✓	
Section Comments:											_	
Additional Findings o	r Comments:											
										☐ READY FOR FA	N SURMITTAL	
Inspector: Igor Ric	os									☐ NEEDS FURTH	ER REVIEW	
Picture Checklist:	☑ DHM	□	Background	☑ 3rd Party	Fauinment	☐ Contamina	tion \Box				ion Result	
Circoniist.	Site Corners	•	Access Road	EOG Equi		Trash/Junk				PASS		AIL

On-Site_Inspection_Form v1.xlsx

10/20/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 152475

DEFINITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	152475
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 152475

Q	UESTIONS
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377 Action Number: 152475 Action Type:
	[C-103] Sub. Release After P&A (C-103Q)
QUESTIONS	
Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes
If any production equipment or structure is to remain on the location, please specify	3rd party riser on west side of pad.
Site Evaluation Please answer all the questions in this group.	
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes
Poured onsite concrete bases do not have to be removed.	
Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 152475

	(continu	11
	I CONTINI I	וחם

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	152475
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Abandoned Pipelines					
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).					
Have all fluids have been removed from any abandoned pipelines	Not answered.				
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.				
Have all accessible points of abandoned pipelines been permanently capped	Not answered.				

ast Remaining or Only Well on the Location					
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.					
Have all electrical service poles and lines been removed from the location	Yes				
Is there any electrical utility distribution infrastructure that is remaining on the location	No				
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes				
Have all the retrievable pipelines, production equipment been removed from the location	Yes				
Has all the junk and trash been removed from the location	Yes				

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 152475

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	152475
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 152475

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	152475
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	10/21/2022