

Surface Reclamation Complete Report

&

Annual Surface Reclamation Monitoring Report

Well Name: SRC KZ STATE #001

API: 30-015-22891

Well Location: G-01-19S-24E

Surface Owner: YATES RANCH PROPERTY LLP

Reclamation Complete Date: 6/16/21

Reclamation Annual Monitoring Date: 7/12/22

Total Acres reclaimed: 0.5

Seed Mix:

	Species	lb/acre (Drilled)	Ib/acre (Broadcast)
4 Dinkus Ranch (8/13/2019)	Black Grama	3.0	6.0
"	Blue Grama	2.5	5.0
"	Hairy Grama	3.0	6.0
ш	Sideoats Grama	4.5	9.0
· ·	Sacaton, Alkali	3.0	6.0
· ·	Saltbush Four-wing (DeWinged Seed)	2.0	4.0
"	Plains Bristlegrass	1.5	3.0

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.





Silverback tower, not owned by EOG.





Surface Owner Approval of Reclamation completed with Well P&A

Well Name: SRC KZ State #001

API: 30-015-22891

Location: SW/4NE/4 being approximately 0.50 acres in total area.

Section: 1 Township: 19 South Range: 24 East County: Eddy

Surface owner: Yates Ranch Property LLP PO Box 1394 Artesia, NM 88211

I hereby agree that EOG Resources, Inc. has completed all surface reclamation activities to meet our requirements as surface owner for the above noted well. There is a 3rd Party Communication Tower that is operated/owned by Silverback Exploration and is not owned/operated by EOG Resources, therefore it will not be EOG Resources responsibility to remove.

Surface Owner Name: John A. Yates, III
Surface Owner Signature:

EOG Representative Name: Keith Kistner

EOG Representative Signature: ____

Date: 12/21/2022





Surface Owner Approval of Reclamation completed with Well P&A

Well Name: SRC KZ State #001

API; 30-015-22891

Location: SW/4NE/4 being approximately 0.50 acres in total area.

Section: 1 Township: 19 South Range: 24 East County: Eddy

Surface owner: Yates Ranch Property LLP

PO Box 1394 Artesia, NM 88211

I hereby agree that EOG Resources, Inc. has completed all surface reclamation activities to meet our requirements as surface owner for the above noted well. Landowner is requesting for the sign to be left on location and therefore EOG is not responsible for clean-up of same.

Surface Owner Name: John A. Yates, III

Surface Owner Signature:

EOG Representative Name: Keith Kistner

EOG Representative Signature: __



Poseisad kegasa	or l/17/66124 1at/6/1	Hilspeellon		Date:	<u> 1/19/2</u>	<u>2023</u>		P	age 5 of
Site Name:	SRC KZ State #	¹ 001							
API Number:	30-0 15 - 228	Plug Date	<u>4</u> / <u>3</u>	0 / 21	Program: Initia	al	Monitoring		
Mr. d. t. d.					Fina		Corrective	YES	NO
Was this the last remain Are there any abandone	,	ocation? g to remian on the location	n?					<u> </u>	
·		not including steel marker		e bases, or pipelines)	that are going to remai	n on location	on?		
If any production equipn	ment or structure (includ	ling 3rd party) is to remain	on location, please spe	cify. 3rd	d party communic	cation to	wer		
Site Evaluation									
Recontoured back to	original State/Topsoil	Replaced						YES	NO
Have the rat hole and ce	llar been filled and level	ed?						$\overline{}$	
		ly abandoned & reclaimed?							
Rock or Caliche Surfacing		ted material be stoo	kniled at entrand	e.				· ·	
All Facilities Removed			skpilou ut oritiurie					-	
		t been cleared? (other tha	n the listed above)						
Has all of the required ju	ınk and trash been clear	ed from the location?						$\overline{}$	
		downs and risers have beer		t below ground level	?			<u> </u>	
Have all of the required po		aterials have been remove	a?					$\vdash \checkmark$	
Section Comments:	Tuble buses been remo							To a second	
Dry Hole Marker								YES	NO
Has a steel marker been	installed per COA requir	rements?		Check	One: Buried	MAh	ove Ground	V	
rias a steer marker been	Instance per con requir			Creek	Offic		Federal Lease #		
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Foo	tage) API#		(Federal Only)		
Met	·	/	✓	↓				-	
Not Met Free of Oil or Salt Con	taminated Soil							YES	NO
		mpliance with OCD rules a	nd the terms of the Ope	erator's pit permit and	d closure plan?			\ \frac{1}{\sqrt{2}}	
Have all other environm	ental concerns been add	lressed as per OCD rules?							
If any environmental cor									
		areas outside of wellpad l	nave established vege	etation.				-	
Abandoned Pipelines Only need to provide ans		ı pipelines have been abanı	doned (in accordance w	ith 19. 15. 35. 10 NM	IAC)			YES	NO
Have all fluids have beer			zenea (m accordance m	13. 13. 33. 13	7.0,7			123	
		NOT contain additional re	-	han that which accur	mulated under normal o	peration?			
Have all accessible point	s of abandoned pipeline	s been permanently cappe	d?						
Section Comments:	l. Mall on the Leastin							-	
Last Remaining or On		on up, specifically if there is n	o longer going to be any	vwell or facility rema	inina at this location.			YES	NO
·	,	emoved from the location?							
Is there any electrical ut	ility distribution infrastr	ucture that is remaining on	the location?						\vee
		n remediated in complianc		e terms of the Opera	itor's pit permit and clos	ure plan?		<u> </u>	
Has all the junk and tras		uipment been removed fro e location?	on the location?					 \	
Section Comments:									
iEnvironmental Only-	Do not have to be met to	o pass inspection						-	
This section corresponds	with questions on the Re	eclamation Inspection Forn	n in iEnvironmental but	not related to NMOC	D forms.			Met	Not Met
		es or treatment in remarks)						V	
Site Stability? Erosion co Signs of seeding complet								\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Revegetation Success as			Circle One:	: 0%	25% 50%	75%	100%	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Adequate Reclamation F								_	—
Section Comments:									
Additional Findings or	r Comments	Sign & fence installe	ed per Land owne	er request					
			-	-					
D MAD	PID						READY FOR FA	N SUBMITTAL	
Inspector: B.MADI						_	☐ NEEDS FURTHI	ER REVIEW	
Picture Checklist:	□ DHM ☑	Background 🗸	3rd Party Equipment	Contamination					A.I.
			EOG Equipment	√ Trash/Junk		(PASS		AIL

On-Site_Inspection_Form v1.xlsx

10/20/2022

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 180302

DEFINITIONS

Operator:		OGRID:
E	EOG RESOURCES INC	7377
P	P.O. Box 2267	Action Number:
N	/lidland, TX 79702	180302
		Action Type:
		[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 180302

OGRID:
180302 Action Type:
Action Type:
**
Yes
No
Yes
3rd party, Silverback, communication tower.
Not answered.
Yes
Yes
Yes
THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Yes
Yes
Yes
No discernible drilling pit located and all areas outside of well pad have established vegetation.

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 180302

QUESTIONS (continued)

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	180302
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location			
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.			
Have all electrical service poles and lines been removed from the location	Yes		
Is there any electrical utility distribution infrastructure that is remaining on the location	No		
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes		
Have all the retrievable pipelines, production equipment been removed from the location	Yes		
Has all the junk and trash been removed from the location	Yes		

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 180302

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	180302
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 180302

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	180302
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By		Condition Date
gcordero	None	2/9/2023