nt Report 01/30/2023
ate: LEA /
me:
OIL AND

Subsequent Report

Sundry ID: 2668338

Type of Submission: Subsequent Report

Date Sundry Submitted: 06/16/2022

Date Operation Actually Began: 06/01/2022

Type of Action: Plug and Abandonment

5

Time Sundry Submitted: 12:15

Actual Procedure: Notified BLM Lea COunty office and left message in general mailbox since no one answered the phones. RIH and tagged CIBP @ 5110'. Circulated well with plugging mud. Spotted 35 sacks (8 bbls) Cement on top of CIBP. Pulled 4 stands. Rig in hole and tagged cement at 4958'. Pulled up to 4345' and spotted 35 sacks (8 bbls) cement from 4345'to 4205'. Pulled up to 2997' and spotted 35 sacks from 2996' to 2867'. Pulled back 4 stands and shut down for the day. Tagged cement at 2853'. Tripped out of hole. Rig in hole with wireline at 620'. Shot 4 shots, pull out of hole with wireline and rig in hole with packer. Packer was set at 600'. Attempted to pump into perfs. PSI reached 1750 and held for 15 minutes as per CM. Continued moving up and pulled out of hole with packer. Rigged in hole open ended and spotted 35 sacks (8 bbls) cement from 670' to 520'. Stood 4 stands and waited on cement. Tagged Cement at 503'. Pulled out of hole and left location. Rig in hole 60' and spotted cement from 60' to surface. Pull out of hole and top off cement to surface. Wash up pump and equipment. Rigged down and left location. Attached a copy of the current well bore diagram. Final reclamation will be done under a separate sundry.

Accept	ed for record – NMOCD
JRH	05/03/2023

Received by OCD: 1/30/2023 Well Name: JCT FEDER		Location: T9S / R37E / SEC 24 / E / 33.525817 / -103.100217	County or Parish/State: LEA7
Well Number: 1	Туре	of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM	080255 Unit	or CA Name:	Unit or CA Number:
US Well Number: 3002	538569 Well	Status: Plugged and Abandoned	Operator: SEGURO OIL AND GAS LLC

SR Attachments

Actual Procedure

Current_WBD_Jct_24__1_20220616121319.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: DONNA STURDIVANT

Name: SEGURO OIL AND GAS LLC

Title: Regulatory Clerk

Street Address: 407 N, BIG SPRING ST. SUITE 215

City: Midland

Phone: (432) 219-0740

Email address: dmsreg2014@yahoo.com

Field

Representative Name:

Street Address:

Email address:

City:

Phone:

State:

State: TX

BLM Point of Contact

BLM POC Name: JAMES A AMOS BLM POC Phone: 5752345927 Disposition: Accepted Signature: James A. Amos BLM POC Title: Acting Assistant Field Manager BLM POC Email Address: jamos@blm.gov Disposition Date: 09/03/2022


Zip:

Signed on: JUN 16, 2022 12:15 PM

SEGURO OIL AND GAS, LLC P.O. Box 3176 MIDLAND, TEXAS 79702

Lease JCT I	Federal 24 Well No 1 Location 438 FNL and 860 FEL
County_Lea Coun	tySTNM_Section24TwnShp9SRng37E
API NUMBER	30-025-38569 Page 1
DATE	DAILY REPORTS
May 23, 2022	BLM Lea County office was notified by Paul Anderson. A message was left in their general mailbox since no one was answering the phones. The rig had trouble getting out there that week and with the holiday they were delayed until the first day of June 2022.
June 1, 2022	Arrived on location and company held safety meeting. Finished rigging up. RIH and tagged CIBP @ 5110'. Circulated well with plugging mud. Spotted 35 sacks (8 bbls) Cement on top of CIBP. Pulled 4 stands. Rig in hole and tagged cement at 4958'. Pulled up to 4345' and spotted 35 sacks (8 bbls) cement from 4345' to 4205'. Pulled up to 2997' and spotted 35 sacks from 2996' to 2867'. Pulled back 4 stands and shut down for the day.
June 2, 2022	Arrived on location and company held a safety meeting. Tagged cement at 2853'. Tripped out of hole. Rig in hole with wireline at 620'. Shot 4 shots, pull out of hole with wireline and rig in hole with packer. Packer was set at 600'. Attempted to pump into perfs. PSI reached 1750 and held for 15 minutes as per CM. Continued moving up and pulled out of hole with packer. Rigged in hole open ended and spotted 35 sacks (8 bbls) cement from 670' to 520'. Stood 4 stands and waited on cement. Tagged Cement at 503'. Pulled out of hole and left location.

June 3, 2022 Arrived on location and company held a safety meeting. Rig in hole 60' and spotted cement from 60' to surface. Pull out of hole and top off cement to surface. Wash up pump and equipment. Rigged down and left location.



Released to Imaging: 5/3/2023 2:01:29 PM

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
SEGURO OIL AND GAS, LLC	372066
407 N Big Spring St, Ste 200	Action Number:
Midland, TX 79702	99454
	Action Type:
	[C-103] Sub. Plugging (C-103P)
CONDITIONS	

Created By		Condition Date		
john.harrison	None	5/3/2023		

CONDITIONS

Action 99454

Page 5 of 5