Print

Clear

Page 1 of 4

Form 3160-5 (June 2015)

Notice of Intent

Subsequent Report

is ready for final inspection.)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM-0177517

6. If Indian, Allottee or Tribe Name

Production (Start/Resume)

Reclamation

Recomplete

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

Acidize

Alter Casing

Casing Repair

abandoned well. U	Jse Form 3160-3 (A	PD) for such proposals.	
SUBMIT IN 1	SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit of CA/Agreement, Name and/or No. NMNM-82050X
Oil Well Gas W	Vell Other		8. Well Name and No. CATO SAN ANDRES UNIT #106
2. Name of Operator OXY USA INC.			9. API Well No. 30-005-20056
3a. Address PO BOX 4294 HOUSTON, TX 77210		3b. Phone No. (include area code) (972) 404-3722	10. Field and Pool or Exploratory Area CATO; SAN ANDRES
4. Location of Well (Footage, Sec., T.,R	.,M., or Survey Description))	11. Country or Parish, State
1980 FSL, 660 FEL, UNIT L, SEC	15, T8S R30E		CHAVES
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE OF N	OTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF .	ACTION

Final Abandonment Notice Convert to Injection Plug Back Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site

Hydraulic Fracturing

New Construction

Deepen

PLEASE SEE ATTACHED FINAL WELLBORE DIAGRAM AND FINAL PLUGGING REPORT. WELL IS NOW PLUGGED.

Accepted for Record - contact Rick Flores at rflores@blm.gov for reclamation.

Accepted for record – NMOCD

JRH — 05/09/2023 ——

Water Shut-Off

Well Integrity

Other

14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>) SARAH MCKINNEY	REGULATORY ANALYST SR.			
Signature Sauch Mckinny	Date	02/21/2	2023	
THE SPACE FOR FEDE	ERAL OR S	TATE OFICE USE		
Approved by	Title Pe	troleum Engineer	02/21/2023 Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.		RFO		

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

CASU 106 30-005-20056

Final PA Report: 01/23/2023 - 01/30/2023

01/23/2023: Crew HTGSM. Road Pulling Unit & all Plugging Equipment from Bravo Dome 271 to Cato San Andres 106. Spot in Equipment. Secure Well. SION


01/25/2023: Crew HTGSM. Spot in Base Beam & Pulling Unit. R/U Pulling Unit. 0 PSI on TBG & CSG. Remove Polish Rod. L/D 124-3/4 Rods & 12-7/8 Rods & Pump. Spot in Cat Walk, Pipe Racks & WS TBG. SION

01/26/2023: Crew HTGSM. Function Test BOPE. 0 PSI on TBG & CSG. Remove Larkin wellhead. ND BOPE & Working Floor. L/D 110 JT's of 2-3/8 production TBG. R/U Key Wireline.RIH w/ 3-3/4 Gauge Ring to 3350'. POOH w/ wireline. RIH w/ 4.5 CIBP. Set @ 3336'. POOH w/ wireline & Rig down. P/U 107 Jt's of 2-3/8 WS TBG. Tag CIBP. Install TIW Valve. Close BOPE & all valves. SION

01/27/2023: Crew HTGSM. 0 PSI on TBG & CSG. Circulate well w/ 60 BBL's of FW. PSI Test CSG to 500 PSI & held good. Circulated well w/ 35 BBL's of 10# salt gel. Spotted 7 BBLs (30 sxs) of Class C CMT & displaced to 2806 w/ 11 BBLs of 10# salt gel. POOH w/ 30 JTs of TBG & L/D 14 Jt's of TBG. Crew conduct BOPE Closing Drill. WOC. RIH w/ TBG & Tag Top of CMT @ 2792 w/ 92 JT's of TBG. L/D 40 Jt's of TBG. to 1625'. Spot 10.7 BBL (45 sxs) of Class C CMT & displaced to 960' w/ 4 BBLs of BW. L/D 52 Jt's of WS TBG. Close BOPE & Lock Pins. Close all valves. SION

01/30/2023: Crew HTGSM. 0 PSI on CSG. Rig up Key Wireline. RIH w/ Perf Gun. Tag CMT @ 963'.

Perforate CSG @ 505'. POOH w/ WL & RD. Est Injection Rate @ 2 BPM @ 600 PSI w/ 35 BBL's of BW. ND BOPE & NU WH. Pump 54 BBLs (225 sxs) of Class C CMT & Circulated CMT to surface. Close all Valves. Rig down Pulling Unit. Rig down Remaining Plugging Equipment. Well is Plugged



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 215020

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	215020
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
john.harrison	None	5/9/2023