

Well Name: MOJAVE AJY COM	Well Location: T20S / R23E / SEC 35 / SWSE /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: FEE	Unit or CA Name: MOJAVE AJY COM 1	Unit or CA Number: NMNM87890
US Well Number: 300152853100S1	Well Status: Producing Oil Well	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2708246
Type of Submission: Subsequent Report
Date Sundry Submitted: 12/20/2022
Date Operation Actually Began: 12/05/2022
Type of Action: Reclamation
Time Sundry Submitted: 09:43

Actual Procedure: P&A Reclamation and re-seeding was completed on 12/5/2022. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2023 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

MOJAVE_AJY_COM_2_CRR_2022_12_15_20221220094304.pdf

Received by OCD: 6/19/2023 3:16:14 PM

Page 2 of 7

Well Name: MOJAVE AJY COM	Well Location: T20S / R23E / SEC 35 / SWSE /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: FEE	Unit or CA Name: MOJAVE AJY COM 1	Unit or CA Number: NMNM87890
US Well Number: 300152853100S1	Well Status: Producing Oil Well	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: DEC 20, 2022 09:43 AM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY	BLM POC Title: Legal Instruments Examiner
BLM POC Phone: 5752345931	BLM POC Email Address: dmckinne@blm.gov
Disposition: Accepted	Disposition Date: 06/16/2023
Signature: Deborah McKinney	



Surface Reclamation Complete Report

Well Name: MOJAVE AJY COM #002

API: 30-015-28531

Well Location: O-35-20H-23E

Surface Owner: BLM

Reclamation Complete Date: 12/5/22

Total Acres reclaimed: 4.25 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

Pipeline marker with a sign left on location.



Date & Time: Mon Dec 5 10:06:57 MST 2022
Position: 032.51681°N / 104.57038°W
Altitude: 3706ft
Datum: NORTH AMERICAN 1983, CONUS
Azimuth/Bearing: 264° S84W 4693mils (True)
Zoom: 1X
I. Rios



On-Site Regulatory Reclamation Inspection							Date: 12 / 05 / 2022	
Site Name: Mojave AJY Com #002								
API Number: 30-0 15 28531		Plug Date: 05 / 12 / 2021		Program: Initial		Monitoring		
				Final		Corrective		
Was this the last remaining or only well on the location?							YES	NO
Are there any abandoned pipelines that are going to remain on the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
If any production equipment or structure (including 3rd party) is to remain on location, please specify.								
Risers on the west side of pad.								
Site Evaluation								
Recontoured back to original State/Topsoil Replaced							YES	NO
Have the rat hole and cellar been filled and leveled?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have the cathodic protection holes been properly abandoned & reclaimed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rock or Caliche Surfacing materials have been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
All Facilities Removed for Final Reclamation								
Have all of the pipelines & production equipment been cleared? (other than the listed above)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has all of the required junk and trash been cleared from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all of the required metal bolts and other materials have been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the required portable bases been removed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Dry Hole Marker							YES	NO
Has a steel marker been installed per COA requirements?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground								
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)		
Met	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
Not Met								
Free of Oil or Salt Contaminated Soil							YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all other environmental concerns been addressed as per OCD rules?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
If any environmental concerns remain on the location, please specify.								
Abandoned Pipelines							YES	NO
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NM4C).							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all fluids have been removed from any abandoned pipelines?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all accessible points of abandoned pipelines been permanently capped?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Last Remaining or Only Well on the Location							YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all electrical service poles and lines been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Is there any electrical utility distribution infrastructure that is remaining on the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Have all the retrievable pipelines, production equipment been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Has all the junk and trash been removed from the location?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Environmental Only - Do not have to be met to pass inspection							Met	Not Met
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Site Stability? Erosion controls in place (if necessary) & working.							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Signs of seeding completion? (Broadcast/Drilled)							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Revegetation Success as compared to background? Met > 75% Circle One: <input checked="" type="radio"/> 0% <input type="radio"/> 25% <input type="radio"/> 50% <input type="radio"/> 75% <input type="radio"/> 100%							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Adequate Reclamation Fence Installed?							<input checked="" type="checkbox"/>	<input type="checkbox"/>
Section Comments:								
Additional Findings or Comments: pipeline marker with sign left on location								
Inspector: Igor Rios								
Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/>							<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW Inspection Result <input checked="" type="radio"/> PASS <input type="radio"/> FAIL	
<input checked="" type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/>								

On-Site_Inspection_Form v1.xlsx

10/20/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 230328

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230328
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	9/29/2023