

Well Name: JUDITH AIJ FED	Well Location: T20S / R24E / SEC 9 / SESE /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM39121	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152663200X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2721358

Type of Submission: Subsequent Report	Type of Action: Reclamation
Date Sundry Submitted: 03/16/2023	Time Sundry Submitted: 01:36
Date Operation Actually Began: 10/24/2022	

**Actual Procedure:** P&A Reclamation and re-seeding was completed on 10/24/2022. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2024 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

JUDITH\_AIJ\_FEDERAL\_1\_CRR\_2022\_10\_25\_20230316133603.pdf

Well Name: JUDITH AIJ FED	Well Location: T20S / R24E / SEC 9 / SESE /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM39121	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152663200X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: MAR 16, 2023 01:36 PM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY	BLM POC Title: Legal Instruments Examiner
BLM POC Phone: 5752345931	BLM POC Email Address: dmckinne@blm.gov
Disposition: Accepted	Disposition Date: 06/16/2023
Signature: Deborah McKinney	



## Surface Reclamation Complete Report

**Well Name:** JUDITH AIJ FEDERAL #001

**API:** 30-015-26632

**Well Location:** P-09-20S-24E

**Surface Owner:** BLM

**Reclamation Complete Date:** 10/24/22

**Total Acres reclaimed:** 2.75 acres

**Seed Mix:**

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Black Grama	2.0	4.0
"	Blue Grama	2.0	4.0
"	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
"	Little Bluestem	2.5	5.0
"	Firewheel (Gaillardia)	1.0	2.0
"	Fourwing Saltbush	1.0	2.0
"	Common Winterfat	0.5	1.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

3<sup>rd</sup> party riser on SW side of pad. Valve box and riser on SE side of road by pad entrance.











On-Site Regulatory Reclamation Inspection							Date: 10 / 24 / 2022	
Site Name: Judith AIJ Federal #001								
API Number: 30-015-26632		Plug Date: 04 / 08 / 2022		Program: Initial		Monitoring		
				Final		Corrective		
Was this the last remaining or only well on the location?							YES	NO
Are there any abandoned pipelines that are going to remain on the location?							✓	
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?							✓	✓
If any production equipment or structure (including 3rd party) is to remain on location, please specify. 3rd party riser on SW side of pad Valve box & riser on SE side of road by pad entrance.								
<b>Site Evaluation</b>								
Recontoured back to original State/Topsoil Replaced							YES	NO
Have the rat hole and cellar been filled and leveled?							✓	
Have the cathodic protection holes been properly abandoned & reclaimed?							✓	
Rock or Caliche Surfacing materials have been removed?							✓	
Section Comments:								
<b>All Facilities Removed for Final Remediation</b>								
Have all of the pipelines & production equipment been cleared? (other than the listed above)							✓	
Have all of the required junk and trash been cleared from the location?							✓	
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							✓	
Have all of the required metal bolts and other materials have been removed?							✓	
Have all the required portable bases been removed?							✓	
Section Comments:								
<b>Dry Hole Marker</b>							YES	NO
Has a steel marker been installed per COA requirements?							✓	
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground								
DHM Info	Operator Name	Lease Name & Number	UL-S-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)		
Met	✓	✓	✓	✓	✓	✓		
Not Met								
<b>Free of Oil or Salt Contaminated Soil</b>							YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							✓	
Have all other environmental concerns been addressed as per OCD rules?							✓	
If any environmental concerns remain on the location, please specify.								
<b>Abandoned Pipelines</b>							YES	NO
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).								
Have all fluids have been removed from any abandoned pipelines?							✗	
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?							✗	
Have all accessible points of abandoned pipelines been permanently capped?							✗	
Section Comments:								
<b>Last Remaining or Only Well on the Location</b>							YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.								
Have all electrical service poles and lines been removed from the location?							✓	
Is there any electrical utility distribution infrastructure that is remaining on the location?								✓
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							✓	
Have all the retrievable pipelines, production equipment been removed from the location?							✓	
Has all the junk and trash been removed from the location?							✓	
Section Comments:								
<b>Environmental Only: Do not have to be met to pass inspection</b>							Met	Not Met
This section corresponds with questions on the Reclamation Inspection Form in iEnvironmental but not related to NMOC forms.								
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							✓	
Site Stability? Erosion controls in place (if necessary) & working.							✓	
Signs of seeding completion? (Broadcast/Drilled)							✓	
Revegetation Success as compared to background? Met >75%								✓
Circle One: 0% 25% 50% 75% 100%							N	A
Adequate Reclamation Fence Installed?								
Section Comments:								
Additional Findings or Comments: Two track road going north on east side of road by pad entrance.								
Inspector: Igor Rios								
Picture Checklist: <input checked="" type="checkbox"/> OHM <input checked="" type="checkbox"/> Background <input checked="" type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> <input type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> <input type="checkbox"/>								
<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW <b>Inspection Result</b> <input checked="" type="radio"/> PASS <input type="radio"/> FAIL								

On-Site\_Inspection\_Form v1.xlsx

10/20/2022



**From:** [Bruelhart, Alex J.](#)  
**To:** [Jennifer Palma](#); [Terry, Diane J.](#); [Brown, Nikki N.](#); [Maitlen, K'Lee D.](#)  
**Cc:** [Gibson, Raul](#); [Espino, Cesar M.](#); [Corral, Alfredo V.](#); [Ziegler, Rick L.](#)  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal - additional locations  
**Date:** Friday, July 22, 2022 8:55:46 AM  
**Attachments:** [image002.png](#)

---

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you Jennifer! If there are any questions please let me know.

Nikki/Diane please see Jennifer's email below. If these meters are active please move forward with TA. I can have Alfredo pull the meters if need be.

K'Lee, please add these locations below to our list of meter run removals.

### ***Alex Bruelhart***

Versado Area

[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)

Cell: 918-894-1360



---

**From:** Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>  
**Sent:** Friday, July 22, 2022 9:49 AM  
**To:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>  
**Subject:** [EXTERNAL] Measurement Equipment Removal - additional locations

**CAUTION:** This email originated from outside of Targa. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good Morning Alex,

I've 4 additional locations that have been or are being P&A that need to have Targa meters removed. They are as follows:

Rokesmith BDI State Com #1: 33.3923569,-103.475029

Mattea BFA State #1: 33.398571,-103.4379272

Hummingbird ADM State #1: 32.9381714,-103.2655716, quick note on this one: EOG sold this well effective 5/2021 but took it back over effective 6/2022.

Kemnitz South AFL State #1: 32.8730278,-103.5981293, quick note on this one: EOG sold this well effective 5/2021 but took it back over effective 6/2022. Also, my field production technician that has been working on decommissioning this location indicated that the meter # is unreadable but the line on the downstream side of the meter run has been marked so he was able to tell it's a Targa meter.



Please let me know if you have any questions.

Have a great weekend!!!

Jen

*Jennifer Palma*  
*Lead Operations Assistant*  
*EOG Resources, Inc*  
*Artesia Division*  
*104 South 4<sup>th</sup> Street*  
*Artesia, NM 88210*  
*Office Phone: (575) 748-4149*  
*Cell Phone: (575) 513-8394*  
*Email: [Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)*

---

**From:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>  
**Sent:** Monday, July 18, 2022 10:50 AM  
**To:** Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Morning Jennifer, we have removed and ATD' d each of the actual meters on location. We have not removed any of the physical meter runs. Our tracking list for removal has been updated and our crew(s) will get to each of them as they come up on the list.

***Alex Bruelhart***

Versado Area

[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)

Cell: 918-894-1360



---

**From:** Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>  
**Sent:** Monday, July 18, 2022 9:36 AM  
**To:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>

**Cc:** Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

Good Morning Alex,  
Could I get an update on any progress that has been made on the removal of measurement equipment please?

If you require anything further from me please let me know.

Sincerely,  
Jennifer

*Jennifer Palma*  
*Lead Operations Assistant*  
*EOG Resources, Inc*  
*Artesia Division*  
*104 South 4<sup>th</sup> Street*  
*Artesia, NM 88210*  
*Office Phone: (575) 748-4149*  
*Cell Phone: (575) 513-8394*  
*Email: [Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)*

---

**From:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>  
**Sent:** Monday, May 23, 2022 1:20 PM  
**To:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>; Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

Alex,  
below would be the priority that these are needing to be removed in. The sooner the better to prevent any reclamation issues. Thanks for your assistance in this, please let me know if you have any questions Thanks.

Strait BLN State Com #4  
Strait BLN State Com #5  
Judith AIJ Federal #1  
Merle BOJ State Com #11  
Elvis BOV State Com #1  
Gato Loco BFT Com #1  
Jerry Jeff BED State Com #1  
Judson AUU State Com #2  
Abby BLF State Com #1

McBride BEH State Com #1

Christopher Gurule  
Measurement & Automation Foreman  
EOG Resources, INC  
Artesia Division  
O: 575-748-4224  
C: 575-703-4243  
[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)

---

**From:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>  
**Sent:** Monday, May 16, 2022 9:51 AM  
**To:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>; Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

George, according to ROW we don't need to remove out down leg at any of these sites but we can remove the measurement equipment. I can not at this time give you any kind of time frame of when this will happen. If you could send me a list of the higher priority leases for you. Then I can possibly squeeze in our crew between other maintenance projects. Just let me know. Thanks

**Alex Bruelhart**

Versado Area  
[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)  
Cell: 918-894-1360



---

**From:** Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>  
**Sent:** Monday, May 16, 2022 10:25 AM  
**To:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>; Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>



**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

All,

Please see my below notes as to the removal obligations per each of these easements.

Gato Loco BFT Com#1 33.57508,-103.49868- No removal obligations referenced.  
Strait BLN St Com #5 33.4305763,-103.4916382- No removal obligations referenced.  
Judson AUU St Com#2 33.4127235,-103.4325104- No removal obligations referenced.  
Abby BLF St #1 33.5426,-103.55593- No removal obligations referenced.  
Mcbride BEH ST #1 33.4775696,-103.4753876- No removal obligations referenced.  
Jerry Jeff BED St Com #1 33.4587364,-103.5072021- No removal obligations referenced.  
Merle BOJ ST COM#11 33.467083,-103.4281311- No removal obligations referenced.

Thanks,  
Colton Rainey  
ROW Agent  
Targa Resources  
(432) 248-9519  
[crainey@targaresources.com](mailto:crainey@targaresources.com)



---

**From:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>  
**Sent:** Wednesday, May 11, 2022 1:48 PM  
**To:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>; George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>; Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>; Jennifer Palma <[Jennifer\\_Palma@eogresources.com](mailto:Jennifer_Palma@eogresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

Not sure if you already got this info but if not please see below. Let us know if you need anymore info.

---

**From:** Bruelhart, Alex J. <[abruelhart@targaresources.com](mailto:abruelhart@targaresources.com)>  
**Sent:** Thursday, April 28, 2022 4:21 PM  
**To:** George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>  
**Cc:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>; Rainey, Colton D. <[crainey@targaresources.com](mailto:crainey@targaresources.com)>; Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>  
**Subject:** RE: [EXTERNAL] Measurement Equipment Removal

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

George, can you send me some GPS points? We have a couple thousand meter runs and its just easier to locate them with a GPS. I've also CC'd our ROW department to check any removal requirements listed in our easements. Thanks

***Alex Bruelhart***

Versado Area

[abruehart@targaresources.com](mailto:abruehart@targaresources.com)

Cell: 918-894-1360



---

**From:** George Flores <[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)>

**Sent:** Thursday, April 28, 2022 8:49 AM

**To:** Bruehart, Alex J. <[abruehart@targaresources.com](mailto:abruehart@targaresources.com)>; Gibson, Raul <[rgibson@targaresources.com](mailto:rgibson@targaresources.com)>

**Cc:** Christopher Gurule <[Christopher\\_Gurule@eogresources.com](mailto:Christopher_Gurule@eogresources.com)>

**Subject:** [EXTERNAL] Measurement Equipment Removal

**CAUTION:** This email originated from outside of Targa. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good morning gentlemen, I wanted to see if we could get the following locations measurement equipment removed as soon as possible. The wells have been plugged and are scheduled for reclamation. So it's imperative that we remove the equipment in a timely manner. Thanks for your help any questions please reach out to me. 575-703-0497

Gato Loco BFT Com#1 33.57508,-103.49868

Strait BLN St Com #5 33.4305763,-103.4916382

Judson AUU St Com#2 33.4127235,-103.4325104

Abby BLF St #1 33.5426,-103.55593

Mcbride BEH ST #1 33.4775696,-103.4753876

Jerry Jeff BED St Com #1 33.4587364,-103.5072021

Merle BOJ ST COM#11 33.467083,-103.4281311

EOG RESOURCES ARTESIA DIVISION

[George\\_Flores@eogresources.com](mailto:George_Flores@eogresources.com)

Cell [575 703-0497](tel:5757030497)

---

This email (including any attachments and accompanying emails) may contain proprietary and confidential information. If you are not the intended recipient, please telephone the sender and immediately delete this e-mail (including any attachments and accompanying

emails). Please do not replicate, disclose, distribute, forward, or retain this e-mail or any part of this email. Thank you.



**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 230110

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230110
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	10/20/2023