

Well Name: PRESTON FEDERAL	Well Location: T20S / R24E / SEC 34 / NESE /	County or Parish/State: EDDY / NM
Well Number: 12	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM045276	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152907000X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2721875

Type of Submission: Subsequent Report	Type of Action: Reclamation
Date Sundry Submitted: 03/21/2023	Time Sundry Submitted: 10:03
Date Operation Actually Began: 03/07/2023	

**Actual Procedure:** P&A Reclamation and re-seeding was completed on 3/7/2023. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2024 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

PRESTON\_FEDERAL\_12\_CRR\_2023\_3\_20\_20230321100312.pdf

Received by OCD: 6/19/2023 11:14:35 AM

Page 2 of 6

Well Name: PRESTON FEDERAL	Well Location: T20S / R24E / SEC 34 / NESE /	County or Parish/State: EDDY / NM
Well Number: 12	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM045276	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152907000X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: MAR 21, 2023 10:03 AM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY	BLM POC Title: Legal Instruments Examiner
BLM POC Phone: 5752345931	BLM POC Email Address: dmckinne@blm.gov
Disposition: Accepted	Disposition Date: 06/16/2023
Signature: Deborah McKinney	



## Surface Reclamation Complete Report

**Well Name:** PRESTON FEDERAL #012

**API:** 30-015-29070

**Well Location:** I-34-20S-24E

**Surface Owner:** BLM

**Reclamation Complete Date:** 3/7/23

**Total Acres reclaimed:** 4.10 acres

**Seed Mix:**

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2024 to determine if successful vegetation regrowth is established.





On-Site Regulatory Reclamation Inspection							Date: 3 / 8 / 2023	
Site Name: Preston Federal #012								
API Number: 30-0 15 - 29070		Plug Date: 1 / 31 / 2022		Program: Initial		Monitoring		
				Final		Corrective		
Was this the last remaining or only well on the location?							YES	NO
Are there any abandoned pipelines that are going to remain on the location?							✓	
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?								✓
If any production equipment or structure (including 3rd party) is to remain on location, please specify.								
<b>Site Evaluation</b>								
Recontoured back to original State/Topsoil Replaced							YES	NO
Have the rat hole and cellar been filled and leveled?							✓	
Have the cathodic protection holes been properly abandoned & reclaimed?							✓	
Rock or Caliche Surfacing materials have been removed?							✓	
Section Comments:								
All Facilities Removed for Final Reclamation								
Have all of the pipelines & production equipment been cleared? (other than the listed above)							✓	
Has all of the required junk and trash been cleared from the location?							✓	
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?							✓	
Have all of the required metal bolts and other materials have been removed?							✓	
Have all the required portable bases been removed?							✓	
Section Comments:								
Dry Hole Marker							YES	NO
Has a steel marker been installed per COA requirements?							✓	
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground								
DHM Info	Operator Name	Lease Name & Number	UL-S-T-Rt	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)		
Met	✓	✓	✓	✓	✓	✓		
Not Met								
Free of Oil or Salt Contaminated Soil							YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							✓	
Have all other environmental concerns been addressed as per OCD rules?							✓	
If any environmental concerns remain on the location, please specify.								
<b>Abandoned Pipelines</b>								
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).							YES	NO
Have all fluids have been removed from any abandoned pipelines?								
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?								
Have all accessible points of abandoned pipelines been permanently capped?								
Section Comments:								
<b>Last Remaining or Only Well on the Location</b>								
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.							YES	NO
Have all electrical service poles and lines been removed from the location?							✓	
Is there any electrical utility distribution infrastructure that is remaining on the location?								✓
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?							✓	
Have all the retrievable pipelines, production equipment been removed from the location?							✓	
Has all the junk and trash been removed from the location?							✓	
Section Comments:								
<b>Environmental Only: Do not have to be met to pass inspection</b>								
This section corresponds with questions on the Reclamation Inspection Form in iEnvironmental but not related to NMOC forms.							Met	Not Met
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)							✓	
Site Stability? Erosion controls in place (if necessary) & working.							✓	
Signs of seedling completion? (Broadcast/Drilled)							✓	
Revegetation Success as compared to background? Met >75%. Circle One: 0% 25% 50% 75% 100%							✓	
Adequate Reclamation Fence Installed?							N	A
Section Comments:								
Additional Findings or Comments: Trash picked up.								
Inspector: Igor Rios								
Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/>							<input type="checkbox"/> READY FOR IAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW	
<input checked="" type="checkbox"/> Site Corners <input type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/>							<b>Inspection Result</b> <input checked="" type="radio"/> PASS <input type="radio"/> FAIL	

On-Site\_Inspection\_Form v1.xlsx

10/20/2022

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 230098

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230098
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	10/27/2023