

Well Name: GULF AGT FED	Well Location: T20S / R24E / SEC 6 / SENW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM39120	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152034400X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2701853

Type of Submission: Subsequent Report

Type of Action: Reclamation

Date Sundry Submitted: 11/08/2022

Time Sundry Submitted: 09:35

Date Operation Actually Began: 10/31/2022

Actual Procedure: P&A Reclamation and re-seeding was completed on 10/31/2022. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2023 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Received by OCD: 12/20/2023 2:06:12 PM

Page 2 of 7

Well Name: GULF AGT FED	Well Location: T20S / R24E / SEC 6 / SENW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM39120	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152034400X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: NOV 08, 2022 09:35 AM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: JAMES A AMOS	BLM POC Title: Acting Assistant Field Manager
BLM POC Phone: 5752345927	BLM POC Email Address: jamos@blm.gov
Disposition: Accepted	Disposition Date: 02/03/2023
Signature: James A. Amos	



Surface Reclamation Complete Report

Well Name: GULF AGT FEDERAL #001

API: 30-015-20344

Well Location: F-06-20S-24E

Surface Owner: BLM

Reclamation Complete Date: 10/31/22

Total Acres reclaimed: 1.25

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #1 (For Loamy Soils)	Plains lovegrass	1.0	2.0
"	Sand dropseed	2.0	4.0
"	Sideoats grama	10.0	20.0
"	Plains Bristlegrass	4.0	8.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

EOG will now have contractors install a reclamation fence instead of doing a Ditch Cut/Berm.



Pig launcher on east side of the road across from pad, not pad/location.





On-Site Regulatory Reclamation Inspection						Date: <u>11/01/2022</u>			
Site Name: <u>Gulf AGT Federal #001</u>									
API Number: <u>30-0 15 20344</u>		Plug Date: <u>03 / 14 / 2022</u>		Program: Initial		Monitoring Final Corrective			
Was this the last remaining or only well on the location?								YES	NO
Are there any abandoned pipelines that are going to remain on the location?								✓	✓
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?								✓	✓
If any production equipment or structure (including 3rd party) is to remain on location, please specify. _____									
Site Evaluation									
Recontoured back to original State/Topsoil Replaced								YES	NO
Have the rat hole and cellar been filled and leveled?								✓	✓
Have the cathodic protection holes been properly abandoned & reclaimed?								✓	✓
Rock or Caliche Surfacing materials have been removed?								✓	✓
Section Comments: _____									
All Facilities Removed for Final Reclamation									
Have all of the pipelines & production equipment been cleared? (other than the listed above)								✓	✓
Has all of the required junk and trash been cleared from the location?								✓	✓
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?								✓	✓
Have all of the required metal bolts and other materials have been removed?								✓	✓
Have all the required portable bases been removed?								✓	✓
Section Comments: _____									
Dry Hole Marker								YES	NO
Has a steel marker been installed per COA requirements?								✓	✓
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground									
DHM Info	Operator Name	Lease Name & Number	ULS-T-R	Qtr Section (Footage)	API #	Federal Lease # (Federal Only)			
Men	✓	✓	✓	✓	✓				
Not Met									
Free of Oil or Salt Contaminated Soil								YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?								✓	✓
Have all other environmental concerns been addressed as per OCD rules?								✓	✓
If any environmental concerns remain on the location, please specify. _____									
Abandoned Pipelines									
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMOC).								YES	NO
Have all fluids have been removed from any abandoned pipelines?								✓	✓
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?								✓	✓
Have all accessible points of abandoned pipelines been permanently capped?								✓	✓
Section Comments: _____									
Last Remaining or Only Well on the Location									
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.								YES	NO
Have all electrical service poles and lines been removed from the location?								✓	✓
Is there any electrical utility distribution infrastructure that is remaining on the location?								✓	✓
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?								✓	✓
Have all the retrievable pipelines, production equipment been removed from the location?								✓	✓
Has all the junk and trash been removed from the location?								✓	✓
Section Comments: _____									
Environmental Only- Do not have to be met to pass inspection									
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.								Met	Not Met
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)								✓	✓
Site Stability? Erosion controls in place (if necessary) & working.								✓	✓
Signs of seeding completion? (Broadcast/Drilled)								✓	✓
Revegetation Success as compared to background? Met >75% Circle One: 0% 25% 50% 75% 100%								✓	✓
Adequate Reclamation Fence Installed?								✓	✓
Section Comments: _____									
Additional Findings or Comments: <u>Pig launcher on east side of the road across road from pad, not on pad/location.</u>									
Inspector: <u>Igor Rios</u>									
Picture Checklist: <input checked="" type="checkbox"/> DWH <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> _____									
<input checked="" type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> _____									
<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW									
Inspection Result									
<input checked="" type="radio"/> PASS <input type="radio"/> FAIL									

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 296770

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 296770
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	12/21/2023