Received by OCD: 12/6/2023 12:55:19 PM

Form 3160-5 (June 2019) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			FORM APPROVED OMB No. 1004-0137 Expires: December 31, 2024 5. Lease Serial No. NMSF078766 6. If Indian, Allottee or Tribe Name			
			5.	7. If Unit of CA/Agreen	nent. Name and/or No.	
1. Type of Well	TRIPLICATE - Other instructions on pa	age 2		NMNM78407E		
Oil Well X Gas V	Well Other			8. Well Name and No. ROSA UNIT 614H		
2. Name of Operator				9. API Well No. 30-039-31433		
Bit Address 2010 A ETON PLACE		o (includo anos oo		30-039-31433 10. Field and Pool or Exploratory Area		
3a. Address 2010 AFTON PLACE FARMINGTON, NM 874		o. (include area coa 8-8720	(e)	BASIN MANCOS		
4. Location of Well (Footage, Sec., T.,)				11. Country or Parish, S		
SEC 23 T31N R06W NWSW (L)				RIO ARRIBA COU		
	ECK THE APPROPRIATE BOX(ES) TO I	NDICATE NATUR	E OF NOTI		^	
TYPE OF SUBMISSION			PE OF ACT			
	Acidize De	eepen		uction (Start/Resume)	Water Shut-Off	
Notice of Intent		draulic Fracturing		amation	Well Integrity	
x Subsequent Report		ew Construction	_	mplete	x Other Production	
Subsequent Report	Change Plans Plu	ug and Abandon	Temp	orarily Abandon		
Final Abandonment Notice	Convert to Injection Plu	ıg Back	Wate	r Disposal		
the Bond under which the work wi completion of the involved operation completed. Final Abandonment No ready for final inspection.) 11/14/2023 - Skid rig from Rosa U	ally or recomplete horizontally, give subsu ll be performed or provide the Bond No. or ons. If the operation results in a multiple co tices must be filed only after all requirement in t612H to Rosa Unit 614H. NU BOPE. I track, cmt, while displacing with OBM. C OH. Service rig.	n file with BLM/BI ompletion or recom ents, including recla FIH to 1,150', drill o	A. Required pletion in a mation, have out #1 & #2	subsequent reports must new interval, a Form 316 e been completed and the DVT plugs @ 3422' & 4	the filed within 30 days following 60-4 must be filed once testing has been e operator has determined that the site is 622. Test 9-5/8" csg to 1500psi/ 30min.	
11/15/2023 - PU 8.5" curve, lateral	assembly. TIH to 6185'. Condition & circ	ulate. Wash & ream	n f/6212' t/62	279'. Drill f/6279' t/8040'		
11/16 - 11/19/2023 - Continue to d	rill 8.5" lateral f/8,040' t/17,311' (TD). SO	OH. Laydown BHA	. RU casing	equipment. Run 5.5" cs	g to 6950'.	
685cf), 12.8ppg, 1.73 yield. Pump Bumped plug w/2500psi. Pressure	HCP-110 csg, 20.0#, landed @ 17,296', F 1925sx Tail Premium Class G 65/35 cmt (up to 3400psi. PT 5.5" csg 1570psi/30min p for rig move. Release Rig. RDMO.	545bbls, 3061cf) 13	8.2ppg, 1.59	yield. Drop top cmt plug		
14. I hereby certify that the foregoing is	s true and correct. Name (Printed/Typed)					
Etta Trujillo		Title Regulate	Title Regulatory Specialist			
Signature <i>Eta Trujillo</i> D		Date 12/4/2	Date 12/4/2023			
0	THE SPACE FOR FE	DERAL OR S	TATE OF	ICE USE		
Approved by		Title		Da	Ife	
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		ant or				
Title 18 U.S.C Section 1001 and Title 4	3 U.S.C Section 1212, make it a crime for	any person knowin	gly and will	fully to make to any departure	artment or agency of the United States	
any false, fictitious or fraudulent statem	ents or representations as to any matter wi	ithin its jurisdiction.				

GENERAL INSTRUCTIONS

•

eceived by UCD: D2/6/2023 12:55:19 PM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Repor
Well Name: ROSA UNIT	Well Location: T31N / R6W / SEC 23 / NWSW / 36.882844 / -107.439701	County or Parish/State: RIO ARRIBA / NM
Well Number: 614H	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF78766	Unit or CA Name: ROSA UNIT	Unit or CA Number: NMNM78407E
US Well Number: 3003931433	Well Status:	Operator: LOGOS OPERATING LLC

Subsequent Report

Sundry ID: 2764805

Type of Submission: Subsequent Report

Date Sundry Submitted: 12/06/2023

Date Operation Actually Began: 11/14/2023

Type of Action: Drilling Operations Time Sundry Submitted: 10:59

Actual Procedure: 11/14/2023 - Skid rig from Rosa Unit 612H to Rosa Unit 614H. NU BOPE. TIH to 1,150', drill out #1 & #2 DVT plugs @ 3422' & 4622. Test 9-5/8" csg to 1500psi/ 30min. TIH to 6135'. Drill out 9-5/8" shoe track, cmt, while displacing with OBM. Clean out old hole below casing shoe and drill f/6245' t/6279'. TOOH. TIH with 8.5" f/6269' - t/6279'. Condition & circulate. TOOH. Service rig. 11/15/2023 - PU 8.5" curve, lateral assembly. TIH to 6185'. Condition & circulate. TOOH. Service rig. 11/15/2023 - PU 8.5" curve, lateral assembly. TIH to 6185'. Condition & circulate. Wash & ream f/6212' t/6279'. Drill f/6279' t/8040'. 11/16 - 11/19/2023 - Continue to drill 8.5" lateral f/8,040' t/17,311' (TD). SOOH. Laydown BHA. RU casing equipment. Run 5.5" csg to 6950'. 11/20/2023 - RIH w/388jts, 5.5" HCP-110 csg, 20.0#, landed @ 17,296', FC @ 17,202'. Circulate. Mix & pump 396sx Lead Premium Class G 65/35 cmt (122bbls, 685cf), 12.8ppg, 1.73 yield. Pump 1925sx Tail Premium Class G 65/35 cmt (545bbls, 3061cf) 13.2ppg, 1.59yield. Drop top cmt plug, displaced w/381bbls FW. Circulate. Bumped plug w/2500psi. Pressure up to 3400psi. PT 5.5" csg 1570psi/30mins. RD cmt crew. Install pack-off and BPV. 11/21 - 11/25/2023 - ND BOP. Prep for rig move. Release Rig. RDMO.

SR Attachments

PActual Procedure

3160_5_Rosa_Unit_614H_Production_Subsequent_Report_20231125_20231206105834.pdf

Received by OCD: 12/6/2023 12:55:19 PM Well Name: ROSA UNIT	Well Location: T31N / R6W / SEC 23 / NWSW / 36.882844 / -107.439701	County or Parish/State: RID ^{age 3} of 4 ARRIBA / NM
Well Number: 614H	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMSF78766	Unit or CA Name: ROSA UNIT	Unit or CA Number: NMNM78407E
US Well Number: 3003931433	Well Status:	Operator: LOGOS OPERATING LLC

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: ETTA TRUJILLO

Name: LOGOS OPERATING LLC

Title: Regulatory Specialist

Street Address: 2010 AFTON PLACE

City: Farmington

State: NM

Phone: (505) 324-4154

Email address: ETRUJILLO@LOGOSRESOURCESLLC.COM

Field

Representative Name: Street Address: City: State: Phone: Email address:

BLM Point of Contact

BLM POC Name: MATTHEW H KADE BLM POC Phone: 5055647736 Disposition: Accepted Signature: Matthew Kade BLM POC Title: Petroleum Engineer BLM POC Email Address: MKADE@BLM.GOV

Zip:

Signed on: DEC 06, 2023 10:59 AM

Disposition Date: 12/06/2023

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
LOGOS OPERATING, LLC	289408
2010 Afton Place	Action Number:
Farmington, NM 87401	291819
	Action Type:
	[C-103] Sub. Drilling (C-103N)

CONDITIONS		
Created By	Condition	Condition Date
kelly.roberts	Report top of cement for production casing next sundry. For casing pressure tests, report test result on future submittals. All pressure test reports must contain amount of pressure applied, test duration, and test results.	2/13/2024

Page 4 of 4