

# U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: LENTIL FEDERAL Well Location: T26S / R25E / SEC 19 / County or Parish/State: EDDY /

NWSW / 32.0262034 / -104.4418939

Well Number: 161 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMNM113929 Unit or CA Name: Unit or CA Number:

**US Well Number:** 3001546514 **Well Status:** Temporarily Abandoned **Operator:** TAP ROCK

OPERATING LLC

# **Subsequent Report**

**Sundry ID: 2754279** 

Type of Submission: Subsequent Report

Type of Action: Temporary Abandonment

Date Sundry Submitted: 10/01/2023 Time Sundry Submitted: 09:50

**Date Operation Actually Began:** 09/21/2023

**Actual Procedure:** Tap Rock performed an MIT for the referenced well September 21, 2023 and requests to extend the TA an additional year. See attached MIT chart.

## **SR Attachments**

#### **Actual Procedure**

20230922\_135512\_20230926073617\_20231001095019.PDF

# **SR Conditions of Approval**

### **Specialist Review**

TA\_COA\_20231013200103.pdf

Page 1 of 2

eceived by OCD: 10/16/2023 7:53:58 AM
Well Name: LENTIL FEDERAL

Well Location: T26S / R25E / SEC 19 /

NWSW / 32.0262034 / -104.4418939

Type of Well: CONVENTIONAL GAS **Allottee or Tribe Name:** 

NM

Zip:

County or Parish/State: EDD 1/2

**Unit or CA Name:** 

**Unit or CA Number:** 

**US Well Number: 3001546514** 

Lease Number: NMNM113929

Well Number: 161

Well Status: Temporarily Abandoned

**Operator: TAP ROCK OPERATING LLC** 

# **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Signed on: OCT 01, 2023 09:50 AM **Operator Electronic Signature: JEFFREY TRLICA** 

Name: TAP ROCK OPERATING LLC

Title: Regulatory Analyst

Street Address: 523 PARK POINT DRIVE SUITE 200

City: GOLDEN State: CO

Phone: (720) 772-5910

Email address: JTRLICA@TAPRK.COM

## **Field**

**Representative Name:** 

**Street Address:** 

City: State:

Phone:

**Email address:** 

## **BLM Point of Contact**

**BLM POC Name: JONATHON W SHEPARD BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5752345972 BLM POC Email Address: jshepard@blm.gov

**Disposition:** Approved Disposition Date: 10/13/2023

Signature: Jonathon Shepard

Page 2 of 2


#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972


# **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-689-5981.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.



## Post TA – Well Bore Diagram



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 275821

#### **CONDITIONS**

Operator:	OGRID:
TAP ROCK OPERATING, LLC	372043
523 Park Point Drive	Action Number:
Golden, CO 80401	275821
	Action Type:
	[C-103] Sub. Temporary Abandonment (C-103U)

#### CONDITIONS

Created By		Condition Date
gcordero	None	3/21/2024