

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Gand O Service		API Number 30-015-02545	
Property Name Artesia Unit		Well No. 47	

1. Surface Location									
UL - Lot 6	Section 3	Township 18	Range 28	Feet from 1980	N/S Line N	Feet from 1980	E/W Line W	County Eddy	

Well Status										
TA'D WELL YES	NO	YES	SHUT-IN NO	TN	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7-27-22

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	No Pressure				
Flow Characteristics				16 pressure	
Puff	Y / N	Y / N	Y / N	Y / N	CO2 WTR GAS Type of Fluid Injected for Waterhead if applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test used

Signature: Dan Smolik		OIL CONSERVATION DIVISION	
Printed name: Dan Smolik		Entered into RBDMS	
Title: Compliance Officer		Re-test	
E-mail Address:			
Date: 7-27-22	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 142569

CONDITIONS

Operator: G and C Operating, LLC P.O. Box 1618 Artesia, NM 88211	OGRID: 265378
	Action Number: 142569
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/5/2024