

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Oilfield Water Logistics</i>		API Number <i>30-025-37799</i>
Property Name <i>Lotus SWP</i>		Well No. <i>#012</i>

UL - Lat <i>B</i>	Section <i>32</i>	Township <i>22 S</i>	Range <i>32 E</i>	Feet from	N/S Line	Feet From	E/W Line	County <i>Lea</i>
----------------------	----------------------	-------------------------	----------------------	-----------	----------	-----------	----------	----------------------

Well Status		DATE <i>07-19-23</i>	
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐

OBSERVED DATA

	(A) Surface	(B) Interim 1	(C) Interim 2	(D) Prod Case	(E) Tubing
Pressure	<i>0</i>			<i>0</i>	<i>1250</i>
Flow Characteristics					
Full	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	CO2 ☐
Steady Flow	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	WTR ☒
Surges	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	GAS ☐
Down to nothing	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Type of Fluid
Gas or Oil	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Injected for
Water	Y/N ☒	Y/N ☐	Y/N ☐	Y/N ☒	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Failed
BHT - Well shut in due to over pressure.
Tbg had 1250 # w/ max pres of 1150 #.
Well is to be shut in ASAP.
Failed BHT.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness: <i>Shay Roberts</i>		

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 253146

CONDITIONS

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 253146
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	9/30/2024