



NEW MEXICO CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE
 401 RIO BRADLEY ROAD
 AZTEC NM 87410
 (505) 334-6176 FAX (505) 334-6170
 9700 Tampabay State Commission District Office

BRADENHEAD TEST REPORT

(Name of Property and Address)

Date of Test 9-10-2024 Operator Wagon API # 30-007-20653

Property Name Urr B Well No. 106 Location: Unit E Section 19 Township 30 Range 18

Well Status Shut-In (or Producing) Initial PSI: Tubing 90 Intermediate NA Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0		6		
10 min	0		7		
15 min	0		8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Braden head nothing Nothing after 5 minutes

By Chavez, Leticia

Witness _____

Operator
(Position)

E-mail address _____

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 386460

CONDITIONS

Operator: Wapiti Operating, LLC 1251 Lumpkin Rd Houston, TX 77043	OGRID: 328741
	Action Number: 386460
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
smcfall	None	10/21/2024