

American Valve & Meter, Inc.

1113 W. BROADWAY
P.O. BOX 166 HOBBS,
NM 88240

DATE: 4/27/23

T0:McNabb

This is to certify that:


I, Justin Harris, Technician for American Valve & Meter Inc. Has checked
the calibration of the following instrument. At these points.

Ser#9117

08" Pressure recorder

Pressure #			Temperature *or Pressure #		
Test	Found	Left	Test	Found	Left
- 0	-	- 0	-	-	-
- 500	-	- 500	-	-	-
- 700	-	- 700	-	-	-
- 1000	-	- 1000	-	-	-
- 200	-	- 200	-	-	-
- 0	-	- 0			

Remarks: _____

Signature: 

D000000X

South District-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Mewbourne	API Number 30-025-30570
Property Name QPBSSU 12B	Well No. 003

1. Surface Location

UL - Lot 5	Section 14	Township 18S	Range 32E	Feet from	N/S Line	Feet From	E/W Line	County Lea
----------------------	----------------------	------------------------	---------------------	-----------	----------	-----------	----------	----------------------

Well Status

TA'D WELL YES	☒ NO	☒ YES	SHUT-IN NO	☒ INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 8-15-2023
------------------	-------------------------------------	--------------------------------------	---------------	--------------------------------------	-----------------	-----	-----------------	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	☒ Y ☐ N	Y / N	Y / N	☒ Y ☐ N	CO2 WTR ☒ GAS ☐ Type of Fluid Injected for Waterflood if applies
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	☒ Y ☐ N	Y / N	Y / N	☒ Y ☐ N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	☒ Y ☐ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

When filling production casing with centrifugal pump
started communicating with surface casing
did not chart
! FAILED!

Signature: Mike Gilbert		OIL CONSERVATION DIVISION	
Printed name: Mike Gilbert		Entered into RBDMS	
Title: Pumptruck Operator		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 258131

CONDITIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 258131
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Repair well	11/12/2024