

District I
1625 N French Dr., Hobbs, NM 88240
Phone: (505) 395-6161 Fax: (505) 395-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBER ENERGY, LLC	API Number 30-025-24122
Property Name NORTH VACUUM ABO EAST UNIT	Well No 4

Surface Location

Oil - Lot P	Section 7	Township 17S	Range 35E	Feet from 460	NS Line FSL	Feet From 660	E/W Line FEL	County LEA
-----------------------	---------------------	------------------------	---------------------	-------------------------	-----------------------	-------------------------	------------------------	----------------------

Well Status

TA/B WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD	OIL	PRODUCER	GAS	DATE 8-1-2024
-------------------------	-----------	-----------------------	-----------	-----------------------	-----	-----	----------	-----	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Csg	(E) Tubing
Pressure	0			30	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Exposed for Waterhead/H spills
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well Down

Packer leak - Fail

Well is to be
shut in ASAP

JK

Printed name <i>Gore Lin</i>		OIL CONSERVATION DIVISION	
Title		Entered into RBDMS	
E-mail Address		Re-test	
Date 8-1-2024	Phone		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 382296

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 382296
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Repair well	11/14/2024