

EG2200X
South District-Atenas

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division ~~Alamosa~~ District Office

BRADENHEAD TEST REPORT

| | |
|---|-----------------------------------|
| Operator Name KP KAUFFMAN COMPANY INC | API Number 30-015-05691 |
| Property Name EAST SHUGART | Well No. #024 |

Surface Location

| | | | | | | | | |
|----------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|--------------------------|----------------------|-----------------------|
| UL - Lot N | Section 35 | Township 18S | Range 31E | Feet from 990 | N/S Line S | Feet From 1650 | E/W Line W | County EDDY |
|----------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|--------------------------|----------------------|-----------------------|

Well Status

| | | | | | | | |
|--|--|---|---|---|--|---|---------------------------|
| TA'D WELL YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> | SHUT-IN NO <input type="checkbox"/> YES <input checked="" type="checkbox"/> | INJECTOR NO <input type="checkbox"/> YES <input checked="" type="checkbox"/> | SWD NO <input type="checkbox"/> YES <input type="checkbox"/> | OIL NO <input type="checkbox"/> YES <input type="checkbox"/> | PRODUCER NO <input type="checkbox"/> YES <input type="checkbox"/> | GAS NO <input type="checkbox"/> YES <input type="checkbox"/> | DATE 11/26/2024 |
|--|--|---|---|---|--|---|---------------------------|

OBSERVED DATA

| | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Csg | (E)Tubing |
|----------------------|---|--------------|--------------|---|---|
| Pressure | 0 | / | / | 0 | 1100 |
| Flow Characteristics | | | | | |
| Puff | <input checked="" type="checkbox"/> N | Y / N | Y / N | Y / <input checked="" type="checkbox"/> | CO2 |
| Steady Flow | Y / <input checked="" type="checkbox"/> | Y / N | Y / N | Y / <input checked="" type="checkbox"/> | WTR <input checked="" type="checkbox"/> |
| Surges | Y / <input checked="" type="checkbox"/> | Y / N | Y / N | Y / <input checked="" type="checkbox"/> | GAS |
| Down to nothing | <input checked="" type="checkbox"/> N | Y / N | Y / N | <input checked="" type="checkbox"/> N | Type of fluid Injected for Waterflood if applies |
| Gas or Oil | Y / <input checked="" type="checkbox"/> | Y / N | Y / N | Y / <input checked="" type="checkbox"/> | |
| Water | Y / <input checked="" type="checkbox"/> | Y / N | Y / N | Y / <input checked="" type="checkbox"/> | |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT OK
PRODUCTION SLIGHT FLUID DISCHARGE

| | |
|-----------------|---------------------------|
| Signature: | OIL CONSERVATION DIVISION |
| Printed name: | Entered into RBDMS |
| Title: | Re-test |
| E-mail Address: | |
| Date: | Phone: |
| Witness: | <i>[Signature]</i> |

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 408238

CONDITIONS

| | |
|--|--|
| Operator: K P KAUFFMAN COMPANY INC 1700 Lincoln Street Denver, CO 80203 | OGRID: 228296 |
| | Action Number: 408238 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner | None | 12/9/2024 |