

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0320

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-20179	
Property Name VACUUM GLORIETA WEST UNIT		Well No 086	

1. Surface Location									
UL - Lot K	Section 36	Township 17S	Range 34E		Feet from 2310	N/S Line FSL	Feet From 2310	E/W Line FWL	County LEA

Well Status										
YES	TA'D WELL ☒ NO	YES	SHUT-IN ☒ NO	INJ	INJECTOR	SWD	☒ OIL	PRODUCER	GAS	DATE 7-31-2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	35	200
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	WTR
Surges	Y / ☒ N	Y / N	Y / N	Y / N	GAS
Down to nothing	☒ Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 		OIL CONSERVATION DIVISION	
Printed name: Jesus Romero		Entered into RBDMS	
Title: Field Specialist		Re-test	
E-mail Address: JRomero@OilCons.org			
Date: 7-31-2024	Phone: 682-352-4714		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 388490

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 388490
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024