

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 395-6161 Fax (575) 395-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-27194
Property Name CENTRAL VACUUM UNIT		Well No 153

1. Surface Location									
Bl. - Lot L	Section 6	Township 18S	Range 35E		Feet from 2196	N/S Line FSL	Feet From 525	E/W Line FWL	County LEA

Well Status												
YES	TA'D WELL	☒ NO	YES	SHUT-IN	☒ NO	INJ	INJECTOR	SWD	☒ OIL	PRODUCER	GAS	DATE 2/6/25

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	0	120	310
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Indicated for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Richard Paul</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test
Printed name Richard Paul	
Title Lease Operator	
E-mail Address paulr@centralvac.com	
Date 2/6/25	
Phone 817-739-5643	
Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 442262

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 442262
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	6/16/2025