

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 399-6161 Fax: (575) 399-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC	API Number 30-025-33599
Property Name WEST VACUUM UNIT	Well No 57

Surface Location									
UL - Lot P	Section 34	Township 17S	Range 34E		Feet from 75	N/S Line FSL	Feet From 1305	E/W Line FEL	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO
									DATE 2-11-2025

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod Casing	(E) Tubing
PRESSURE	0			0	1100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 	OIL CONSERVATION DIVISION
Printed name: Eloy Carmona	Entered into RBDMS
Title: FSH	Re-test
E-mail Address: Eduillen@cfhfields.com	
Date: 2-11-2025	Phone: 682-478-6731
Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 442364

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 442364
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	6/17/2025