District.) 1625 N French Dr., Hobbs, NM 88240 Phone (575):393-6161 Fax. (975):393-0-20

### State of New Mexico

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADE	HEAD TES	T REPORT				
MORNINGSTAR OPERATING, LLC			30-0	30-025-38002 Well No		
Property Name CENTRAL VACUUM UNIT				342	II NO	
* Surface Location						
UtLot Section Township Range 34E	Feet from 82	N/S Line FNL	Feet From 1186	FEL FEL	LEA	
	Well Status					
YES TA'D WELL NO YES SHUT-IN NO (IN	INJECTOR	SWD OIL	PRODUCER GA	is 2-	DATE -3-2025	

### OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	$\theta$		0	1530
Flow Characteristics				15 ((4)	CO2
Puff	VIN	Y (1)	AIN	¥ ! (19	WTR _
Steady Flow	Y I (N)	YIN	V/N	1 / (N)	GAS _
Surges	Y / (N)	YIN	YW	W N	Type of Field Inferred for
Down to nothing	N I(R)	(W/ N	Y/W	Y/N	Waterfixed if
Gas or Oil	Y I (N)	VICK	Y/N	VIN	-1"
Water	V I (N)	Y (N	Y Y Y	V ···	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

	and the second s
CONTRACTOR	
Signature	OIL CONSERVATION DIVISION
The state of the s	Entered into RBDMS
Printed name //oy Carmone	Re-test
Engladdens Ehrillan a Ct Field SVCS COM	
Date: 2-3-2025 Phone (55)-478-10731	
Wintess	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 442313

### **CONDITIONS**

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	442313
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

### CONDITIONS

Created By		Condition Date
blydick	None	6/17/2025