

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/17-1015 Operator BMG API #30-039-06816				
Property Name <u>FRCOU</u> Well No. <u>16</u> Location: Unit <u>C</u> Section <u>Z8</u> Township <u>Z7</u> Range <u>1-8</u>				
Well Status(Shut-In or Producing) Initial PSI: Tubing \( \begin{align*} \begin{align*} \text{Entermediate} \) Casing \( \begin{align*} \begin{align*} \text{Bradenhead} \( \begin{align*} \begin{align*} \begin{align*} \text{Entermediate} \end{align*} \) Bradenhead \( \begin{align*} ali				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE FLOW CHARACTERISTICS  Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE  BH Int Csg Int Csg				
TIME 0 0 Steady Flow				
10 min 0				
15 min O O Down to Nothing				
20 min Nothing				
25 min Gas				
30 min Gas & Water				
Water  If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD U INTERMEDIATE				
REMARKS:				
Position Witness Witness				
(Position)				
E-mail address				

Released to Imaging: 7/3/2025 8:09:20 AM

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 475546

## **CONDITIONS**

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	475546
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

## CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/3/2025