

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

	(Submit I copy to above	, accuracy
Date of Test /-/2-2015	Operator RMG	API #30-0_39-23 209
Property Name EPCMU 6-8	Well No. 37 Location	: Unit <u>C_</u> Section_ <u>&</u> Township <u>ZCv</u> Range <u> E</u>
Well Status(Shut-In or Producing) I	Initial PSI: Tubing 70 Inte	ermediate Casing 24 Bradenhead 0
OPEN BRADENHEAD AND INTE	ERMEDIATE TO ATMOSPH	ERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE	TERM	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min P 24		
10 min 0 24		
15 min 0 24	Down to Not	thing
20 min_	Nothing	/
25 min	Gas	
30 min_	Gas & Water	r
	Water	
If bradenhead flowed water, check all o	of the descriptions that apply be	low:
CLEAR FRESH	SALTYSULFUR	BLACK
5 MINUTE SHUT-IN PRESSURE	BRADENHEAD O	INTERMEDIATE
REMARKS:		
. 1		
By Jun Medion	Witness	
By Jun Mediano lease operator (Position)	_	
E-mail address		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 475551

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	475551
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/3/2025