

# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test $5 - \lambda 3 - \lambda 0 \lambda 5$ Operat	or BMG API#30-039-23807
Property Name Beck Bubbit Well No. #	Location: Unit G Section 7 Township KN Range W
Well Status(Shut-In or Producing) Initial PSI: 7	Tubing 34 Intermediate Casing 3\ Bradenhead 0
OPEN BRADENHEAD AND INTERMEDIATE	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 3	Steady Flow
10 min 3	Surges
15 min 0 3\	Down to Nothing
20 min	Nothing V
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the description	ions that apply below:
CLEAR FRESH SALTY	SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENH	IEAD INTERMEDIATE
REMARKS: NO PICSSUR STORY >	ero entire Duration oftest
By Johnstran Alexandra	Witness
(Position)	
E-mail address	
L-man address	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 467517

### **CONDITIONS**

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	467517
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

## CONDITIONS

Created By		Condition Date
tvermersch	None	7/3/2025