

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test $\frac{5}{\lambda}$ $\frac{1}{\lambda}$ Operator $\frac{8}{8}$ $\frac{1}{\lambda}$ API #30-0 $\frac{39}{\lambda}$ - $\frac{1}{\lambda}$				
Property Name High abbenture Well No. # \ Location: Unit \ Section \ Township 25 N Range \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate Casing Bradenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE BH Int Csg Int Csg				
TIME 5 min Steady Flow				
10 min Surges				
15 min O 36 Down to Nothing				
20 min Nothing				
25 min Gas				
30 min Gas & Water				
Water				
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE				
REMARKS: Brodenhood Had NO pressure at all Stayed at O For				
entire Nurstian OF test				
TVO THE DAMES AND ASSESSMENT OF THE PROPERTY O				
By Johnathan Shelby Witness				
(Position)				
E-mail address				

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 469836

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	469836
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
tvermersch	None	7/3/2025