

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX: (505)334-6170

[http://emrmd.state.nm.us/ocd/District III/3district.htm](http://emrmd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 5/12/25 Operator Dugan Production Corp API # 30-043-05168
Property Name KEESEEE Margurite Well No 4 Location: Unit A Section 33 Township 23N Range 03W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURE						FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 minutes	<u>0</u>		<u>30</u>			Steady Flow		
10 minutes	<u>0</u>		<u>30</u>			Surges		
15 minutes	<u>0</u>		<u>30</u>			Down to Nothing		
20 minutes	<u>0</u>		<u>30</u>			Nothing	<u>X</u>	
25 minutes	<u>0</u>		<u>30</u>			Gas		
30 minutes	<u>0</u>		<u>30</u>			Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By 
Switcher
(Position)

Witness _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464893

CONDITIONS

Operator: H K KEESEE AND C J KEESEE TRUST P.O. Box 420 Farmington, NM 87499	OGRID: 9667
	Action Number: 464893
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/3/2025