

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 5/12/25 Operator Dugan Production Corp API # 30-043-20018
Property Name KEESEEE Cinco Diablos Well No 11 Location: Unit P Section 19 Township 23N Range 03W
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 40 Bradenhead 5.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	.1		40			Steady Flow	
10 minutes	.2		40			Surges	
15 minutes	.2		40			Down to Nothing	X
20 minutes	.1		40			Nothing	
25 minutes	.2		40			Gas	
30 minutes	.2		40			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD .2 INTERMEDIATE _____

REMARKS:

By Luhe Duh
Switcher
(Position)

Witness _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 464889

CONDITIONS

Operator: H K KEESEE AND C J KEESEE TRUST P.O. Box 420 Farmington, NM 87499	OGRID: 9667
	Action Number: 464889
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/3/2025