State Of New Mexico **Energy, Minerals and Natural Resources Department**

14-Jul-25

LOGOS OPERATING, LLC

Pre Enforcement Notification

2010 Afton Place Farmington, NM 87401

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-045-35847] HEROS 2308 09L COM #004H

OGRID: 289408

L-09-23N-08W 1476 FSL 300 FWL

Inspection Date Type Inspection Routine Inspection 7/14/2025 **Violation** Title

Inspector [TV] Thomas Vermersch **Corrective Action Due**

Inspection No. iTV2519550633

cTV2519560115 19.15.16.8 Sign on Wells Illegible or Unreadable

10/12/2025

(The well nam on sign is coming off and is not legible. Please have sign fixed.)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.