



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/6/25 Operator Jacco DBA Black Hawk API #30-0 39-26864
Property Name Jicari/29-2-8 Well No. 4 Location: Unit D Section 8 Township 29N Range 02W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0		10		
10 min	0		10		
15 min	0		10		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: blew Bradenhead no gas, no vapor,
no H₂S

By BH DJM

Witness _____

(Position)

E-mail address oie.services4@gmail.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 486103

CONDITIONS

Operator: JICARILLA ENERGY CO P.O. 1048 Farmington, NM 87401	OGRID: 11859
	Action Number: 486103
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/30/2025