



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/5/25 Operator Jacob DBA Blackhawk API #30-0 39-29480

Property Name Jicarilla 29-02-17 Well No. 24 Location: Unit Section 17 Township 29N Range 02W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

Open braden head no gas
no vapor. no H₂S

By BH DM

Witness

(Position)

E-mail address oieservicesH@gmail.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 487516

CONDITIONS

Operator: JICARILLA ENERGY CO P.O. 1048 Farmington, NM 87401	OGRID: 11859
	Action Number: 487516
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/30/2025