



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/9/25 Operator Jacobs DBA Black Hawk API #30-0 39-30079
Property Name Jicarilla 29-02-04 Well No. 143 Location: Unit Section 4 Township 29N Range 2W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>0</u>		<u>0</u>			
10 min	<u>0</u>		<u>0</u>			
15 min	<u>0</u>		<u>0</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	<input checked="" type="checkbox"/>	
Nothing	<input checked="" type="checkbox"/>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: blew down bradenhead, gas
no vapor no H²S

By BT DM

Witness

(Position)

E-mail address oieservices14@gmail.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 486091

CONDITIONS

Operator: JICARILLA ENERGY CO P.O. 1048 Farmington, NM 87401	OGRID: 11859
	Action Number: 486091
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	7/30/2025