

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corporation		API Number 30-025-116530
Property Name East Blinberry Tankard Unit		Well No. 24

1. Surface Location									
UL - Lot 9	Section 11	Township 21S	Range 37E		Feet from 2310	N/S Line S	Feet From 1650	E/W Line E	County Lea



Well Status									
TA'D WELL YES ☐ NO ☒		SHUT-IN YES ☐ NO ☒		INJ INJECTOR YES ☐ NO ☒		PRODUCER OIL ☐ GAS ☒		DATE 12/16/2024	

Water Source Well
OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid _____
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for _____
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if _____

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Convert from injection well to Water Supply well /
BHT-OK
Csg integrity Only

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: 			

RECEIVED
Apache Corp

INSTRUCTIONS ON BACK OF THIS FORM

DEC 1 2024

Permian-Midland
Regulatory

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 420183

CONDITIONS

Operator: APACHE CORPORATION 303 Veterans Airpark Ln Midland, TX 79705	OGRID: 873
	Action Number: 420183
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
ronald.heuer	None	8/1/2025